South Dakota Spill Report Form
ATP Site

Spill Case Number	2025.146		
Reported: (mm/dd/yy) 10/03/25	Time: 3:30pm	Recorded By: Justin Allen	

A. REPORTER

Reported By: Robert Prann			
Organization Name: American Engineering Testing, Inc			
Organization: ☐ discharger ☐ public ☐ state ☐ local ☐ federal			
Address: 1745 Samco Road			
City: Rapid City	County: Pennington	State: SD	
Zip: 57702	Phone: 605-388-0029		

B. DISCHARGER (Responsible Party)

Name: SD DOT			
Address: 700 E Broadway Ave			
City: Pierre	County: Hughes	State: SD	
Zip: 57501	Phone: 605-773-4114		

C. INCIDENT LOCATION

Street or Approx. Location: As above in B ☐			LAT. 43.76110	
Custer DOT Shop, 115 Centennial Dr			LONG. -103.60998	
Survey Description:			Sec.	T / R
City: Custer	Zip: 57730	County: Custer	State: SD	

D. DATE

Spill Date: (mm/dd/yy) 06/09/25	Spill Time:

E. MATERIAL

Material Type (Code/Name): ☐ hazardous substance ☐ oil ☐ material unknown ☐ other	Quantity Spilled	Spilled in Water	Units (Check 1)
Gasoline & Diesel			○ lb. ○ bbl. ○ gal. ○ oth.
			○ lb. ○ bbl. ○ gal. ○ oth.
			○ lb. ○ bbl. ○ gal. ○ oth.

F. SOURCE

Source of Spill: ☐ AST ☑ UST ☐ railway ☐ fixed facility ☐ pipeline ☐ highway ☐ other	
Description: Regulated Tank: ☑	One - 2,000 gal diesel UST and One - 2,000 gal gasoline UST

G. MED.

Medium Affected: ☐ air ☑ land ☐ water ☐ groundwater ☐ within facilities only	
Waterway Affected:	

H. CAUSE

Reported Cause: ○ transportation accident ○ operational error ○ dumping ○ equipment failure ○ natural phenomenon ○ unknown ○ Other:	
Description: leaky UST system	

I. DAM.

Damages: No. of injuries: No. of deaths: Property Damage > $50,000 ☐	

J. ACTIONS

Date of Tank Removal: 06/09/25	Removed Two - 2,000 gal USTs
ATP # 3795 PRCF # 8662	

K. NOTIFIED

Responding Agency: ☑ DANR ☐ Local ☐ discharger ☐ federal ☐ EPA ☐ Other	
Agencies Notified:	

L. COMMENTS

Comments:	No contaminated soils removed.
Sample Results:	Tank basin soil samples @ 9 ft below grade had petroleum concentration below detectable limits. Sample below removed diesel dispenser had a TPH-D concentration of 41.5 ppm.

Department of Agriculture and Natural Resources
Insepction, Compliance, and Remediation Program
523 East Capitol Avenue
Pierre, South Dakota 57501

Business Hours M thru F 8:00 - 5:00 pm
Normal business hours - (605) 773-3296
After business hours - (605) 773-3231

DEPARTMENT of AGRICULTURE and NATURAL RESOURCES
JOE FOSS BUILDING
523 E CAPITOL AVE
PIERRE SD 57501-3182
danr.sd.gov

November 24, 2025

Chris Ott
SD DOT
700 E Broadway Ave
Pierre, SD 57501

Re: Closure of Department of Agriculture and Natural Resources File # 2025.146 pertaining to the removal of two 2000-gallon gasoline & diesel tanks at the Custer DOT Shop (ATP FID #3795), 115 Centennial Dr, Custer, Custer County, South Dakota

Dear Mr. Ott,

The Department of Agriculture and Natural Resources (DANR) has reviewed the case file for your site. As a result of this review, the DANR has determined work at this site can end, and the file can be closed. Petroleum hydrocarbon concentrations were detected while removing the tank system, but concentrations did not exceed DANR Tier I Action/Trigger Levels; therefore, DANR will not perform any further testing or remediation associated with the tank system removed on June 9, 2025.

As you know, the tanks were removed from this site as part of South Dakota's Abandoned Tank Program. If problems arise from contamination associated with the tanks that may not have been detected, please contact us so that further action may be taken. Should you have any questions or concerns, please contact Justin Allen of my staff. Thank you for your cooperation in protecting the groundwater resources of South Dakota.

Sincerely,

Terry Florentz, P.E.
Inspection, Compliance, & Remediation Program
Phone: (605) 773-3296

cc: Dustin Willett, Pennington County Emergency Manager, Rapid City, SD
John McVey, Petroleum Release Compensation Fund – PRCF #8662
Robert Prann, American Engineering Testing, Inc., Rapid City, SD