South Dakota Spill Report Form

PRCF #: **Case #:** 2026.104

Reported (MM/DD/YY): 7/14/26	Time:	Recorded By: HK

A. REPORTER

Reported By: Josh/Fred			
Organization Name: Rapid City HAZMAT/Butte Cty EM		☐ Discharger ☐ Public ☑ State ☑ Local ☐ Federal	
Phone:	Email:		
Address:			
City:	State:	Zip:	

B. DISCHARGER (Responsible Party) ☐ As Above in A

Name: IDC Transport, Inc			
Address: 3000 Dundee Rd Unit 213			
City: Northbrook	State: IL	Zip: 60062	
Phone:	Email:		

C. INCIDENT DATE & LOCATION ☐ As Above In B

Spill Date: (MM/DD/YY) 7/14/26	Spill Time:		
Street or Approx. Location: Hilderbrand Creek Culvert on Highway 85			
Survey Description: 44.901387, -103.712594			
City: Arpan	County: Butte	State: SD	Zip:

D. MATERIAL

Material type (Code/Name): ☐ Hazardous Substance ☐ Material Unknown ☑ Oil ☑ Other	Quantity Spilled	Spilled in Water	Units (Check one)
Diesel	unk	n/a	☐ lb. ☐ bbl. ☑ gal. ☐ oth.
Beer	unk	n/a	☐ lb. ☐ bbl. ☑ gal. ☐ oth.
			☐ lb. ☐ bbl. ☐ gal. ☐ oth.

E. SOURCE

Source of Spill: ☐ AST ☐ UST ☐ Railway ☑ Transport ☐ Fixed Facility ☐ Pipeline ☐ Highway ☐ Other

Description: Both saddle tanks on semi

Regulated Tank Facility: ☐ Tank Facility ID #:

F. MEDIUM

Medium Affected: ☐ Air ☑ Land ☐ Water ☐ Groundwater ☐ Within Facilities Only

Waterway Affected: dry creek bed

G. CAUSE

Reported Cause: ☑ Transportation Accident ☐ Operational Error ☐ Dumping ☐ Equipment Failure ☐ Natural Phenomenon ☐ Unknown ☐ Other

Description: Semi left the road damaging both saddle tanks

H. DAMAGES

# of Injuries: Driver | # of Fatalities:

I. ACTIONS

Response Action Taken:
Preparation for truck removal is underway

K. NOTIFIED

Responding Agency: ☐ DANR ☐ Local ☐ Discharger ☐ Federal ☐ EPA ☐ Other

Agencies Notified: DANR, Rapid City HAZMAT, SD Highway Patrol

K. COMMENTS

Comments:

Department of Agriculture and Natural Resources
Inspection, Compliance, and Remediation Program
523 East Capitol Avenue
Pierre, South Dakota 57501

Business Hours M – F 8:00-5:00 pm
Normal Business Hours- (605)773-3296
After Business Hours- (605) 773-3231

DEPARTMENT of AGRICULTURE and NATURAL RESOURCES
JOE FOSS BUILDING
523 E CAPITOL AVE
PIERRE SD 57501-3182
danr.sd.gov

Camelia Ilinescu
IDC Transport, Inc.
3000 Dundee Rd Unit 213
Northbrook, IL 60062

July 14, 2026

Subject: Department of Agriculture and Natural Resources File Number #2026.104: pertaining to a petroleum release on Highway 85 at Hilderbrand Creek, near Arpan, South Dakota.

Dear Mr. Ilinescu,

The Department of Agriculture and Natural Resources (DANR) is contacting you regarding the event noted above. A copy of the initial spill report form is enclosed for your review. Based on the information provided, an unknown volume of petroleum was released as a result of a single vehicle accident. The procedures for the assessment and cleanup of spills such as this were developed to protect surface and groundwater resources. In this situation, DANR requires the following work be performed:

- Retain an environmental consultant certified to perform petroleum remediation in South Dakota. Direct your consultant to excavate contaminated soil and properly dispose of all contaminated materials at a permitted municipal solid waste facility;
- Provide DANR with post-cleanup photos and landfill receipts;
- By **August 14, 2026**, please complete and return the attached Written Contamination Incident Follow Up Report form.

Hanna Kollbaum has been assigned as the project manager for this case. She will review the information provided and will contact you if further remedial action is necessary. If you have questions or need additional information, please do not hesitate to contact her at (605) 773-3296. Thank you for your cooperation and assistance.

Sincerely,

Jaclyn McGuire
Inspection, Compliance, & Remediation Program
(605) 773-3296

cc: Fred Lamphere, Butte County Emergency Manager
Jason Saivong, Butte County Assistant Emergency Manager
Joel Flesner, DOT Engineer
Jonah Schmagel, DOT Engineer

DEPARTMENT of AGRICULTURE and NATURAL RESOURCES
JOE FOSS BUILDING
523 E CAPITOL AVE
PIERRE SD 57501-3182
danr.sd.gov

July 16, 2026

Camelia Ilinescu
IDC Transport, Inc.
3000 Dundee Rd Unit 213
Northbrook, IL 60062

Re: Closure designation for DANR File #2026.104: pertaining to a petroleum release on Highway 85 at Hilderbrand Creek, near Arpan, South Dakota.

Dear Mr. Ilinescu,

The Department of Agriculture and Natural Resources (DANR) has reviewed the actions taken in response to the above referenced incident. Based on the information provided, there is no risk to human health or further risk to the environment. Therefore, the department is closing this case.

On July 14, 2026, DANR staff were notified of the release of an unknown volume of petroleum at an active construction site. The release was the result of a single vehicle accident involving one of your semi-trucks. The debris from the accident was scraped up and properly disposed at the Belle Fourche Landfill. No evidence of petroleum contamination remains at the site. If any future problems arise related to this release, IDC Transport Inc. may be responsible for performing further assessment and cleanup.

If you have questions or concerns about this site's Closure designation, please contact Hanna Kollbaum of my staff at 605.773.3296. Thank you for your cooperation in protecting South Dakota's groundwater resources.

Sincerely,

Terry Florentz, P.E.
Administrator
Inspection, Compliance, and Remediation Program

cc: Fred Lamphere, Butte County Emergency Manager
Jason Saivong, Butte County Deputy Emergency Manager
Joel Flesner, DOT Engineer
Jonah Schmagel, DOT Engineer

511 6th Avenue
Belle Fourche, SD 57717

SCALE TICKET

This is not an Invoice.

Customer ID: **336**
Customer: **Plains Towing & Recovery**
301 Roundup St
Belle Fourche, SD 57717

SITE	TICKET	GRID	WEIGHMASTER
CBFSL	1441	LOOSEFILL	Chanel K

DATE IN	TIME IN	VEHICLE	ROLL OFF
07/15/2026	12:40 PM	000 Cash	None

JOB NUMBER	MANIFEST
69	Side Dump

Job: **Plains Towing & Recovery**
Generator: **Plains Towing & Recovery - Default Job**

DESCRIPTION	QTY	UOM	RATE	NET AMOUNT	TAXES/FEES	AMOUNT DUE
21 MSW-Loosefill	17.43	TONS	$ 68.00	$ 1,185.24	$ 0.00	$ 1,185.24

Gross Weight	Tare Weight	Net Weight	Totals:			
79,080 lbs	44,220 lbs	34,860 lbs 17.43 tons		$ 1,185.24	$ 0.00	$ 1,185.24

Vehicle: **000 Cash - Cash Customer, Residential Vehicle**

PAYMENT TYPE
On Account

511 6th Avenue
Belle Fourche, SD 57717

SCALE TICKET

This is not an Invoice.

Customer ID: 336
Customer: Plains Towing & Recovery
301 Roundup St
Belle Fourche, SD 57717

SITE	TICKET	GRID	WEIGHMASTER
CBFSL	1441	LOOSEFILL	Chanel K

DATE IN	TIME IN	VEHICLE	ROLL OFF
07/15/2026	12:40 PM	000 Cash	None

JOB NUMBER	MANIFEST
69	Side Dump

Job: Plains Towing & Recovery
Generator: Plains Towing & Recovery - Default Job

DESCRIPTION	QTY	UOM	RATE	NET AMOUNT	TAXES/FEES	AMOUNT DUE
21 MSW-Loosefill	17.43	TONS	$ 68.00	$ 1,185.24	$ 0.00	$ 1,185.24

Gross Weight	Tare Weight	Net Weight	Totals:			
79,080 lbs	44,220 lbs	34,860 lbs 17.43 tons		$ 1,185.24	$ 0.00	$ 1,185.24

Vehicle: 000 Cash - Cash Customer, Residential Vehicle

PAYMENT TYPE
On Account

511 6th Avenue
Belle Fourche, SD 57717

SCALE TICKET

This is not an Invoice.

Customer ID: **336**
Customer: **Plains Towing & Recovery**
301 Roundup St
Belle Fourche, SD 57717

SITE	TICKET	GRID	WEIGHMASTER
CBFSL	1462	LOOSEFILL	Chanel K

DATE IN	TIME IN	VEHICLE	ROLL OFF
07/15/2026	02:08 PM	000 Cash	None

JOB NUMBER	MANIFEST
69	Sidedump

Job: **Plains Towing & Recovery**
Generator: **Plains Towing & Recovery - Default Job**

DESCRIPTION	QTY	UOM	RATE	NET AMOUNT	TAXES/FEES	AMOUNT DUE
21 MSW-Loosefill	6.56	TONS	$ 68.00	$ 446.08	$ 0.00	$ 446.08

Gross Weight 57,440 lbs
Tare Weight 44,320 lbs
Net Weight 13,120 lbs
6.56 tons

Totals:	$ 446.08	$ 0.00	$ 446.08

Vehicle: **000 Cash - Cash Customer, Residential Vehicle**

PAYMENT TYPE
On Account

511 6th Avenue
Belle Fourche, SD 57717

SCALE TICKET

This is not an Invoice.

Customer ID: 336
Customer: Plains Towing & Recovery
301 Roundup St
Belle Fourche, SD 57717

SITE	TICKET	GRID	WEIGHMASTER
CBFSL	1462	LOOSEFILL	Chanel K

DATE IN	TIME IN	VEHICLE	ROLL OFF
07/15/2026	02:08 PM	000 Cash	None

JOB NUMBER	MANIFEST
69	Sidedump

Job: Plains Towing & Recovery
Generator: Plains Towing & Recovery - Default Job

DESCRIPTION	QTY	UOM	RATE	NET AMOUNT	TAXES/FEES	AMOUNT DUE
21 MSW-Loosefill	6.56	TONS	$ 68.00	$ 446.08	$ 0.00	$ 446.08

Gross Weight 57,440 lbs
Tare Weight 44,320 lbs
Net Weight 13,120 lbs
6.56 tons

Totals:	$ 446.08	$ 0.00	$ 446.08

Vehicle: 000 Cash - Cash Customer, Residential Vehicle

PAYMENT TYPE
On Account

Outlook

RE: [EXT] 2026-07-16 - Mile Marker 75.3, Hwy 85, Butte County, SD

From Schmagel, Jonah <Jonah.Schmagel@state.sd.us>
Date Mon 7/20/2026 10:11 AM
To McGuire, Jaclyn <Jaclyn.McGuire@state.sd.us>
Cc Kollbaum, Hanna <Hanna.Kollbaum@state.sd.us>; McBurnett, Josh <Josh.McBurnett@state.sd.us>; Flesner, Joel <Joel.Flesner@state.sd.us>; Schmagel, Jonah <Jonah.Schmagel@state.sd.us>

Jackie,

I spoke with our people out there, and they reported that everything appears to be cleaned up and there is no remaining contamination. We will continue to monitor the area, but everything looks good at this time.
Please let us know if you need anything else.

Thanks,
Jonah S.

From: McGuire, Jaclyn <Jaclyn.McGuire@state.sd.us>
Sent: Thursday, July 16, 2026 12:26 PM
To: Flesner, Joel <Joel.Flesner@state.sd.us>; Schmagel, Jonah <Jonah.Schmagel@state.sd.us>
Cc: Kollbaum, Hanna <Hanna.Kollbaum@state.sd.us>
Subject: FW: [EXT] 2026-07-16 - Mile Marker 75.3, Hwy 85, Butte County, SD

Joel and Jonah,
We received these pictures from the towing company. Based on all of this information it looks like we don't have any remaining contamination. Can you confirm on your end?

Thanks,
Jackie McGuire

Jackie McGuire, CPRR | Spills Team Lead
Inspection, Compliance, and Remediation Program
SD Department of Agriculture and Natural Resources
523 East Capitol Ave. Pierre, SD 57501
Office: 605.773.3296 | Cell: 605.295.4146
24-Hour Spill Reporting: 605.773.3231
Spills Reporting Info

Photos were received by DANR staff on July 14, 2026.



A box culvert is being installed in a dry creek bed.


IDC
Transport, Inc.
Skokie, IL
GPSTab
BUD LIGHT





Photo shows the damage to the box culvert.



Photo shows the damage to the box culvert.

The following photos were received by DANR staff on July 16, 2026. They show site conditions before the accident debris was cleared from the site.


BUD LIGHT
BUD LIGHT
BUD LIGHT


ECP
ECP
IDC
321
Budweiser
BUD LIGHT
ULTRA

US DOT 1727243
MC 632942 P
1530860 MC
VIN KN565311
GPS Tab
ECP
ECP
Budweiser

The following photos were received by DANR staff on 16 July, 2026. They show site conditions after the crash debris and beer contaminated soil was scraped up.


ECP






12x12
Butte
PLACE TOTE
LABEL HERE




ECP
ECP
ECP
ECP
ECP
ECP
ECP
ECP
ECP


12x12
Butte
PLACE TOTE
LABEL HERE

