South Dakota Spill Report Form

PRCF #: **Case #:** 2026.112

Reported (MM/DD/YY): 7/29/26	Time: 330 PM	Recorded By: KN

A. REPORTER

Reported By: Savannah Baldwin

Organization Name: Ellsworth AFB — ☐ Discharger ☐ Public ☐ State ☐ Local ☑ Federal

Phone: — Email:

Address: Ellsworth AFB

City: Ellsworth AFB — State: SD — Zip: 57706

B. DISCHARGER (Responsible Party) ☐ As Above in A

Name: CMS Corp

Address: 1480 Ford St

City: Maumee — State: OH — Zip: 43537

Phone: — Email:

C. INCIDENT DATE & LOCATION ☐ As Above In B

Spill Date: (MM/DD/YY) 7/21/26 — Spill Time:

Street or Approx. Location: Bulk Fuel area

Survey Description:

City: Ellsworth AFB — County: Meade — State: SD — Zip: 57706

D. MATERIAL

Material type (Code/Name): ☐ Hazardous Substance ☐ Oil ☐ Material Unknown ☑ Other	Quantity Spilled	Spilled in Water	Units (Check one)	
Diesel	50	no	☐ lb. ☐ bbl.	☑ gal. ☐ oth.
			☐ lb. ☐ bbl.	☐ gal. ☐ oth.
			☐ lb. ☐ bbl.	☐ gal. ☐ oth.

E. SOURCE

Source of Spill: ☑ AST ☐ UST ☐ Railway ☐ Transport ☐ Fixed Facility ☐ Pipeline ☐ Highway ☐ Other

Description: Pallet broke causing the tank to leak

Regulated Tank Facility: ☐ Tank Facility ID #:

F. MEDIUM

Medium Affected: ☐ Air ☑ Land ☐ Water ☐ Groundwater ☐ Within Facilities Only

Waterway Affected:

G. CAUSE

Reported Cause: ☐ Transportation Accident ☐ Operational Error ☐ Dumping ☑ Equipment Failure ☐ Natural Phenomenon ☐ Unknown ☐ Other

Description: Pallet broke

H. DAMAGES

# of Injuries: — # of Fatalities:

I. ACTIONS

Response Action Taken:

K. NOTIFIED

Responding Agency: ☐ DANR ☐ Local ☐ Discharger ☑ Federal ☐ EPA ☐ Other

Agencies Notified: NRC, SD DANR, EAFB

K. COMMENTS

Comments:

The fuel was spilled into a secondary containment and was cleaned up using absorbents. The absorbents were placed in drums for disposal.

Department of Agriculture and Natural Resources
Inspection, Compliance, and Remediation Program
523 East Capitol Avenue
Pierre, South Dakota 57501

Business Hours M – F 8:00-5:00 pm
Normal Business Hours- (605)773-3296
After Business Hours- (605) 773-3231

DEPARTMENT of AGRICULTURE and NATURAL RESOURCES
JOE FOSS BUILDING
523 E CAPITOL AVE
PIERRE SD 57501-3182
danr.sd.gov

Savannah Baldwin
Ellsworth AFB
2125 Scott Drive, 28 CES/CEIEC
Ellsworth, SD 57706

July 30, 2026

Subject: Department of Agriculture and Natural Resources File Number 2026.112, pertaining to a diesel spill at Ellsworth AFB, Ellsworth AFB, South Dakota.

Dear Ms. Baldwin,

The Department of Agriculture and Natural Resources (DANR) is contacting you regarding the above referenced spill. A copy of the initial spill report form is enclosed for your review. Based on the information provided, 50 gallons of diesel were released from a tank. The product was spilled into secondary containment. The procedures for the assessment and cleanup of spills such as this were developed to protect surface and groundwater resources. In this situation, DANR requires the following:

- Properly dispose of the contaminated materials at a permitted municipal solid waste landfill;
- Provide this office cleanup photos and a copy of disposal receipts; and
- By August 31, 2026, please complete and return the attached Written Contamination Incident Follow Up Report form.

Derek Shiefelbein has been assigned as the project manager for this case. He will review all information provided and will contact you regarding any additional requirements. If you have questions or need additional information, please do not hesitate to contact either Derek or myself at 605.773.3296. Thank you for your cooperation in this matter.

Sincerely,

Jackie McGuire
Inspection, Compliance, & Remediation Program
(605) 773-3296

cc Sean Henderson, Meade County Emergency Manager, Sturgis, SD

INCIDENT FOLLOW-UP REPORT

DANR CASE FILE #: 2026.112

RETURN COMPLETED FORM TO:

SOUTH DAKOTA DEPARTMENT OF AGRICULTURE AND NATURAL RESOURCES (DANR)
INSPECTION, COMPLIANCE, AND REMEDIATION PROGRAM
JOE FOSS BUILDING
523 EAST CAPITOL AVENUE
PIERRE SD 57501-3182

NAME/TYPE OF PRODUCT SPILLED: Diesel Fuel

TOTAL AMOUNT OF PRODUCT SPILLED: 50 gallons

POUNDS OF ACTIVE INGREDIENT SPILLED (fertilizer/pesticide spills): N/A

AMOUNT OF PRODUCT RECOVERED: 50 gallons

WAS SURFACE WATER OR GROUND WATER IMPACTED BY THE SPILL?: No

SPILL DATE: 21 July 2026 DATE CLEANUP OCCURRED: 21 July 2026

SPILL LOCATION (physical address, directions, distance to nearest intersection or landmark, etc.):
1756 Rickenbacker Ct., Near Tank 8212

LATITUDE/LONGITUDE: 44.156728 / -103.095814

LAND USE (Residential, Commercial, Agricultural, Industrial, Other – describe): Commercial

RESPONSIBLE PARTY: CMS Corp

MAILING ADDRESS: 1480 Ford St.

CITY/STATE: Maumee/OH TELEPHONE NUMBER: (419) 276-3575

PROPERTY OWNER: 28th Civil Engineering Squadron

MAILING ADDRESS: 2125 Scott Dr.

CITY/STATE: Ellsworth/SD TELEPHONE NUMBER: (605) 385-2631

CONSULTANT / CLEANUP CONTRACTOR (if applicable): N/A

MAILING ADDRESS

CITY/STATE: TELEPHONE NUMBER:

INSURANCE PROVIDER (if applicable): N/A

NAME OF INSURED:

POLICY NUMBER: CLAIM NUMBER:

MAILING ADDRESS:

CITY/STATE: TELEPHONE NUMBER:

INCIDENT FOLLOW-UP REPORT (Page 2 of 2)

DANR CASE FILE #: 2026.112

WAS SOIL EXCAVATED?: No DIMENSIONS OF EXCAVATION: N/A

CUBIC YARDS EXCAVATED:

DISPOSAL SITE (Name of Facility):

DISPOSAL DATE: ***If soil was disposed, attach copies of disposal receipts***

FERTILIZER/PESTICIDE SPILLS ONLY

WAS CONTAMINATED SOIL/MATERIAL LAND APPLIED?: N/A

APPLICATION DATE ***Requires DANR Pre-Approval***

WAS SPILL CONTAINED TO IMMEDIATE AREA?: Yes

DISTANCE TO AND NAME OF NEAREST SURFACE WATER (include currently dry perennial streams):

Unnamed Tributary of Box Elder Creek, Outfall 006 - 2.3 miles

DISTANCE TO NEAREST WATER WELL (if applicable): 4.1 miles

OWNER OF NEAREST WATER WELL (if applicable): Wesley Rick (Irrigation Well)

DESCRIBE RESPONSE ACTION AND ADDITIONAL WORK PLANNED:

The contractor CMS working on an Area D fuel tank renovation were fueling equipment around the work area by moving the fuel tank around using a forklift. They lifted the secondary containment the fueling tank was sitting on, the secondary containment gave out under the weight of the tank and the tank tipped over spilling diesel fuel. The tank was picked back up onto the containment but the movement caused the tank to then tip backwards spilling more fuel. Overall 50 gallons of diesel was spilled, all of the fuel was contained to the Area D concrete dike system. The fuel was then surrounded with absorbents to keep the spill from spreading. The spill was cleaned up using buckets, absorbents and kitty litter. All of the used absorbents and kitty litter were collected into 55 gallon drums for disposal. The waste was manifested and picked up by Clean Harbors for disposal on 14 September 2026.

FORM COMPLETED BY: Savannah Baldwin DATE: 15 September 2026

E-MAIL ADDRESS: savannah.baldwin@us.af.mil

Original – DANR
Copy – Keep for your records.

CSV SK SHIP# 243487135

Spill Area D

V2609 2955

009842670SKS

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: SDE571524644 | 2. Page 1 of: 1 | 3. Emergency Response Phone: 1-800-468-1760 | 4. Manifest Tracking Number: 009842670 SKS

GENERATOR

5. Generator's Name and Mailing Address
Ellsworth AFB
2125 Scott Drive, Suite 2
ELLSWORTH AFB SD 57706-0000
Generator's Phone: 714-334-9884

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: SAFETY-KLEEN SYSTEMS INC | U.S. EPA ID Number: TXR000091285

7. Transporter 2 Company Name: CLEAN HARBORS ENV Svc Inc | U.S. EPA ID Number: MAD053322250

8. Designated Facility Name and Site Address: CLEAN HARBORS ENVIRONMENTAL SERVICES, IN
2247 S HIGHWAY 71
KIMBALL , NE 69145
Facility's Phone: 326-235-4012 | U.S. EPA ID Number: NED981723513

9a HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
X	1NA1993, WASTE DIESEL FUEL, (FUEL OIL), 3, PG III	1	DM	200	P	D001
X	2UN3175, SOLIDS CONTAINING FLAMMABLE LIQUID, N.O.S., (FUELS, DIESEL, NO. 2, KEROSINE (PETROLEUM), ABSORBENTS), 4.1, PG II	3	DM	747	P	NONE
	3.					
	4.					

14. Special Handling Instructions and Additional Information: TSD:KP 100817445 EL216651 CSD:
1)ERG#128;2)ERG#133;
24H EMERGENCY#800-468-1760 CH/SK/TFI-Contract retained by generator confers agency authority on initial transporter to add or substitute additional transporters on generator's behalf.

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Douglas Baldwin | Signature | Month 9 | Day 14 | Year 26

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit
Transporter signature (for exports only): Date leaving U.S.

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials

Transporter 1 Printed/Typed Name: Austin Rodgers | Signature | Month 9 | Day 14 | Year 26

Transporter 2 Printed/Typed Name: Lance Knue | Signature | Month 9 | Day 17 | Year 26

DESIGNATED FACILITY

18. Discrepancy

18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator) | U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator) | Month | Day | Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H040	H040		

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a

Printed/Typed Name: Terri Jenkins | Signature | Month 09 | Day 18 | Year 26

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.
1)10648486/3288958 2)10647975/3281123

DESIGNATED FACILITY TO EPA's e-MANIFEST SYSTEM

510 2605 125 255

CSY SK SHIP# 249487199

009842670SKS

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
SD2571924644	1	1-800-468-1760	009842670 SKS

GENERATOR

5. Generator's Name and Mailing Address
Ellsworth AFB
2125 Scott Drive, Suite 2
ELLSWORTH AFB SD 57706-2020
Generator's Phone: 714-334-3884

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: SAFETY-KLEEN SYSTEMS INC — U.S. EPA ID Number: TXR000081205

7. Transporter 2 Company Name — U.S. EPA ID Number

8. Designated Facility Name and Site Address: CLEAN HARBORS ENVIRONMENTAL SERVICES, IN
2247 S HIGHWAY 71
KIMBALL , NE 69145
Facility's Phone: 308-235-4012 — U.S. EPA ID Number: NED981723513

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
X	1 NA1993, WASTE DIESEL FUEL, (FUEL OIL), 3, PG III	1	DM	200	P	D001
X	2 UN3175, SOLIDS CONTAINING FLAMMABLE LIQU ID, N.O.S., (FUELS, DIESEL, NO. 2, KEROS INE (PETROLEUM), ABSORBENTS), 4.1, PG II	3	DM	747	P	NONE
	3.					
	4.					

14. Special Handling Instructions and Additional Information: TSD:KP 100817445 EL216851 CSD:
1)ERG#128;2)ERG#133;
24H EMERGENCY#800-468-1760-CH/SK/TFI-Contract retained by generator confers agency authority on initial transporter to add or substitute additional transporters on generator's behalf.

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked, and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Douglas Baldwin — Signature — Month 9 Day 14 Year 26

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Austin Rodgers — Signature — Month 9 Day 14 Year 26
Transporter 2 Printed/Typed Name — Signature — Month Day Year

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
18b. Alternate Facility (or Generator) — Manifest Reference Number: — U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) — Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name — Signature — Month Day Year

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.
1)10648486/3280956 2)10647975/3281123

DESIGNATED FACILITY TO EPA's e-MANIFEST SYSTEM

Attach Photos (Required):	Diesel Fuel Cell Spill Clean-up Report Photos.pdf  Diesel Fuel Plastic Pallet Replace Strong Wooden Pallet with 2 straps tie down  Fuel Cell Containment Plastic Pallet Broke that causes to flipped over the Fuel Cell

SUMMARY

Investigated By:	Joselito Guiking
Signature:	
Date:	July 22nd 2026
Health and Safety Director Follow-Up	FOLLOW-UPS **Resolved by Christopher Warren on 7/24/26** Please follow up on this Incident Investigation Report. - by Joselito Guiking on 7/24/26 - by Christopher Warren on 7/24/26 

Generated Monday, July 27th 2026, 2:46pm CDT.

powered by NOVARA

DIESEL FUEL SPILL CLEAN-UP REPORT PHOTOS AT TANK 16



Diesel Fuel Spilled Contained with Snake



Diesel Fuel was removed & stored into 5 gallons buckets



Absorbing Pads was used to cleanup the spill fuel



Kitty Litter Sand was used for final Clean-up



Completed Fuel Spill Final Cleaned up



Completed Diesel Fuel Spilled Cleaned up

From: BALDWIN, SAVANNAH P CIV USAF AFGSC 28 CES/CEIEC
To: Newling, Kelsey
Subject: RE: [EXT] Recent Spill
Date: Wednesday, July 29, 2026 3:25:22 PM
Attachments: image002.png

Hi Kelsey,

Yes, the spill occurred on base in our bulk fuels area within the diked containment.

I don't remember if you need latitude and longitude or not but its:
Lat: 44.148491
Long: -103.0949

Also, I misspoke before, you can address the letter to me. At least that is what I have had done previously.

Thanks,

Savannah Baldwin, GS-11
Air Quality, Water, Tanks, and Spills Manager
28 CES/CEIE
Ellsworth AFB
Comm: 605-385-2631
DSN: 675-2631

From: Newling, Kelsey <Kelsey.Newling@state.sd.us>
Sent: Wednesday, July 29, 2026 2:20 PM
To: BALDWIN, SAVANNAH P CIV USAF AFGSC 28 CES/CEIEC <savannah.baldwin@us.af.mil>
Subject: [Non-DoD Source] Recent Spill

> You don't often get email from kelsey.newling@state.sd.us. Learn why this is important

Hi Savannah,

My brain wasn't quite with it while I was on the phone. But where was the spill at on base?

Thanks,

Kelsey Newling
Environmental Scientist II/SARA Title III Coordinator
SD Department of Agriculture and Natural Resources
Inspection, Compliance and Remediation Program

Phone: 800.433.2288
Joe Foss Building
Pierre, SD 57501
Title III: https://danr.sd.gov/Agriculture/Inspection/SARATitle3/default.aspx

Attach Photos (Required):	Diesel Fuel Cell Spill Clean-up Report Photos.pdf  Diesel Fuel Plastic Pallet Replace Strong Wooden Pallet with 2 straps tie down  Fuel Cell Containment Plastic Pallet Broke that causes to flipped over the Fuel Cell

SUMMARY

Investigated By:	Joselito Guiking
Signature:	
Date:	July 22nd 2026
Health and Safety Director Follow-Up	FOLLOW-UPS **Resolved by Christopher Warren on 7/24/26** Please follow up on this Incident Investigation Report. - by Joselito Guiking on 7/24/26 - by Christopher Warren on 7/24/26 

Generated Monday, July 27th 2026, 2:46pm CDT.

powered by NOVARA

DIESEL FUEL SPILL CLEAN-UP REPORT PHOTOS AT TANK 16



Diesel Fuel Spilled Contained with Snake



Diesel Fuel was removed & stored into 5 gallons buckets



Absorbing Pads was used to cleanup the spill fuel



Kitty Litter Sand was used for final Clean-up



Completed Fuel Spill Final Cleaned up



Completed Diesel Fuel Spilled Cleaned up