

DEPARTMENT of ENVIRONMENT and NATURAL RESOURCES
Minerals & Mining Program
2050 West Main, Suite #1, Rapid City, SD 57702-2493
Telephone: 605-773-4201, FAX: 605-394-5317

FORM 2
RECEIVED

APPLICATION FOR PERMIT TO DRILL DEPT OF ENVIRONMENT & NATURAL RESOURCES - RAPID CITY

Type of well: Type of work Injection Oil Well Gas Well Reenter Well Drill Directional Well ✓ Drill New Well Other: Other: Telephone: Name and Address Operator: GULF EXPLORATION, Company On North Broadway Extension; Oklahoma City, Oklahoma 73114 405-840-3381 Name and Address of Surface Owner: Willis Williams/Tetrad Corporation P.O. Box 159; Elk Mountain, Wyoming 82324 Name and Address of Drilling Contractor and Rig Number: Not Yet Determined Surface Location of well: Qtr-Qtr, Sec, Twp, Rge, County, feet from nearest lines of section, and latitude and longitude (if available): 451' FNL, 1430' FEL (NE¼NW¼NE¼) of Section 29, T10S, R1E, B.H.M.; Lat: 43.158284, Long: -104.020647 (NAD 83) If Directional, top of pay and bottom hole location from nearest lines of section: Not Applicable Description of Spacing Unit: Acres in Spacing (Drilling) Unit: NW¼NE¼ of Section 29, T10S, R1E, B.H.M. 40 Acres Field and Pool, or Wildcat: Proposed Depth and Formation: Elevation: Well Name and Number: 3800' 2nd Leo Formation 3854.5 Wildcat Pointe du Hoc #1-29 Cementing Program (amount, type, yield, additives) Top of Cement: Weight per Foot: Depth: Size of Hole: Size of Casing: Surface 145 sx, circulated to surface w/100% excess 24.0# 400' 8.625" 1) 12.250" 560 sx, circulated to 2800' w/20% excess 2800' 17.0# 3800' 5.500" 2) 7.875" 3) 4) Describe Proposed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). Use additional page(s) if appropriate. PLEASE REFER TO THE ATTACHED DRILLING PROGNOSIS FOR ADDITIONAL INFORMATION Pit Liner Specifications: 12 mil plastic/vinyl liner I hereby certify that the foregoing as to any work or operation performed is a true and correct report of such work or operation. Al W. Salomone Co-Manager Signature Title Name (Print)

FOR OFFICE USE ONLY

Approved By:	2	Title: ADMINIST	RATOR,MINERAL	S & M	MINING PROGRAM
Permit No.: <u>2089</u>	API No.: 40 047	20350	Date Issued:	9-	-20-19
Conditions, if any, on attached page. SEE ATTACHED					



DEPARTMENT of ENVIRONMENT and NATURAL RESOURCES

JOE FOSS BUILDING 523 EAST CAPITOL PIERRE, SOUTH DAKOTA 57501-3182

denr.sd.gov

PERMIT CONDITIONS

Gulf: Pointe du Hoc 1-29 10S-1E-29 NWNE, Fall River County Permit: #2089 API: 40 047 20350

Approval has been granted to drill this location as detailed on the attached Application for Permit to Drill (Form #2) with the following additional conditions:

- 1. This permit is conditioned on compliance with all applicable requirements of South Dakota Codified Laws 45-9 and Administrative Rules of South Dakota (ARSD) 74:12.
- 2. The operator shall provide the department with the name of the drilling contractor before drilling commences.
- 3. A 12-mil woven, reinforced high-density polyethylene liner must be used on all pits.
- 4. Surface runoff must be diverted around the drill site.
- 5. The surface hole must be drilled with fresh water.
- 6. If any oil based mud is used for drilling you must have a pit reclamation plan approved by the department.
- 7. Cement must be circulated to the ground surface on the surface casing.
- 8. If production casing (long string) is set:
 - A. Cement must be circulated on the long string from total depth to the top of the Inyan Kara formation plus 50 feet.
 - B. A cement bond log must be run and filed with the department within 60 days of completion of the well.
- 9. Please notify this office prior to plugging so a witness can be on location. If plugging will occur after regular business hours, call Jeff Klenner at 605-394-2229.
- 10. If abandoned: Either a plugging plan must be submitted at least seven days prior to plugging for the department's review and approval or the following plan must be followed:
 - A. If the entire production casing is left in the wellbore:
 - 1. A mechanical integrity test must be conducted to verify the integrity of the casing as required by ARSD 74:12:03:02(4)(b)(ii).
 - a. If the test is unsuccessful, the well must be plugged as though no production casing is present or the leak must be located and isolated by squeeze cementing.
 - 2. All perforations must be isolated, either by squeeze cementing or placing a cast iron bridge plug, with a minimum of 20 feet of cement, above the perforations.
 - 3. A 100-foot plug, half in and half out of the base of the surface casing must be installed.
 - 4. A 25-foot cement plug at the top of the surface casing must be installed.
 - 5. Heavy, mud-laden fluid must be placed between all plugs.
 - B. If a portion of the production casing is removed:
 - 1. All perforations must be isolated, either by squeeze cementing or placing a cast iron bridge plug, with a minimum of 20 feet of cement, above the perforations.
 - 2. A 100-foot cement plug, half in and half out of the top of the casing stub must be installed after the retrievable part of the production casing has been removed.
 - 3. A 100-foot cement plug, half in and half out of the top of any fluid bearing formations or salt zone encountered between the top of the casing stub and the base of the surface casing must be

Gulf: Pointe du Hoc 1-29

Permit #2089 Page Two

installed. Fluid bearing formations at this site include: Minnelusa, Minnekahta, Canyon Springs, and Inyan Kara.

- 4. A 100-foot plug, half in and half out of the base of the surface casing must be installed.
- 5. A 25-foot cement plug at the top of the surface casing must be installed.
- 6. Heavy, mud-laden fluid must be placed between all plugs.
- C. Without production casing:
 - 1. 100-foot cement plugs, half in and half out of the top of any salt zones encountered and the following formations must be installed: Minnelusa, Minnekahta, Canyon Springs, and Inyan Kara.
 - 2. A 100-foot cement plug, half in and half out of the base of the surface casing must be installed.
 - 3. A 25-foot cement plug at the top of the surface casing must be installed.
 - 4. Heavy, mud-laden fluid must be placed between all plugs.
- D. The casing string must be cut off at least three feet below the final ground surface contour. A plate with the name of the operator, well name and number, and legal location by quarter-quarter section, township and range must be welded to the casing stub. The location of the abandoned well must be surveyed with high resolution global positioning system equipment or other appropriate survey methods sufficient to accurately locate the well. Survey coordinates must be included in the final abandonment report.
- 11. Surface reclamation of the site must be completed within one year of plugging and abandoning the well.
- 12. Interim reclamation must be conducted on all areas disturbed by a well drilling operation and not needed for production operations within 12 months after the well is completed in accordance with ARSD 74:12:03:07.
- 13. A washed and dried set of sample cuttings (and cores, if cut) must be shipped, free of charge, to:

Tim Cowman Geological Survey Program Akeley-Lawrence Science Center University of South Dakota 414 E. Clark Street Vermillion, SD 57069-2390