

SOUTH DAKOTA WELL REHABILITATION REPORT


10-85

Location $\frac{1}{4}$ $\frac{1}{4}$ Sec 16 Twp 123N Rg 63W

County

Brown

Please mark well location with an "X"



Rehabilitation Completion Date _____

PROPOSED USE:

☐ Domestic ☐ Municipal ☐ Stock
☐ Irrigation ☐ Industrial

Well Owner:

Name Spotman Sallet ServiceAddress East Hwy 12 Aberdeen SDDescribe original construction if possible?
(Attach original log if known)Artesian well 1" steel casing
Mr. Ken Buhler: talked you
about this Well @ North Dakota Drillers
convention - Did have this Well

Description of condition of well before rehabilitation:

Cut off extent 3" steel to top of growth
with 6" frost proof Hydrant - used 2 1/2" + 3" tee with a 1" plug
to well top - but construction doing digging & install Hydrant -
Location - The west ten feet of North seventy ft of the south
Description of rehabilitation work completed: Three hundred forty five feet of the east
two hundred fifty-six and eight tenths feet of lot 1.2 McIntyres
sub division of the south one-half of the SW quarter of Sec 16-123-
Rg -63W of the fifth principal Meridian, City of Aberdeen Brown CO.

Recasing information: Material _____ Diameter _____ Inches Depth _____ Feet

 Describe screen or perforations _____ Screen Location From _____ To _____
 From _____ To _____
Grout: ☐ YES ☐ NO Describe grouting procedure and grout _____

Well Test Data:

Specific capacity _____ Static water level _____

If a flowing well GPM _____ Shut in _____ PSI

This well rehabilitation was completed under license # 92 And this report is true and accurate.Drilling firm Indel WellSignature of Licensed Representative Flumer 11/1/11Signature of Well Owner BR ZornickDate 4-14-93