


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location NW 1/4 SW 1/4 Sec 35 Twp 124N Rg 64WCounty
BrownPlease mark well
location with
an "X"Well Owner: Kaneb Pipeline Operating
Name Valero L.P. Partnership, LPAddress One Valero Way
P.O. Box 696000
San Antonio, TX 78269Plugging completion Date 5/17/06

CHECK APPROPRIATE BOX

EXISTING WELL ☒ MP-2TEST HOLE ☐Well depth 16'

Hole depth _____

Casing material PVC

Hole size _____

Casing size(s) 2 inchCasing condition good

Describe plugging procedure: Protective steel casing was removed. PVC riser and screen were removed. Sand was added to approximately 3' from surface. Upper 3 feet was filled with concrete.

Describe grout or plugging material: Concrete

Type of non-slip plug: _____

This well or test hole was plugged under license # 530 And this report is true and accurate.

Drilling firm Maxim Technologies

Signature of Licensed Representative [Signature]

Signature of Well Owner [Signature]

Date 6-19-06

RECEIVED
JUN 30 2006
WATER RIGHTS
PROGRAM

7-7-06