

STATE OF SOUTH DAKOTA WELL DRILLERS REPORT


Location $\frac{1}{4}$ $\frac{1}{4}$ Sec 30 Twp 119N Rg 48W

County

Grant

North

Please mark well location with an "X"

Well Completion Date 11-24-1984

PROPOSED USE:

☒ Domestic ☐ Municipal ☐ Test Holes
☐ Irrigation ☐ Industrial ☐ Stock

Method of Drilling:

Rotary

WELL CONSTRUCTION:

Diameter of hole 30 inches Depth 45 feetCasing: ☐ Steel ☐ Plastic ☒ OtherSpecify Cement
 Pipe Weight Diameter From To
 _____ lb/ft _____ inches _____ feet _____ feet
 _____ lb/ft _____ inches _____ feet _____ feet
Was a well screen used? ☐ Yes ☒ No

If Not Specify _____

Screen Type _____ Slot Size _____

Length _____ Diameter _____

Was Casing left open end? ☒ Yes ☐ NoWas a Packer or seal used? ☐ Yes ☒ No

If so what material? _____

Was well gravel packed? ☒ Yes ☐ NoWas well grouted? ☐ Yes ☒ No

Describe grouting procedure _____

To what depth? _____ Feet

What was grouting material? _____

If cement, how many sacks? _____

Location of packer(s) and screen or perforated pipe _____

WAS WELL PLUGGED OR ABANDONED ☐ Yes ☒ No

If so how and with what material? _____

Well Owner:

Name Cornelius Homan FarmAddress Milbank, So Dak

Well Log:

Depth

Formation	From	To
	<u>45</u>	<u>20</u>
	<u>24</u>	<u>to water</u>
<u>black dirt</u>	<u>0</u>	<u>3</u>
<u>clay</u>	<u>3</u>	<u>15</u>
<u>sand clay</u>	<u>15</u>	<u>22</u>
<u>water gravel</u>	<u>22</u>	<u>24</u>
<u>sand clay</u>	<u>24</u>	<u>35</u>
<u>water gravel</u>	<u>35</u>	<u>37</u>
<u>sand clay</u>	<u>37</u>	<u>42</u>
<u>water gravel</u>	<u>42</u>	<u>45</u>

STATIC WATER LEVEL _____ Feet

If flowing: closed in pressure _____ PSI

GPM flow _____ through _____ inch pipe

Controlled by ☐ Valve ☐ Reducers ☐ Other

If other; specify _____

Can well be completely shut off? _____

WELL TEST DATA:

☒ Pumped☐ Bailed

Describe: _____


☐ Other _____

Pumping Level Below Land Surface

20 ft. After 30 Hrs. pumped _____ GPM35 ft. After 2 Hrs. pumped 6 GPM

_____ ft. After _____ Hrs. pumped _____ GPM

Remarks:

This well was drilled under license # 455

and this report is true and accurate.

owner _____
Drilling FirmSigned by James O. Farrelly3-29-1985
Date

5-16-85