


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location NE 1/4 NW 1/4 Sec 2 Twp 93N Rg 60WCounty
BON HOMMEPlease mark well
location with
an "X"

Well Owner:

Name BON HOMME COLONYAddress 31230 COLONY RDTABOR, SD 57063Plugging completion Date 5/19/11

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐Well depth ?Casing material STEELCasing size(s) 2"Casing condition DETERIORATED

Hole depth _____

Hole size _____

RECEIVED

JAN 17 2012

WATER RIGHTS
PROGRAMDescribe plugging procedure: PUMPLINE STUCK IN WELL. DUG DOWN
AROUND CASING. CUT OFF SIX FEET BELOW
GROUND LEVEL. PUT ON CEMENT CAPDescribe grout or plugging material: PORTLAND CEMENT. 50/50 MIX - THICK
BUT POURABLE.

Type of non-slip plug: _____

This well or test hole was plugged under license # 21 And this report is true and accurate.Drilling firm KORANDA WELL COMPANY LLCSignature of Licensed Representative Ken G. KorandaSignature of Well Owner Samuel J. WaldnesDate 6-3-11