

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT


10-85

Location NE 1/4 NW 1/4 Sec 2 Twp 93N Rg 60W

Well Owner:

County BON HOMMEName BON HOMME COLONYAddress 31230 COLONY RD.

Please mark well location with an "X"

Address TABOR, SD 57063Plugging completion Date 5/19/11

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐Well depth ?Casing material STEELCasing size(s) 4"Casing condition GOOD

Hole depth _____

Hole size _____

RECEIVED

JAN 17 2012

WATER RIGHTS
PROGRAM

Describe plugging procedure: PULLED OUT THREE PIPE. BALANCE OF
PUMP LINE STUCK IN WELL. CYLINDER STUCK AT
132 FT. DUG DOWN AROUND WELL. CUT OFF
BELOW PITLESS UNIT. PUT IN FOUR BAGS BENTONITE
AND CEMENT CAP ON TOP.

Describe grout or plugging material: PORTLAND CEMENT. 50/50 MIX - THICK
BUT POURABLE.

Type of non-slip plug: _____

This well or test hole was plugged under license # 21 And this report is true and accurate.Drilling firm KORANDA WELL COMPANY LLCSignature of Licensed Representative June T. KorandaSignature of Well Owner Samuel J. WaldnerDate 6-3-11