


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location NE 1/4 NE 1/4 Sec 13 Twp 15 Rg 18ECounty TacksonPlease mark well
location with
an "X"

Well Owner:

Name C.P. RailroadAddress 6000 800 LaSalle Ave. Suite 200
Minneapolis, Minnesota 55402Well location Cottonwood SD Well #1
Depo Well 43.96546 - 101.90439Plugging completion Date 10-28-2015

CHECK APPROPRIATE BOX

EXISTING WELL



TEST HOLE

Well depth 40 feetCasing material vit tileCasing size(s) 18 in.Casing condition good

Hole depth _____

Hole size _____

RECEIVED

JAN 27 2016

WATER RIGHTS
PROGRAM

Describe plugging procedure: drilled well, filled with bentonite chips, then cement
then local fill excavated and destroyed top 6' of casing
(well was filled with sand before bentonite was added.)
to top of water level

Describe grout or plugging material: grout chips, bag cement

Type of non-slip plug: CementThis well or test hole was plugged under license # 694 And this report is true and accurate.Drilling firm Antler enterprisesSignature of Licensed Representative [Signature]

Signature of Well Owner _____


Date 12-3-2015

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location NE 1/4 NE 1/4 Sec 13 Twp 0415 Rg 18E
KB per LAT/LSN

County

TacksonPlease mark well
location with
an "X"

Well Owner:

Name C.P. RailroadAddress 40 Aetona 800 LaSalle Ave Suite 500
Minneapolis MN, 55402Well location Cottonwood SD well #2
Section well 43.9649 - 101.90002Plugging completion Date 10-28-2015

CHECK APPROPRIATE BOX

EXISTING WELL



TEST HOLE



Well depth

30 feet

Casing material

Vit. Tile

Casing size(s)

18 in.

Casing condition

fair

Hole depth

Hole size

RECEIVED

JAN 27 2016

WATER RIGHTS
PROGRAMDescribe plugging procedure: drilled well, filled with bentonite chips, then cement
then fill from local source, excavated, and demolished top 6' casing
(well was filled with sand, before bentonite was added)
Top of water levelDescribe grout or plugging material: grout chips, bag cement

Type of non-slip plug:

CementThis well or test hole was plugged under license # 694 And this report is true and accurate.Drilling firm Autler enterprisesSignature of Licensed Representative [Signature]

Signature of Well Owner

Date 12-3-2015