


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location SW 1/4 SW 1/4 Sec 26 Twp 94 Rg 64County
CHARLES MIXPlease mark well
location with
an "X"

Well Owner:

Name YANKTON SIOUX TRIBEAddress 9100 388th AVE.MARTY, SDPlugging completion Date 3/23/16EAST WELL

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐Well depth 200'Casing material STEELCasing size(s) 5Casing condition FAIR

Hole depth _____

Hole size _____

RECEIVED

JAN - 5 2017

WATER RIGHTS
PROGRAM

Describe plugging procedure: PLACED BENTONITE CHIPS FROM
BOTTOM TO TOP IN WATER. LAST 6"-1'
PLACED PORTLAND CEMENT CAP. PITLESS UNIT
REMOVED FIRST.


Describe grout or plugging material: BENTONITE CHIPS & WATER. PORTLAND
CEMENT & WATER, THICK CONSISTENCY ON TOP
OF BENTONITE.

Type of non-slip plug: _____

This well or test hole was plugged under license # 21 And this report is true and accurate.Drilling firm KORANDA WELL COMPANY LLCSignature of Licensed Representative June T. KorandaSignature of Well Owner Yankton Sioux Tribe, Richard Leasing, Utilities ManagerDate 6-22-2016

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location SW 1/4 SW 1/4 Sec 26 Twp 93⁴ Rg 64County
CHARLES MIXPlease mark well
location with
an "X"

Well Owner:

Name YANKTON SIOUX TRIBEAddress 9100 388th AVE.MARTY, SDPlugging completion Date 3/23/16MIDDLE WELL

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐Well depth 200'Casing material STEELCasing size(s) 5"Casing condition FAIR

Hole depth _____

Hole size _____

RECEIVED

JAN - 5 2017

WATER RIGHTS
PROGRAM

Describe plugging procedure: PLACED BENTONITE CHIPS FROM
BOTTOM TO TOP IN WATER. LAST 6"-1'
PLACED A CEMENT CAP. PITLESS UNIT
REMOVED FIRST.


Describe grout or plugging material: BENTONITE CHIPS & WATER
PORTLAND CEMENT & WATER, THICK CONSISTENCY
ON TOP OF BENTONITE PITLES

Type of non-slip plug: _____

This well or test hole was plugged under license # 21 And this report is true and accurate.Drilling firm KORANDA WELL COMPANY LLCSignature of Licensed Representative Jane T. KorandaSignature of Well Owner Yankton Sioux Tribe, Richard Leason, Utility ManagerDate 6/22/16

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location SW 1/4 SE 1/4 Sec 26 Twp 91 N Rg 64County
CHARLES MIXPlease mark well
location with
an "X"

Well Owner:

Name YANKTON SIOUX TRIBEAddress 9100 388th AVEMARTIN, SDPlugging completion Date 3/23/16WEST WELL

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐Well depth 200'Casing material STEELCasing size(s) 5"Casing condition FAIR

Hole depth _____

Hole size _____

RECEIVED

JAN - 5 2017

WATER RIGHTS
PROGRAM

Describe plugging procedure: PLACED BENTONITE CHIPS FROM
BOTTOM TO TOP IN WATER. LAST 6"-1'
PLACED A CONCRETE CAP PITLESS UNIT
REMOVED FIRST

Describe grout or plugging material: BENTONITE CHIPS & WATER
PORTLAND CEMENT & WATER, THICK
CONSISTENCY ON TOP OF BENTONITE.

Type of non-slip plug: _____

This well or test hole was plugged under license # 21 And this report is true and accurate.Drilling firm KORANDA WELL COMPANY LLCSignature of Licensed Representative June J. KorandaSignature of Well Owner Yankton Sioux Tribe, Richard Leason, Utilities ManagerDate 6-22-2016