


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02

Location NW 1/4 SE 1/4 Sec 9 Twp 1N Rg 7ECounty PenningtonPlease mark well
location with an "X"Plugging Completion Date 6-13-17

Well Owner:

Name: Rapid City Public Works Dept.Address: 300 6th Street #2City, State, Zip: Rapid City SD 57701Comments: Southwest Firehouse
BH-2

RECEIVED

JUN 16 2017

WATER RIGHTS
PROGRAM

CHECK APPROPRIATE BOX

EXISTING WELL ☒	TEST HOLE ☐
Well depth <u>20 Feet</u>	Hole depth _____
Casing material <u>PVC</u>	Hole size _____
Casing size(s) <u>2"</u>	
Casing condition <u>Good</u>	

Describe plugging procedure:

Sand to 15' below surface
Cement Grout to surface


Describe grout or plugging material:

Dayton Superior
1107 Advantage Grout, cementitious
Non-Shrinking, Non-Corrosive

Type of non-slip plug: _____

This well or test hole was plugged under license # 541 and this report is true and accurate.Drilling firm: FMG EngineeringSignature of Licensed Representative: [Signature]Signature of Well Owner: [Signature]Date: 6-14-17

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02

Location NW $\frac{1}{4}$ SE $\frac{1}{4}$ Sec 9 Twp 1N Rg 7ECounty PenningtonPlease mark well
location with an "X"Plugging Completion Date 6-13-17

Well Owner:

Name: Rapid City Public Works Dept.Address: 300 6th St. #2City, State, Zip: Rapid City SD 57701

Comments:

Southwest Firehouse
BH-3

RECEIVED

JUN 16 2017

WATER RIGHTS
PROGRAM

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐Well depth 25 feetCasing material PVCCasing size(s) 2"Casing condition Good

Hole depth _____

Hole size _____

Describe plugging procedure:


Sand to 15' below surfaceCement Grout to surface

Describe grout or plugging material:

Dayton Superior1107 Advantage Grout, cementitiousNon-Shrinking, Non-Corrosive

Type of non-slip plug: _____

This well or test hole was plugged under license # 541 and this report is true and accurate.Drilling firm: FMG EngineeringSignature of Licensed Representative: [Signature]Signature of Well Owner: [Signature]Date: 6-14-17

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02Location NW 1/4 SE 1/4 Sec 9 Twp 1 N Rg 7ECounty PenningtonPlease mark well
location with an "X"Plugging Completion Date 6-13-17

Well Owner:

Name: Rapid City Public Works Dept.Address: 300 6th St. #2City, State, Zip: Rapid City SD 57701

Comments:

Southwest Firehouse
BH-4**RECEIVED****JUN 16 2017****WATER RIGHTS
PROGRAM****CHECK APPROPRIATE BOX**

EXISTING WELL ☒	TEST HOLE ☐
Well depth <u>20 feet</u>	Hole depth _____
Casing material <u>PVC</u>	Hole size _____
Casing size(s) <u>2"</u>	
Casing condition <u>Good</u>	

Describe plugging procedure:

Sand to 15' below surfaceCement Grout to surface

Describe grout or plugging material:

Dayton Superior1107 Advantage Grout, cementitiousNon-shrinking, Non-corrosive

Type of non-slip plug: _____

This well or test hole was plugged under license # 541 and this report is true and accurate.Drilling firm: FMG EngineeringSignature of Licensed Representative: [Signature]Signature of Well Owner: [Signature]Date: 6-14-17



Google Earth

feet
meters

100

500



Pennington County
Rapid City

NW¼ SE¼, Sec. 9, T1N, R7E



FMG, INC. 3700 Sturgis Road, Rapid City, South Dakota 57702-0317

605/342-4105
www.fmgengineering.com

RECEIVED

JUN 16 2017

**WATER RIGHTS
PROGRAM**

June 14, 2017

DENR – Water Rights Program

Attn: Ken Buhler

Joe Foss Building

523 East Capitol Avenue

Pierre, SD 57501

RE: WELL PLUGGING REPORTS – SOUTHWEST FIREHOUSE, RAPID CITY, SD

Dear Mr. Buhler,

We were retained by the City of Rapid City to abandon three monitor wells at the Southwest Firehouse in Rapid City, SD. The wells were installed by FMG in 1990. The wells were plugged on June 13, 2017, in accordance with SD Well Construction Standard 74:02:04:69.

Enclosed are three well plugging reports, one for each monitor well. We trust this information to be sufficient. Please contact us with any questions.

Respectfully submitted,

FMG, Inc.,

Brandon Silver

Enclosures