SOUTH DAKOTA WATER WELL COMPLETION REPORT

2024

Location SE ¼ SW ¼ Sec 10 Twp 4S Rg 5E

County: Custer

GPS Coordinates

Lat: _____

Lon: _____

Please mark well location with an "X" on section grid



Well Completion Date: 1/8/2026

Distance from nearest potential pollution source (Septic tank, abandoned well, feed lot, etc.)

? 1200 ft. from Septic (identify source)

PROPOSED USE:
- [x] Domestic/Stock
- [ ] Municipal
- [ ] Business
- [ ] Monitoring Well
- [ ] Irrigation
- [ ] Industrial
- [ ] Institutional
- [ ] Test Hole
- [ ] Dewatering Well
- [ ] Geothermal
- [ ] Other _____

METHOD OF DRILLING: Forward Rotary Air Hammer

CASING DATA: [ ] Steel [x] Plastic [ ] Other

If other describe: Set 30 ft of 6" 160 psi PVC

PIPEWEIGHT	DIAMETER	FROM	TO	HOLE DIAMETER
LB/FT	IN	0 FT	28 FT	8.75 IN
LB/FT	IN	28 FT	160 FT	6 IN
LB/FT	IN	FT	FT	IN

GROUTING DATA:

Grout Type	No. of Sacks	Grout Weight	From	To
Portland II	4	Lb/gal	28.0 Ft	0.0 Ft
w/ 2% bent		Lb/gal	Ft	Ft

Describe grouting procedure: Through Trimmie Pipe

SCREEN: [x] Perforated pipe [ ] Manufactured

Diameter 4.5 Inches Length 140.0 Feet

Matenal PVC

Slot Size .25 Set From 160.0 Feet to 20.0 Feet

Other information: 60 feet staggered from bottom

WAS A PACKER OR SEAL USED? [ ] Yes [x] No

If so, what matenal?

Describe packer(s) and location

DISINFECTION: Was well disinfected upon completion?

- [x] Yes, How? w/ chlorine solution
- [ ] No, Why Not?

Lab sample sent to for water quality analysis

Well Owner: Jonathan R & Holly R Price, Trustees Price Family 2012 Revocable Trust

Business Name: c/o Studt Construction, Inc

Address: 25078 Ruby Road

City, State, Zip: Custer, SD 57730

RECEIVED JAN 26 2026 OFFICE OF WATER

WELL LOG:

FORMATION	DEPTH FROM	DEPTH TO
Hard pegmatite	0.0	5.0
Soft Schist	5.0	22.0
Medium Hard Gray Schist	22.0	70.0
Soft Brown Shist	70.0	85.0
Pegmatite	85.0	90.0
Pegmatite Fracture 2 gpm	90.0	92.0
Pegmatite	92.0	110.0
Pegmatite Fracture 15 gpm	110.0	112.0
Pegmatite	112.0	131.0

STATIC WATER LEVEL 90.0 FEET

If flowing: closed in pressure _____ PSI

GPM flow 20.0 through _____ Inch pipe

Controlled by [ ] Valve [ ] Reducers [ ] Other _____

Reduced flow rate _____ GPM

Can well be completely shut in?

WELL TEST DATA:
- [x] Pumped Describe: w/ air
- [ ] Bailed [x] Air
- [ ] Other

Pumping Level Below Land Surface

_____ Ft. After _____ Hrs. pumped _____ GPM

_____ Ft. After _____ Hrs. pumped _____ GPM

If pump installed, pump rate: _____ GPM

REMARKS Owners Address: 22733 Ordonez Dr, Salinas, CA 93908-1031
Property Address: 25450 Lower French Creek Rd,Custer, SD 57730

Formation Continued:
Pegmatite Fracture gpm 20+ 131-133
Pegmatite/Schist 133-160

This well was drilled under license # 324

And this report is true and accurate.

Drilling firm: Alexander Drilling, Inc

Signature of License Representative: [signature]

Signature of Well Owner or Equitable Property Holder: [signature] for Studt Construction, Inc

Date: 1/16/26

Please return White Copy to DANR Water Rights 523 E. Capitol Ave., Pierre SD 57501