#### By using this form you are agreeing to our terms of use. Please read: SD EForm - 0947 V5

Department of Agriculture and Natural Resources Minerals and Mining Program 523 East Capitol Avenue

Pierre, South Dakota 57501-3182 605 773-4201; Fax: 605 773-5286 RECEIVED

APR 06 2022

AMENDMENT TO MINING/MILLING PERMIT NO.

**PAID** 

MINERALS & MINING PROGRAM

	APR 0 6 2022
Operatoria nema:	Ck#
Operator's name: Cold Spring Granite Co.	Amount #_ /, &\alpha\cap
Mailing address:	Telephone:
17482 Granite West Rd. Cold Spring, MN 56320	(320) 685-3621
Cold Spring, Win 30320	
Local address:	Telephone:
Coldspring-Milbank 14982 485th Avenue	(605) 432-9389
Milbank, SD 57252	
Posident agent (if out of state corneration):	
C.I. Corpo	ration System
Desident and address	Decident assertation bearing
Resident agent address:	Resident agent telephone:
310 S. Coteau St. Pierre, SD 57501	(605) 221-2779
1 lefte, 3D 37301	
Legal description of affected land:	
Portions of Sections 7, 8, and 17; T120N-R47W	
or the same of the	
County: Grant	
Description of amendment:	
See Attachment	THE RESERVE OF THE PARTY OF THE
Oce Attachment	
THE RESERVE TO LET A PROPERTY OF	THE RESERVE OF THE PARTY OF THE
ASSESSED FOR THE STATE OF THE S	
THE RESERVE OF THE PARTY OF THE	Committee of the second second second
Name and address of surface owner:	Name and address of mineral owner:
Could Continue Countillo Co	Cold Caring Cronita Ca
Cold Spring Granite Co. 17482 Granite West Rd.	Cold Spring Granite Co. 17482 Granite West Rd.
Cold Spring, MN 56320	Cold Spring, MN 56320

2021 Amendment.doc Page 1

#### INSTRUCTIONS:

This amendment application must be accompanied by:

1. The contents of the permit amendment pursuant to ARSD 74:29:03:03.

2. A fee of \$1,000 payable to the Department of Agriculture and Natural Resources pursuant to SDCL 45-6B-14 for a large scale operation. A fee of \$100 payable to the Department of Agriculture and Natural Resources pursuant to SDCL 45-6B-55 for a small scale operation.

Prior to Board approval of the permit amendment, the operator must submit the following:

- Proof of filing a copy of the amendment with the Register of Deeds pursuant to ARSD 74:29:03:05(1), ARSD 74:29:03:08, and ARSD 74:29:03:10.
- 2. A surety in an amount to be determined by the department pursuant to ARSD 74:29:03:04.
- 3. A copy of instruments of consultation from all surface landowners, if different than the owner of the minerals pursuant to SDCL 45-6B-12 and 13.

Applicant hereby affirms that the mining and milling will be conducted pursuant to SDCL 45-6B, or any regulations promulgated thereunder; that he will grant access to the SD Board of Minerals and Environment or its agents to the area under application from the date of the application and during the life of the permit as is necessary to assure compliance with SDCL 45-6B.

I declare and affirm under the penalties of perjury that this claim (petition, application, information) has been examined by me, and to the best of my knowledge and belief, is in all things true and correct.

toland	Date: 3-10-2a
Signature	
Title: Environmental Engineer	
STATE OF Minnesota	
COUNTY OF Stearns	
On this 6th day of Ma	, 20_22_, before me personally appeared
Steve Chouarand	, who acknowledged himself to be the Environmental Engineer
for Cold Spring Granite (Operator)	(Title) and that he is authorized to execute the Amendment to Mining/
(Operator) Milling Permit for the purposes contained to	herein.
Notary Bublic	My Commission Expires: 1-31-2023
SEAL RENAE J. HEMMESCH Notary Public Minnesota My Commission Expires January 31, 2023	FOR DEPARTMENT USE ONLY
DATE APPROVED: BOND AMOUNT:	PERMIT NUMBER:
	Chairman, SD Board of Minerals & Environment

2021 Amendment.doc Page 2

ADDITIONAL BOND AMOUNT:

#### STATE OF SOUTH DAKOTA

### APR 0 6 2022 MINERALS & MINING PROGRAM

### BEFORE THE SECRETARY OF

#### THE DEPARTMENT OF AGRICULTURE AND NATURAL RESOURCES

IN THE MATTER OF THE APPLICATION OF	}
Cold Spring Granite Co.	) CERTIFICATION OF
STATE OF Minnesota	) APPLICANT
COUNTY OF Stearns	}
I, Steve Chouanard	the applicant in the above matter after being duly owing information in regard to this application:

I have read and understand South Dakota Codified Law Section 1-41-20 which provides:

"The secretary may reject an application for any permit filed pursuant to Titles 34A or 45, including any application by any concentrated swine feeding operation for authorization to operate under a general permit, upon making a specific finding that:

- (1) The applicant is unsuited or unqualified to perform the obligations of a permit holder based upon a finding that the applicant, any officer, director, partner, or resident general manager of the facility for which application has been made:
  - (a) Has intentionally misrepresented a material fact in applying for a permit;
  - (b) Has been convicted of a felony or other crime involving moral turpitude;
  - (c) Has habitually and intentionally violated environmental laws of any state or the United States which have caused significant and material environmental damage;
  - (d) Has had any permit revoked under the environmental laws of any state or the United States; or
  - (e) Has otherwise demonstrated through clear and convincing evidence of previous actions that the applicant lacks the necessary good character and competency to reliably carry out the obligations imposed by law upon the permit holder; or
- (2) The application substantially duplicates an application by the same applicant denied within the past five years which denial has not been reversed by a court of competent jurisdiction. Nothing in this subdivision may be construed to prohibit an applicant from submitting a new application for a permit previously denied, if the new application represents a good faith attempt by the applicant to correct the deficiencies that served as the basis for the denial in the original application.

All applications filed pursuant to Titles 34A and 45 shall include a certification, sworn to under oath and signed by the applicant, that he is not disqualified by reason of this section from obtaining a permit. In the absence of evidence to the contrary, that certification shall constitute a prima facie showing of the suitability and qualification of the applicant. If at any point in the application review, recommendation or hearing process, the secretary finds the applicant has intentionally made any material misrepresentation of fact in regard to this certification,

consideration of the application may be suspended and the application may be rejected as provided for under this section.

Applications rejected pursuant to this section constitute final agency action upon that application and may be appealed to circuit court as provided for under chapter 1-26."

I certify pursuant to 1-41-20, that as an applicant, officer, director, partner, or resident general manager of the activity or facility for which the application has been made that I; a) have not intentionally misrepresented a material fact in applying for a permit; b) have not been convicted of a felony or other crime of moral turpitude; c) have not habitually and intentionally violated environmental laws of any state or the United States which have caused significant and material environmental damage; (d) have not had any permit revoked under the environmental laws of any state or the United States; or e) have not otherwise demonstrated through clear and convincing evidence of previous actions that I lack the necessary good character and competency to reliably carry out the obligations imposed by law upon me. I also certify that this application does not substantially duplicate an application by the same applicant denied within the past five years which denial has not been reversed by a court of competent jurisdiction. Further;

"I declare and affirm under the penalties of perjury that this claim (petition, application, information) has been examined by me, and to the best of my knowledge and belief, is in all things true and correct."

Dated this 10 day of 11 arch, 20 day.	
Applicant (print) Steve Chouanard	
manne	
Applicant (signature)	
Subscribed and sworn before me this 10th day of March ,	202>
Penae 6	
Notary Public (signature)	
My commission expires: 1-31-2023	
RENAE J. HEMMESCH Notary Publics EAL Minnesota Ay Commission Expires January 31, 2023	

PLEASE ATTACH ANY ADDITIONAL INFORMATION NECESSARY TO DISCLOSE
ALL FACTS AND DOCUMENTS PERTAINING TO
SDCL 1-41-20 (1) (a) THROUGH (e).
ALL VIOLATIONS MUST BE DISCLOSED, BUT WILL NOT
AUTOMATICALLY RESULT IN THE REJECTION OF AN APPLICATION

### **Description of Amendment:**

An application has been submitted from Cold Spring Granite Company for amending the Large Scale Mine Permit #008 to add 59.31 acres of permitted affected acreage. This is because Cold Spring Granite Company has reached the maximum 48.40 acres of additional affected land that can be added through technical revisions. Cold Spring Granite Company is requesting to add a topsoil stockpile, extend a grout disposal area to include a grout crushing pad and increase block storage. The proposed Permit amendment covers three areas of operation at Cold Spring Granite's Milbank Quarries.

First at Milbank #2, 3.70 acres of new permitted affected area would be for a portion of an overburden (sand) Stockpile, north of the quarry that extends outside of the permitted affected area. Cold Spring Granite Company is also proposing to place a 35.50-acre grout crushing pad in an area that is currently permitted for grout disposal. Next, 28.80 acres of new permitted affected area are required for future expansion of the crushing pad to the north of the Milbank #2 Quarry. Finally, Cold Spring Granite Company plans to stockpile topsoil along the edge of the crushing pad. One acre of the topsoil stockpile will be inside the current permitted grout pile disposal area, while the remaining 13.64 acres will be in the new permitted affected acreage. The topsoil stockpile berm will be 150 ft. wide x 10 high and 4,270 ft. long. These revisions can be seen on the Milbank #2 Permit Amendment Map.

Second, north of the Milbank shop, Cold Spring Granite Company plans to add 5.47 acres of new permitted affected acreage for block storage. The company also plans add 3.47 acres of new permitted affected acreage to an area south of the shop for block storage. These revisions can be seen on the Milbank Shop and Fishers Permit Amendment Map.

Finally, at the Milbank #1 Quarry, Cold Spring Granite Company is planning to remove granite for crushing from two Pre 1971 grout piles that account for 4.23 acres of new permitted affected acreage. These areas will be reclaimed when the granite is completely removed. These revisions can be seen on the Milbank #1 Permit Amendment Map.

### **Amendment to Mining Permit**

Responses to ARSD 74:29:03:03

- 1. Cold Spring Granite Co.
- 2. Permit Number 008
- 3. Amendment is being made to expand the size of the permitted affected area within the current permit boundary. Also, a change from grout disposal area to a grout crushing pad and topsoil stockpile. Please refer to attached Description of Amendment.
- 4. ARSD 74:29:03:03(4) Legal Description: Portions of Sections 7, 8, and 17; T120N-R47W, Grant County.
- 5. ARSD 74:29:03:03(5) and ARSD 74:29:02:12(4) and (6) and ARSD 74:29:03:03(15) and ARSD 74:29:03:07(45-6B-7) (8). A map showing the added affected area is included.
  - Maps Include
    Milbank #1 Permit Amendment Map
    Milbank #2 Permit Amendment Map
    Milbank Shop and Fishers Permit Amendment Map
- 6. ARSD 74:29:03:03(6): The estimated cost of implementing and completing the reclamation of land affected by the amendment: The stripping and reclamation of the land will be done by Fishers Sand and Gravel Industries. The stripping of topsoil equals 1 Ft. of stripping with an estimated 1,600 yards per acre. The reclamation would be to spread topsoil at an estimated 2,178 tons per acre.
  - 1) Milbank #2 Permit Amendment Map: The Area North of Milbank #2 will be made into a large Crushing Pad. Only 35.5 acres will initially be made into a crushing pad with an additional 43.37 acres for future crushing pad area and berm. This adds up to a total of 78.87 acres. Development and stripping of the site comes to an estimated 64.34 acres X 1,600 yards=102,944 yards. Reclamation of the site is estimated at 64.34 acres X 2,178 tons per acre, which comes to a total of 140,132 tons of fill material. Fishers estimated spreading cost would be about \$3 per ton. The cost of to cover the site back to matching elevations would be \$420,396. The 140,132 tons to reclaim the area would come from the overburden pile and topsoil piles. Since the overburden pile will also be used to fill in holes, the actual size of the pile might be smaller. The current size of the overburden pile is 3.7 acres. If we use 2,178 tons of topsoil per acre it will cost an estimated \$24,176 to cover the overburden pile with topsoil. To seed the site in native prairie grass it is estimated to be about \$300 per acre. The

- complete site with the overburden pile comes to an estimated 68.04 acres, so 68.04 acres X \$300 comes to \$20,412.
- 2) Milbank Shop and Fishers Permit Amendment Map: The Area around the Shop is 8.94 acres of expansion. The 21.09 acres that are permitted but have not been affected yet would remain as is. The 8.94 acres would have topsoil removed and that would be stored on the top soil stockpiles in Milbank #2 Permit amended area. This would come to 8.94 acres X 1,600 yards =14,304 yards of topsoil. To reclaim this area, it would be 8.94 acres X 2,178 tons per acre=19,471 tons. 19,471 tons X \$3 per ton comes to \$58,414 to reclaim the area. The site would be planted in natural grasses and the seeding would cost \$300 per acres so 8.94 acres X \$300 comes to \$2,682.
- 3) Milbank #1 Permit Amendment Map: These areas are the Old Grout piles near Milbank #1. These areas are currently having the grout removed and used by Fishers. After all the grout is removed Fishers will reclaim the 2 areas by spreading overburden and topsoil over the total 4.23 acres. It would take an estimate 4.23 acres and 2,178 tons of fill material per acre to cover the old grout areas. This cost is estimated at 4.23 acres X 2,178 tons equaling 9,212 tons and 9,212 X \$3 per ton equals \$27,638. Seeding would be done after topsoil has been spread at a cost of \$300 per acre equaling a total of \$1269.
- 7. ARSD 74:29:03:03(7): Reclamation will be up to the standard set forth in the original Permit 008 Reclamation Plan. This starts on page 79 and 80 of the original permit. Milbank #2 and the overburden pile will be reclaimed at the same time. The crushing area will be leveled with Bulldozers after all aggregate piles have been sold and removed. Any depressions will be filled with excess crushing pad material. If any more fill material is needed it will be taken from the over burden pile. After the area is leveled and the overburden pile is sloped to a 4 to 1 ratio, the topsoil will be spread throughout the site. The topsoil will be spread at a 1 ft. layer across the site unless it is not needed to keep an even level. Whatever is left of the topsoil stockpiles after all other areas have been reclaimed, will be seeded according to the seed plan in Appendix "E". The Block Storage Area at the Milbank Shop will be reclaimed by removing all of the blocks on site and spreading a 1ft. layer of topsoil from Milbank #2. After spreading the topsoil, it will be seeded according to the original permit in Appendix "E". Once all the Grout is removed from

the Pre-1971 grout piles on Milbank #1, fill material will be brought in to level any areas that might have depression and do not match the natural landscape. When the area is leveled, topsoil will be spread at about a 1 ft. layer, it will be seeded. The Seeding and planting recommendation can be found in Seed Plan Appendix "E" of the original permit. The current planting specifications will be checked with Grant County Soil District before proceeding.

- 8. ARSD 74:29:03:03(10) and 45-6B-44 Cold Spring Granite Co. sent out a copy of the permit application to the following surface landowners adjacent to the site. Cold Spring Granite will submit proof of mailing application with certified mail return receipt.
  - Dakota Granite Co. 48391 150th St. Milbank, SD 57252
  - Marjorie & Bryan Schmidt, 14695 SD Highway 15, Milbank, SD 57252
  - Robert H & Lisa Hinders
     14921 485<sup>th</sup> Ave. Milbank, SD 57252
  - 4) Gene and Leah Pinkert 48575 149 St, Big Stone City, 57216
  - 5) Robert Angerhofer 48616 150th St. Big Stone City, SD 57216
  - Micheal & Jason M Mielitz
     15051 486<sup>th</sup> Ave. Big Stone City, SD 57216
  - 7) David W & Jacquelyn R Meyer 47998 151st St., Milbank, SD 57252
  - 8) Regina Anderson 15001 Co. Highway 37, Big Stone City, SD 57216
- 9. ARSD 74:29:03:03(11) and ARSD 74:29:03:05(2): Cold Spring Granite Co. sent a copy of the permit amendment application to South Dakota Department of Game, Fish, and Parks and the Grant County Natural Resources Conservation Service. A copy of the certified mail return receipt is included as proof of mailing. Cold Spring Granite Co. also sent out a copy of the permit amendment application to the South Dakota Department of Agriculture and Natural Resources, the State Archaeologist, and the South Dakota State Department of Health. A copy of certified mail return receipt is included as proof of mailing.
- 10. ASRD 74:29:03:03(12), ARSD 74:29:02:02, and SDCL 45-6B-4: Since the original permit is in compliance with grant county ordinances the amendment area should not change that. The Milbank #1 area is reclaiming old grout piles and is part of the reclamation plan which is compliance with county ordinances. The Milbank Shop area is just block storage which is also in compliance with county ordinances. Milbank #2 will be the new crushing area and that is

also in compliance with current county ordinances. Cold Spring Granite Co. sent out a copy of the permit amendment application to the Grant County Commission to make sure the Permit amendment is in compliance with all county ordinances. A letter from Grant County Commission is included as proof.

11. ARSD 74:29:03:03(13): Since the areas of the permit amendment are currently flat open field the reclamation will be to return it to same Contours.

Reclamation Maps included: Milbank #1 Reclamation

Milbank #2 Reclamation

Milbank Shop Reclamation Map

- 12. ARSD 74:29:03:03(14) and SDCL 45-6B-46: The mine permit amendment will extend the duration of the operation to an estimated year of 2070. Fishers plans to move into the expansion area by 2025. It is estimated at the current use that the Grout pile on Milbank #2 will be used up by 2065 with 5 years to finish up reclamation.
- 13. ARSD 74:29:03:03(15) and ARSD 74:29:03:07: The mine amendment permit application meets the following procedural completeness requirements in ARSD 74:29:02:01, as applicable.
  - 1) <u>45-6B-4:</u> See Item #10 above.
  - 2) 45-6B-5: Not applicable.
  - 3) 45-6B-6: Not applicable.
  - 4) 45-6B-7: Reclamation plan--Contents
    - 1) The type of reclamation the operator proposes to achieve in the reclamation of the affected land is wildlife habitat. This type of reclamation covers all of the areas of permit #008. The Amendment areas in Milbank #2, Milbank #1 and Milbank Shop are all with going to be reclaimed in Wildlife habitat and will follow the plan put forth in Permit #008.
    - 2) The Amendment locations are all within the area of Permit #008. A standard Soil survey was done for Permit #008 and is considered complete for this application.
    - 3) The Amendment locations are all with in the area of Permit #008. A vegetative survey was done by the Local Conservation district for Permit #008. A copy of this application will be sent to the local Conservation District.
    - 4) The Amendment locations are all with in the area of Permit #008. A wildlife survey was done by the Department of Game, Fish and Parks for Permit

- #008. A copy of this application will be sent to the local DNR Conservation officer for review.
- 5) The historic, archaeological, geologic, scientific and recreational significance are known to the applicant. The permit amendment areas are not changing anything done in the permit process.
- 6) A description how the reclamation plan will be implemented to meet the requirements of:
  - 1. 45-6B-37 Grading. The permit amendment area in Milbank #1 will be leveled and have topsoil added in a 1 ft. layer to match existing topography. This area will then be seeded when all leveled. This area will be sloped to prevent erosion and if any erosion is noticed, silt fence will be used until seed growth stabilizes the area. This will match surrounding topography and existing drainage. This is suitable for wildlife. During the Milbank Shop permit amendment reclamation, fill material and topsoil will be used to level the area back to the flat farm field. This will match the surrounding topography and existing drainage which will be suitable for wildlife. It will be seeded and erosion control will be implemented when needed. The Milbank #2 permit amendment area will also be leveled off and topsoil spread and seeded to match existing topography. The overburden pile on Milbank #2 will be graded to have a final slope with a 4 to 1 ratio, then seeded and suitable for wildlife. These areas will also be covered by grading plan in the original permit #008. The grading plan can be found on page 77 of the original plan. Erosion control is covered on page 62 item #3 of the original permit #008. Current drainage should not be affected and erosion control will be implemented when needed.
  - 2. 45-6B-38 Disposal of refuse. Since there are no structures in the 3 mine permit amendment areas there will be no removal of structures. For Milbank Shop permit amendment, any granite and wood refuse in the block storage area will be removed and

- cleaned up in the reclamation process. In the Milbank #2 Crushing area, granite and refuse will be removed during the Reclamation process. Any refuse in the overburden pile will be removed. As for the Milbank #1 Pre-1971 grout piles, all granite refuse will be crushed and removed. The areas will be leveled and cleared of debris.
- 3. 45-6B-39 Revegetation. The same exact seed mix and seeding timetable will be used for the Amendment areas as the original permit. This can be found in Appendix "E" of the original permit. If the local soil conservation district changes what is recommended in the future Cold Spring Granite co. will adjust at the time of Reclamation.
- 4. 45-6B-40, 45-6B-7(7) and SDCL 45-6B-40 and ARSD 74:29:07: 07: Removal and handling of Topsoil, For Milbank #2 and Milbank Shop permit amendment areas the topsoil will be removed at a depth of 1ft. and stockpiled in a berm along the edge of the crushing pad on Milbank #2. No trees or waste material will be removed from the topsoil locations because these areas are all farm field. During removal of topsoil, earthen berms or silt fence will be used to prevent erosion. The estimated volume of topsoil removed from Milbank #2 and Milbank Shop area is an estimated 117,248 cubic yards. These berms will be an estimated 150 ft. wide by 10 ft. high with 15 to 1 slope. Milbank #2 Permit Amendment Topsoil Cross Section Map shows dimensions of the stockpile. The length will run an estimated 4,270 ft. around the perimeter of the Milbank #2 Permit amendment area. The topsoil stockpiles are labeled on Milbank #2 Permit Amendment Map. The topsoil removed from the overburden stockpile area is shown on the center of Milbank #2 Permit Amendment Map. This is also the location of the topsoil removed from the 7.17 acres of permit area 487. The 7.17 acres from permit area 487 and 3.7 acres from the overburden

RECEIVED
APR 0.6 2022
AIMERALS & MINING PROGRAM

stockpile area comes to 10.87 acres. At 1 ft. of topsoil that comes to an estimated 17,537 cubic yards of topsoil. If there are any shortfalls in topsoil during the reclamation it will come from this topsoil stockpile. The topsoil piles will be seeded for stabilization until reclamation and will have legible signs marking the location. Since the area being stripped of topsoil is the same as the reclamation area, no additional topsoil will be needed. If extra fill is needed to level areas before topsoil is applied, it will be taken from the overburden pile. No topsoil will be removed from Milbank #1. The area will be leveled to match topography of location after all Granite has been removed. Topsoil will be brought in, spread at a 1 ft. layer and seeded after final leveling.

74:29:02:11, ARSD 74:29:07:08 through ARSD 74:29:07:12, and ARSD 74:29:07:27): There are no plans to divert surface runoff in the amendment areas. Milbank # 2 Permit Amendment area will follow all requirements in the Storm Water Pollution Prevention Plan for overburden stockpile, topsoil stockpile and crushing pad. Best management practices will be used around these areas to prevent runoff from escaping the site. This includes seeding the topsoil stockpile and using silt fence or earthen berms to prevent storm water runoff. These locations will also be inspected according to the Storm Water Pollution Prevention Plan (SWPPP) monthly. The Milbank #1 and Milbank Shop area will also follow SWPPP plan mentioned above. The Milbank Shop area will have silt fence along the tributary to the North Fork to make sure no storm water runoff makes it to the tributary. There are also no plans to divert the tributary. In the Milbank #1 area pre-1971 grout pile will be monitored for runoff and silt fence will be

used if needed until Seed growth has been

established.

5. Hydrologic Balance (SDCL 45-6B-41, ARSD

- 6. Slides, Subsidence, or Damage Protection, Fencing (SDCL 45-6B-42 and ARSD 74:29:07:16): There are no plans for quarries and grout piles in the Amendment Areas. In the Milbank #2 Amendment area there will be crushed piles, but this area will have a gate to prevent unauthorized access. The overburden stockpile will be sloped to prevent slides. Milbank #1 and Milbank shop will have no new quarry areas with piles and currently have Gates and fencing.
- 7. Spoil Piles, Weeds (SDCL 45-6B-43, ARSD 74:29:07:14, and ARSD 74:29:07:15): The Milbank #2 amendment area is being constructed to crush an old grout pile so no additional grout piles will be constructed. The Crushed piles will be sold so no weeds will grow and the Topsoil stockpile will be seeded to prevent weeds. The Overburden Stockpile will be shaped to prevent erosion and sprayed if weeds appear. Milbank #1 will have no spoil piles and the area will be seeded when reclamation is completed. The Milbank Shop amendment area is block storage so no piles will accumulate. The noxious weeds in the amendment areas will be taken care of and sprayed like in the original permit #008. This noxious weed control program can be found on page 64 of the original permit.
- 8. 45-6B-45, SDCL 45-6B-44, SDCL 45-6B-45, ARSD 74:29:06:02, ARSD 74:29:07:01, and ARSD 74:29:07:19. The choice of reclamation for the Permit Amendment areas is Wildlife habitat. This reclamation plan was approved by the board under the original Mine Permit #008. The Amendment areas at Milbank #2, Milbank #1 and Milbank Shop are all covered under the original Permit. In the original Mine Permit Area #008 application, Wildlife habitat is listed as the post mine land use in section 37, page 90. This should cover the permit amendment area since it is all in the original permit area.

- 9. 45-6B-46 See Item #12 above.
- 7) See above Item#13 (4) (6) (4) page 6-7.
- 8) See above item #5 Page 1.
- 9) In the Permit Amendment areas there will be no proposed reservoirs, tailings ponds, disposal site, dams, dikes and diversion canals. The baseline water quality and water level of all the areas was completed during the original Permit #008 process.
- 5) 45-6B-8 Previously Mined Land-Surface Mines
  Milbank #2 and Milbank Shop Permit Amendment areas
  are on land that has not been previously mined. Milbank
  #1 area is the reclamation of a Pre-1971 Grout Pile.
- 6) 45-6B-9 Previously Mined Land—Reclamation not required for underground mining. No underground mining has taken place on any of the Permit Amendment areas.
- 7) 45-6B-10 Map of Affected Area An accurate map of the affected areas has been completed. See Milbank #1, Milbank #2, and Milbank Shop Permit Amendment maps.
- 8) 45-6B-14 Fee for Application
  The Permit Amendment fee of \$1,000 is enclosed with the permit amendment application.
- 9) 74:29:03:05(1) Copy of application filed with department and register of deeds. A copy of the permit application has been submitted to Grant County Register of Deeds Office. A letter from the register of deeds, will be submitted for proof to the Mine office.
- 10) 45-6B-32 Grant of permit application in compliance with law—Grounds for denial See number 14 below.
- 11) <u>45-6B-33 Unsuitable land-No Permit issued</u> See number 14 below.
- 12) 45-6B-33.1 Socioeconomic Impact Study
  The original permit #008 had no socioeconomic impacts
  on the surrounding areas and the permit amendment
  areas should have similar impacts.
  - Population Base; Milbank #2, Milbank #1, and Milbank Shop Amendment areas have no homes on site that will be affected and will have minimal impacts on adjacent properties.
  - 2) Employment and Income; Milbank #1 and Milbank shop Amendment areas will not have any impact on employment or income. Milbank #2 permit

- amendment might increase employment and income for Fisher's and Cold Spring Granite Co. which will increase income for the county.
- 3) Tax base; Milbank #1 and Milbank shop will not have any impact the tax base. Milbank #2 might increase employment and income for Fisher's and Cold Spring Granite Co. which will increase tax base for the county.
- 4) Housing; Milbank #2, Milbank #1, and Milbank Shop Amendment areas will have no homes on site.
- 5) Community; Milbank #2, Milbank #1, and Milbank Shop Permit Amendment areas will have no effect on Community services.
- 6) Recreational opportunities; Milbank #2 and Milbank Shop permit amendment areas were farm fields before this amendment and will have no effect on recreation. Milbank #1 Permit Amendment area is in the affected area of the current permit so no recreational opportunities are permitted.
- 14. <u>SDCL 45-6B-7(9)</u>, <u>ARSD 74:29:02:07</u>, <u>ARSD 74:29:02:11</u>, and <u>ARSD 74:29:07:08</u> See Above Item #13 (4) (6) (5).
- SDCL 45-6B-32 and 33 Please address each section of these statutes for the permit amendment area.
  - 45-6B-32. Grant of permit if application in compliance with law--Grounds for denial.
    - The Application is incomplete or the surety has not been posted: The mine permit amendment application and the \$1,000 permit amendment fee have been submitted.
    - 2) The applicant has not paid the required fee; The mine permit amendment application and the \$1,000 permit amendment fee have been submitted.
    - 3) Any part of the proposed mining operation, the reclamation program, or the proposed future use is contrary to the laws or regulation of this state or the United States; Nothing in the new Permit Amendment areas are contrary to the rules and/or regulations.
    - 4) The mining operation will adversely affect the stability of any significant, valuable, and permanent man-made structures located with 200 ft. of the affected land. There are no structures within 200 ft. of the permit amendment areas that are not owned by the owner of the mine.
    - 5) The mining operation would be in violation of any county zoning or subdivisions regulations; The permit amendment areas are not in violation of and county ordinances.

- 6) The proposed mining operation and reclamation cannot be carried out in conformance with the requirements of 45-6B-35 Mining Operations—Applicable law. The permit amendment areas will be reclaimed to the standards listed under SDCL 45-6B-37 to 45.
- 7) The operator is currently found to be in violation of the provisions of this chapter with respect to any mining operation in this state: The current operator has not been found in violation of provisions of this chapter with respect to any mining operation in this state.
  - 45-6B-33. Unsuitable land--No permit issued. No permit may be issued for a mining operation proposed on unsuitable land. Land is unsuitable if the following conditions cannot be satisfactorily mitigated:
  - 1) The Permit Amendment areas can be reclaimed and it is economically and physically feasible.
  - 2) Milbank Shop permit amendment area has a tributary to the North Fork of the Yellow Bank River to the northeast of the affected area. Silt fence will be used to prevent sediment runoff to the tributary and the SWPPP will implement best management practices.
  - 3) The land in the Permit Amendment areas that are going to be affected are not special, exceptional, critical or unique as defined. These areas are in Permit Area #008 which in the original permit was not considered critical.
  - 4) None of the Permit amendment areas will affect the aquifer, wells, or other watershed lands because disturbances will be limited to surface disturbance only with no new quarries.
  - 5) The Permit amendment areas are not biological productive land. Milbank #2 and Milbank Shop locations are both in farm fields. Milbank #1 area is in an already affected area and an old grout pile. Also, no threatened or endangered species are located in these areas. The original wildlife survey in Mine Permit #008 found no threatened or endangered species.
  - 6) No adverse socioeconomic impacts of the proposed mining operations were found in the original permit #008. The area in Milbank #1 was an area already in operation and an old grout pile that removing will only improve the landscape. Milbank #2 and the Milbank Shop are in farms fields that have little socioeconomic impacts on the community.

- 16. <u>SDCL 45-6B-44</u>, <u>SDCL 45-6B-45</u>, <u>ARSD 74:29:06:02</u>, <u>ARSD 74:29:07:01</u>, <u>and ARSD 74:29:07:19</u> See above on page 8, item 13(4)(6)(9).
- 17. <u>ARSD 74:29:07:02</u> Minimizing of adverse Impacts. To minimize the adverse impacts of a mining operation, the following must be considered during the mine planning process:
  - 1) Design of mine operation facilities to minimize surface disturbances; In Milbank #2 permit amendment area the area of disturbance has been address in earlier sections of this application and the maps that have been included. No surface disturbance will happen out of the already discussed areas. The same goes for the block storage area of Milbank Shop. At the Milbank #1 Pre-1971 piles there is only granite removal and no permanent facilities.
  - 2) Construction of mine facilities so that affected lands are cleared in small sections or increments to match the needs of mine production; In the Milbank #2 expansion area, the growth of the crushing area will move slowly at the start as they develop into the pile. As Fishers move their whole operation from their current location to Milbank #2 the topsoil will be removed as the crushing area and piles expand. The overburden stockpile can be used in the early development of the crushing pad. After the initial crushing area is established, the overburden stockpile can have the slopes stabilized and seeded. The Milbank Shop permit amendment area will only expand as needed for block storage. The areas close to the shop will be the first to have the top soil removed and moved to Milbank #2. Milbank #1 will have no additional areas cleared.
  - 3) Visual Screening of affected lands, including pits, dumps, impoundments, process facilities, building, and equipment; The area to the north of Milbank #2 already has a tree line along the road to provide visual screening. This tree line and the current Milbank #2 quarry block all views of the overburden stockpile from the public. The


- north and west side view of overburden stockpile is open farm field with no view of the general public. The area by the Milbank Shop is block storage which is already being done around the Milbank shop. The Milbank #1 grout pile removal is far off the road and cannot be seen.
- 4) Design, construction, and location of mine facilities to minimize impacts to surface water and ground water; The Milbank #2 area is going to remove topsoil which will not be deep enough to affect ground water. The overburden stockpile will be sloped and seeded to prevent any erosion that might flow to surface waters and is in the Current Storm Water Pollution Prevention Plan. This plan assures that all storm water runoff goes through Best Management practices to limit surface water pollution. The Milbank Shop area is block storage and only the topsoil will be removed; no surface or ground water will be affected. The Silt Fence and SWPPP will assure that no run-off will make it to the Tributary to the North Fork of the Yellow Bank River. The removal of the Pre-1971 grout piles has been in progress and have not affected ground water or surface waters.
- Control of Access; All three of the access points to the locations have gates to limit access.
- 6) Preventive measures to minimize impacts to wildlife; The Milbank #1 area is already in an affected area so no wildlife will be affected. Milbank Shop area and Milbank #2 area are both farm fields which is not considered wildlife habitat. In the original Mine Permit #008 all these areas were surveyed for threatened or endangered species to which, none were found.
- 7) Location of waste dumps, spoils piles and topsoil stockpiles to facilitate implementation of reclamation and minimize environmental impacts; The overburden pile is marked on the maps and will be sloped to minimize environmental impacts. The topsoil stockpiles in Milbank #2 are located on Milbank #2 Permit Amendment Map.

- The impacts on the environmental are minimal and monitored by the SWPPP. Since the Milbank Shop and Milbank #1 areas do not have any of the stockpiles, no environmental impacts will happen.
- 8) Minimizing the production of mine waste and spoil;
  Milbank #2 and Milbank #1 areas are actually removing
  mine waste and cleaning up old grout piles so no mine
  waste will be produced. The current overburden stockpile
  is already located on Milbank #2 and will not have
  additional waste added to the pile. Milbank shop #1 is
  block storage so no mine waste is produced.
- 9) Design and location of facilities so they are compatible with surrounding land uses: All 3 of the locations are right next to, or in current granite mining operations so, they are compatible with the surrounding land uses. The overburden stockpile will be next to a large grout pile so; it is compatible with the surrounding land use of stockpile.
- 10) Integration of mine operations planning with the reclamation plan. Milbank #1 Pre-1971 Grout pile cleanup is part of the reclamation process and will be finished in the next few years. This area will be graded and leveled after all the granite is removed. Topsoil will be brought in and spread at a 1 ft. layer, it will then be seeded with the approved seed mix to prevent erosion. Milbank Shop area is block storage so the reclamation will take place when the block storage is no longer needed. This reclamation will start when blocks are removed; fill and topsoil will be brought in and graded to match the surrounding fields. This area will then be seeded with the approved seed mix. Milbank #2 has the Topsoil being in a berm around the property so, when reclamation starts the topsoil will be in place to cover the site. As the Crushing piles are removed reclamation will take place and whatever is left will be used to fill in any uneven areas. If more fill is needed it will be taken from the overburden pile. After the whole site is graded to match the

surrounding fields, topsoil will be spread and seeded to control erosion. Whatever is left of the overburden stockpile after reclamation of the areas, will be sloped to a 4 to 1 ratio and seeded to prevent erosion.


- 18. <u>SDCL 45-6B-37</u>, <u>ARSD 74:29:07:03</u>, <u>and ARSD 74:29:07:04</u> See above page 5, 13 (4) (6) (1).
- 19. <u>SDCL 45-6B-38 and ARSD 74:29:07:13:</u> See above page 5, 13 (4)(6)(2).
- 20. <u>SDCL 45-6B-39</u>, <u>ARSD 74:29:02:10</u>, <u>and ARSD 74:29:07:06</u> See above page 6, 13 (4) (6) (3).
- 21. <u>SDCL 45-6B-40 and ARSD 74:29:07:07:</u> See above page 6, 13 (4) (6) (4).
- 22. <u>SDCL 45-6B-41, ARSD 74:29:07:09, and ARSD 74:29:07:10</u> See above page 7 Item #13 (4) (6) (5).
- 23. ARSD 74:29:07:11 and ARSD 74:29:07:27 There are no plans to construct water impoundments in the amendment area. Fishers plans on using an old quarry hole in the area for the wash plant dust suppression.
- 24. ARSD 74:29:07:12 Roads will not be constructed in the amendment areas.
- 25. <u>SDCL 45-6B-43 and ARSD 74:29:07:14:</u> See above page 7-8, item #13 (4) (6) (7).
- 26. <u>ARSD 74:29:07:15</u> See above page 7-8, Item 13 (4) (6) (7).
- 27. <u>SDCL 45-6B-42 and ARSD 74:29:07:16</u> See above page 7 Item #13 (4) (6) (6).
- 28. <u>SDCL 45-6B-8, SDCL 45-6B-9, and ARSD 74:29:07:17</u> There are no underground or pre-1971 mining areas within the amendment area. Pre-1971 grout piles at Milbank #1 are currently being reclaimed.
- 29. ARSD 74:29:07:18 The person that developed the reclamation plan for the permit amendment area used the same plan from the Original Permit Area #008 plan. This person adjusted this plan for the three Permit Amendment areas. The person developing the plan is an Environmental Engineer and is competent in the management of the post mine land use of wildlife habitat.
- 30. ARSD 74:29:08 The Milbank #2 Permit amendment area is concurrent with the reclamation and will go along with the crushing operation. As the crushing operation moves into the pile, the


crushing piles will also move closer to crusher so the outer edges will be reclaimed first. The crushing pad will be leveled as area is not needed and the overburden pile will be used to fill in unleveled areas. The topsoil will then be spread over the rest of the completed area and seeded with approved seed mix. Whatever is left of the overburden pile will be sloped to a 4 to 1 ratio and then seeded with approved mix. The topsoil berms around this area will be rounded and leveled smooth with a dozer. The seeding will be completed with a quick cover seed mix immediately after completion of the berms, which will help prevent erosion. The dimensions of the stockpile can be seen on Milbank #2 Amendment Topsoil Cross Section Map. The Milbank shop area reclamation will be done as block storage and as area is not needed, topsoil will be spread and then it will be seeded. Milbank #1 permit amendment area Pre-1971 grout piles will be reclaimed as soon as they are clear of grout. If one is cleaned up first, it will immediately start to be reclaimed. The area will be leveled with fines from the crushing area to fill any uneven areas. Topsoil will then be spread and immediately seeded with an approved seed mix from Grant county.






















### RECEIVED APR 08 2022

MINERALS & MINING PROGRAM

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY	
Complete items 1, 2, and 3.  Print your name and address on the reverse so that we can return the card to you.  Attach this card to the back of the mailpiece, or on the front if space permits.  Article Addressed to:  Rebecca Wellnitz  Crant County Register of Deeds  210 E 5th Avenue	A. Signature  X	
Milbank, 50 57252 9590 9402 5885 0038 9852 45 2. Article Number (Transfer from service label) 7016 0340 0000 7693 8387	3. Service Type  ☐ Adult Signature ☐ Adult Signature Restricted Delivery ☐ Certified Mail® ☐ Certified Mail® ☐ Collect on Delivery ☐ Collect on Delivery ☐ Collect on Delivery ☐ Insured Mail ☐ Insured Mail ☐ Insured Mail Restricted Delivery ☐ Cover \$500) ☐ Priority Mail Express® ☐ Registered Mail™ ☐ Registered Mail™ ☐ Registered Mail™ ☐ Restricted Delivery ☐ Return Receipt for Merchandise ☐ Signature Confirmation™ ☐ Signature Confirmation ☐ Restricted Delivery ☐ Cover \$500)	
PS Form 3811, July 2015 PSIN 7530-02-000-5000	Domestic Return Receipt	

### **GRANT COUNTY**



### OFFICE OF REGISTER OF DEEDS

210 East 5<sup>th</sup> Avenue Milbank, SD 57252 Phone: 605-432-4752

APR 0 6 2022

MINERALS & MINING PROGRAM

April 4, 2022

Attn: Steve Chouanard

Environmental Engineer

Cold Spring Granite Co

17482 Granite West Rd

Cold Spring MN 56320

Dear Steve.

The Cold Spring Granite Company copy of Amendment to Mining/Milling Permit No. 008 application has been placed in the Grant County Register of Deeds Office, Grant County, South Dakota for public view.

Sincerely,

Rebecca Wellnitz

Grant County Register of Deeds

U.S. Postal Service™ CERTIFIED MAIL® RECEIPT Domestic Mail Only	U.S. Postal Service™ CERTIFIED MAIL® RECEIPT Domestic Mail Only
For delivery information, visit our website at www.usps.com*.  Certified Add Fee  Starta Services & Fees (check box, add fee as appropriate)  Return Receipt (prardcopy)  Return Receipt (prardcopy)	For delivery information, visit our website at www.usps.com*.  Dermind Mail Fee  Extra Services & Fees (check box, add fee as appropriate)  Return Receipt (hardcopy)  Return Receipt (electronic)  Cartified Mail Restricted Delivery  Adult Signature Required  Adult Signature Restricted Delivery \$  Total Postage  Total Postage and Fees  Sent To  Sireet and Apt. No., or PO Box No.  40  City, State, April 2015 Mar. 1630-06 200 2007  See Reverse for instruction
U.S. Postal Service CERTIFIED MAIL® RECEIPT  Domestic Mail Only  For delivery information, visit our website at www.usps.com®.  Certified Mail Fee  \$ Extra Services & Fees (check box, add fee as appropriate)    Return Receipt (electronic)   Postmain Here   Adult Signature Restricted Delivery   Here   Adult Signature Restricted Delivery   Postage  Total Postage and Fees  \$ Sept To  Street and Apt. No., of FO Box No.  City, State, 2/P+4*  City, State, 2/P+4*  See Reverse for Instructions	U.S. Postal Service  CERTIFIED MAIL® RECEIPT  Domestic Mail Only  For delivery information, visit our website at www.usps.com®.  Certified Mail Fee  Statra Services & Fees (check box, add fee as appropriate)  Return Receipt (electronic)  Return Rec

8734	U.S. Postal Service™  CERTIFIED MAIL® RECEIPT  Domestic Mail Only		
40	For delivery information, visit our website at www.usps.com <sup>b</sup> .		
+D 0000 7693	Certified Mail Fee  \$ Extra Services & Fees (check box, add fee as appropriate)    Return Receipt (hardcopy)		
0340	S Total Postage and Fees		
7076	Dutail W & Dyg vely R More 95 90 00 161-4 57.  161-4 57.  161-4 57.  161-5 57		



8769	U.S. Postal Service™ CERTIFIED MAIL® RECEIPT  Domestic Mail Only	
-	For delivery information, visit our website at www.usps.com*.	
7693	Certified Mail Fee	
7	\$ Extra Services & Fees (cheek has add)	
0000	Extra Services & Fees (check box, add fee as appropriate)   Return Receipt (electronic) \$   Return Receipt (electronic) \$   Certified Mail Restricted Delivery \$   Adult Signature Restricted Delivery \$   Adult Signature Restricted Delivery \$	
0340	Postage \$ Total Postage and Fees 56320	
7076	Sent To Stryn Michals - Repartment or Gume, Fith Ant	

52	U.S. Postal Service™ CERTIFIED MAIL® RECEIPT  Domestic Mail Only	
87	For delivery information, visit our website at www.usps.com*.	
0000 7693	Certified Mail Fee  \$ Extra Services & Fees (check box, add fee as appropriate)    Return Receipt (hardcopy)	
0460	Adult Signature Restricted Delivery \$ Postage \$ Total Postage and Fees	/
75	Septell The least - Board new - F Health	

U.S. Postal Service™  CERTIFIED MAIL® RECEIPT  Domestic Mail Only	U.S. Postal Service <sup>™</sup> CERTIFIED MAIL® RECEIPT Domestic Mail Only
For delivery information, visit our website at www.usps.com*.  Extra Services & Fees (check box, add fee as appropriate)    Return Receipt (furdocopy)   8   Raturn Receipt (furdocopy)   8   Add Signature Required   9   Add Signature Required   \$   Add Signature Restricted Delivery   8   Postage   9   Postage   9   Street and Apr. No., or PO Box   9   City, State, 2/Pu   9   City, State,	For delivery information, visit our website at www.usps.com  Certified Mail Fee  \$ Extra Services & Fees (check box, add fee as appropriate)  Return Receipt (electronic)  Return Receipt (electronic)  Adult Signature Required  Adult Signature Required  Adult Signature Restricted Delivery \$  Postnark  Services and April 2015 April 2015 April 2015  Street and April 2015 April 2015 April 2015  Street and April 2015 April 2015 April 2015  Street and April 2015 April 2015 April 2015  See Neverse for Institute Institu

8677	U.S. Postal Service <sup>TM</sup> CERTIFIED MAIL® RECEIPT Domestic Mail Only For delivery information, visit our website at www.usps.com*.
7016 0340 0000 7693	Certified Maif Fee \$ Extra Services & Fees (check box, add fee as appropriate)   Potum Receipt (electronic)   S     Certified Mail Restricted Delivery   Adult Signature Restricted Delivery   Adult Signature Restricted Delivery   Postage   Adult Signature Restricted Delivery   Postage     STOIL Postage and Fees   Stoil Postage and Fees   Soil No.   City, State, 2(P-14)   Adult Signature Restricted Delivery   Soil Si

### APR 0 6 2022

MINERALS & MINING PROGRAM

U.S. Postal Service™ CERTIFIED MAIL® RECEIPT  Domestic Mail Only	U.S. Postal Service™ CERTIFIED MAIL® RECEIPT Domestic Mail Only
For delivery information, visit our website at www.usps.com <sup>®</sup> .  Certified Mai Fee    Stra Services & Fées (check box, add fee as appropriate)     Return Receipt (hardcopy)   \$   Return Receipt (electronic)   \$   Certified Mail Restricted Delivery   \$   Adult Signature Required   \$   Adult Signature Restricted Delivery   \$   Postage       Postage       Spit To       Signature Restricted Delivery   \$   Postage       Spit To       Signature Restricted Delivery   \$   Postage       Spit To       Signature Restricted Delivery   \$   Postage       Spit To       S	For delivery information, visit our website at www.usps.com®.  Certified Mall Fee  Extra Services & Fees (check box, add fee as appropriate)  Return Receipt (fardicopy)  Return Receipt (electronic)  Certified Mail Restricted Delivery \$  Adult Signature Required  Adult Signature Restricted Delivery \$  Postage  Total Postage and Fees  Sent To  Vicinity State 2/P4.48  City, State 2/P4.48  See Reverse tor Instructions

87	U.S. Postal Service <sup>™</sup> CERTIFIED MAIL® RECEIPT  Domestic Mail Only
637	For delivery information, visit our website at www.usps.com®.
	, visit du Website at Www.usps.com*.
E	Certified Mail Fee
719	\$
	Extra Services & Fees (check Imple as appropriate)  Return Receipt (hardcopy)
	Pring and
0000	Return Receipt (electronic)   Certified Mail Restricted Delivity   State   Adult Signature Required   State   State
	Adult Signature Restricted Dell ery \$
0340	Postage
m	Total Postage and Fees
	s
1	Sent To
7076	Re becan Wellwitz Strant County
1-	210 E Sth Avenue
	milbunk, SO STASTA
F	PS Form 3800, April 2015 PSN 732-02-000-0017 See Reverse for Instructions

Domestic Return Receipt

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY		
■ Complete items 1, 2, and 3.  ■ Print your name and address on the reverse so that we can return the card to you.  ■ Attach this card to the back of the mailpiece, or on the front if space permits.  1. Article Addressed to:  Dukoth Ganite Co.  48391 Isom St.  Milbant, SD 87252	A. Signature  X. H.M. RODIC-19		
9590 9402 4123 8092 0172 92  2. Article Number (Transfer from service label)	3. Service Type  ☐ Adult Signature ☐ Adult Signature Restricted Delivery ☐ Certified Mail® ☐ Certified Mail Restricted Delivery ☐ Collect on Delivery ☐ Collect on Delivery Restricted Delivery ☐ Insured Mail		
2016 0340 0000 7693 8660	Insured Mail Restricted Delivery Restricted Delivery		

PS Form 3811, July 2015 PSN 7530-02-000-9053

			Diller C. Charles C. Marchael C. Company and C. Company
SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY	SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
Complete items 1, 2, and 3.  Print your name and address on the reverse so that we can return the card to you.  Attach this card to the back of the mailpiece, or on the front if space permits.  Anicle Addressed to:  Kory Kezu - Pitt.:+  Conservation:#  1102 Saukohu St. SR2	A. Signature  X. A. Signature  X. A. Signature  X. A. Signature  X. A. Signature  Addresse  G. Date of Delivery  County of the Sen 12 graph  D. Is delivery address different from item 12 graph  If YES, enter delivery address below:	Complete items 1, 2, and 3.  Print your name and address on the reverse so that we can return the card to you.  Attach this card to the back of the mailplece, or on the front if space permits.  Article Addressed to:  Bill ChalCruft  Pepu tment of Heulth  600 Enst Capital Annue	A Signature  X
9590 9402 5885 0038 9852 07  2. Article Number (Transfer from service label)  PD16 0340 0000 7693 6776  S Form 3811, July 2015 PSN 7530-02-000-9053	3. Service Type  Adult Signature Restricted Delivery Cortified Mail Serviced Delivery Collect on Delivery Restricted Delivery Collect on Delivery Collect on Delivery Restricted Delivery Collect on Delivery	Pierre, SD 57501	3. Service Type Adult Signature Adult Signature Adult Signature Restricted Delivery Certified Mail Restricted Delivery Collect on Delivery Restricted Delivery Collect on Delivery Restricted Delivery Insured Mail Restricted Delivery Insured Mail Restricted Delivery Insured Mail Restricted Delivery Insured Mail Restricted Delivery Domestic Return Receipt  Domestic Return Receipt
S FORM 3011, July 2013 PSN 7330-02-000-500	- 1	PS Folin GOT 1, day 2010 to 1.	700
SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY		COMPLETE THIS SECTION ON DELIVERY
Complete items 1, 2, and 3.  Print your name and address on the reverse so that we can return the card to you.  Attach this card to the back of the mailpiece, or on the front if space permits.  I. Anticle Addressed to:  Steve Berkner  Planning and Zaning  Hole Sth Ave.  hil bunk, Sp 57052	A. Signature  X. TL. C-2 C-12 ☐ Agent ☐ Addressee  B. Received by (Printed Name) ☐ L. C-2 C-19 ☐ Q. Date of Delivery ☐ L. C-2 C-19 ☐ Q. Date of Delivery ☐ L. St. Selivery eddress different from Item 1? ☐ Yes If YES, enter delivery address below: ☐ No	SENDER: COMPLETE THIS SECTION  Complete Items 1, 2, and 3.  Print your name and address on the reverse so that we can return the card to you.  Attach this card to the back of the mallplece, or on the front if space permits.  Article Addressed to:  HIND Michals  Deput ment of Gumey Fish, and  U130 Adventure Truit Parky	A Signature  Agent Addressee  B. Received by (Printer Name)  D. Its delivery address different from Item 1?  If YES, enter delivery address below:  No
9590 9402 5885 0038 9851 84  2. Article Number (Transfer from service label)  1016 0340 0000 7693 8738  2. Form 3811, July 2015 PSN 7530-02-000-9063	3. Service Type  Adult Signature  Adult Signature Restricted Delivery Certified Mail Restricted Delivery Collect on Delivery Pleatneted Delivery Dollect on Delivery Pleatneted Delivery Insured Mail Insured Mail Insured Mail Cover \$500)  Domestic Return Receipt  Domestic Return Receipt  Domestic Return Receipt	9590 9402 5885 0038 9852 14  2. Article Number (Transfer from service label)  7016 0340 0000 7693 8769	S. Service Type
The state of the s		PS Form 3811, July 2015 PSN 7530-02-000-9053	The state of the s

SENDED	COMP	ETE THIS	SECTION

- Complete items 1, 2, and 3.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.
- Article Addressed to:

David W& Jacquelyn R Meyer 17991 15tst. St. Milbank, 50 57744

9590 9402 4123 8092 0172 23

2. Article Number (Transfer from ser 016 0340 0000 7693 8714

PS Form 3811, July 2015 PSN 7530-02-000-9053

COMPLETE THIS SECTION ON DELIVERY A. Signature ☐ Agent Addressee

land XA B. Received by (Printed Name) David Meyer

C. Date of Delivery 4-2-22

- D. Is delivery address different from item 1? Yes If YES, enter delivery address below:
- 3. Service Type
- Adult Signature
  Adult Signature Restricted Delivery
  Certified Mail®
  Certified Mail Restricted Delivery
- Collect on Delivery
  Collect on Delivery Restricted Delivery
- ☐ Insured Mail ☐ Insured Mail Restricted Delivery (over \$500)
- Priority Mail Express®
  Registered Mail™
  Registered Mail Restricte
  Delivery
  Return Receipt for
  Merchandise
  Signature Confirmation
  Signature Confirmation
  Restricted Delivery

Domestic Return Receipt

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailplece, or on the front if space permits.
- 1. Article Addressed to:

Robert H& Lisa Hinters 14921 485Th Ave. Milbank, Sh 87252

9590 9402 4123 8092 0171 93

2. Article Number (Transfer from service label)

7016 0340 0000 7693 8677

PS Form 3811, July 2015 PSN 7530-02-000-9053

COMPLETE THIS SECTION ON DELIVERY

x Re 16 leder

Agent Addressee
C. Date of Delivery

B. Received by (Printed Name) Robert # Hinders

Is delivery address different from item 1?

If YES, enter delivery address below:

- . Service Type
  Adult Signature
  Adult Signature Restricted Delivery
  Certified Mell's Restricted Delivery
  Certified Mell's Restricted Delivery
  Collect on Delivery
  Collect on Delivery
  Insured Mell
  Insured Mell Pestricted Delivery
  (over \$500)

- Priority Mail Express®
  Registered Mail™
  Registered Mail Mail™
  Registered Mail Restricted
  Delivery
  Return Receipt for
  Merchandier
  Signature Confirmation™
  Signature Confirmation
  Restricted Delivery

Domestic Return Receipt



Domestic Return Receipt

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON D	ELIVERY
■ Complete items 1, 2, and 3.  ■ Print your name and address on the reverse so that we can return the card to you.  ■ Attach this card to the back of the mailpiece, or on the front if space permits.  1. Article Addressed to:  Robert Angerhafer  48616 150 5t.  Biy Stone City, SD 57216	A. Signature  X	
9590 9402 4123 8092 0172 16	☐ Adult Signature ☐ Adult Signature Restricted Delivery ☐ Certified Mail® ☐ Certified Mail Restricted Delivery ☐ Collect on Delivery	☐ Priority Mail Express® ☐ Registered Mail™ ☐ Registered Mail Restricter ☐ Delivery ☐ Return Receipt for ☐ Merchandise
Article Number (Transfer from service label)	☐ Collect on Delivery Restricted Delivery ☐ Insured Mail	☐ Signature Confirmation™☐ Signature Confirmation
7016 0340 0000 7693 8691	Insured Mail Restricted Delivery	Restricted Delivery

PS Form 3811, July 2015 PSN 7530-02-000-9053