

Examples of Bus Disposal Pictures

Photo #1: Side profile of bus being scrapped



Photo #2: VIN of the bus being scrapped




Photo #3: Engine tag with engine serial number and EPA engine family name



Photo #4: Chassis rail cut in half



Photo #5: Engine block prior to hole being drilled




Photo #6: Engine block after hole has been drilled

