South Dakota Spill Report Form

PRCF #: **Case #:** 2025.007

Reported (MM/DD/YY): 1/19/25	Time: 1:18 PM CST	Recorded By: J. McGuire

A. REPORTER

Reported By: Dar Coy

Organization Name: Fall River EM — ☐ Discharger ☐ Public ☐ State ☑ Local ☐ Federal

Phone: — Email:

Address:

City: — State: — Zip:

B. DISCHARGER (Responsible Party) ☐ As Above in A

Name: New Prime Inc.

Address: 2740 North Mayfair

City: Springfield — State: MO — Zip: 65803

Phone: 800-491-1253 — Email:

C. INCIDENT DATE & LOCATION ☐ As Above In B

Spill Date: (MM/DD/YY) 1/19/25 — Spill Time: 12:19 PM CST

Street or Approx. Location: approx: 13066 Fall River Road, 43.413341, -103.447083

Survey Description:

City: Hot Springs — County: Fall River — State: SD — Zip: 57747

D. MATERIAL

Material type (Code/Name): ☑ Hazardous Substance ☐ Oil ☐ Material Unknown ☐ Other

Material	Quantity Spilled	Spilled in Water	Units (Check one)	
Diesel	75		☐ lb. ☐ bbl.	☑ gal. ☐ oth.
			☐ lb. ☐ bbl.	☐ gal. ☐ oth.
			☐ lb. ☐ bbl.	☐ gal. ☐ oth.

E. SOURCE

Source of Spill: ☐ AST ☐ UST ☐ Railway ☑ Transport ☐ Fixed Facility ☐ Pipeline ☐ Highway ☐ Other

Description: Saddle Tanks

Regulated Tank Facility: ☐ Tank Facility ID #:

F. MEDIUM

Medium Affected: ☐ Air ☑ Land ☐ Water ☐ Groundwater ☐ Within Facilities Only

Waterway Affected: n/a

G. CAUSE

Reported Cause: ☑ Transportation Accident ☐ Operational Error ☐ Dumping ☐ Equipment Failure ☐ Natural Phenomenon ☐ Unknown ☐ Other

Description: 2 vehicle collision.

H. DAMAGES

# of Injuries: 1 — # of Fatalities:

I. ACTIONS

Response Action Taken:

Granular absorbent was put down by first responders. The DOT was planning on putting down sand on the road for remaining contamination.

K. NOTIFIED

Responding Agency: ☐ DANR ☑ Local ☐ Discharger ☐ Federal ☐ EPA ☐ Other

Agencies Notified: DANR

K. COMMENTS

Comments:

Sweeper out of Edgemont was planning on picking up the absorbents on the road.

Department of Agriculture and Natural Resources
Inspection, Compliance, and Remediation Program
523 East Capitol Avenue
Pierre, South Dakota 57501

Business Hours M – F 8:00-5:00 pm
Normal Business Hours- (605)773-3296
After Business Hours- (605) 773-3231

DEPARTMENT of AGRICULTURE and NATURAL RESOURCES
JOE FOSS BUILDING
523 E CAPITOL AVE
PIERRE SD 57501-3182
danr.sd.gov

Dave White
New Prime, Inc.
2740 North Mayfair Avenue
Springfield, MO 65803

January 28, 2025

Subject: Department of Agriculture and Natural Resources File Number 2025.007: pertaining to a diesel release on Highway 18, mm 41, near Hot Springs, SD.

Dear Mr. White:

The Department of Agriculture and Natural Resources (DANR) is contacting you regarding the event noted above. A copy of the initial spill report form is enclosed for your review. Based upon the information provided, a New Prime truck and another vehicle were involved in a transportation accident that resulted in an estimated 75 gallons of diesel released on the roadway and into the southern ditch. DANR is naming the owner of the spilled fuel as responsible for any necessary cleanup or assessment. The local fire department applied Floor Dry to absorb the fuel and a Department of Transportation sweeper cleaned up the impacted Floor Dry on the road. In this instance, DANR requires the following:

- Hire an environmental consultant certified to perform petroleum remediation in South Dakota to oversee and direct the cleanup;
- Excavate contaminated soil. Properly dispose of soil and used absorbents at a permitted municipal solid waste landfill;
- Backfill the area with clean soil and reseed according to SD Department of Transportation standards;
- Provide this office with a copy of disposal receipts and cleanup pictures; and
- By March 1, 2025, please complete and return the enclosed Written Contamination Incident Follow Up Report form (this is a standard form so you can skip the questions that do not apply to your situation).

Jaclyn McGuire has been assigned as the project manager for this case. If you have any questions or need additional information, please do not hesitate to contact her at 605.773.3296. Thank you for your cooperation and assistance.

Sincerely,

Trish Kindt
Inspection, Compliance, & Remediation Program
(605) 773-3296

cc Dar Coy, Fall River County Emergency Manager
Bruce Schroeder, SD DOT Custer Area Engineer

INCIDENT FOLLOW-UP REPORT

DANR CASE FILE #: 2025.007

RETURN COMPLETED FORM TO:

SOUTH DAKOTA DEPARTMENT OF AGRICULTURE AND NATURAL RESOURCES (DANR)
INSPECTION, COMPLIANCE, AND REMEDIATION PROGRAM
JOE FOSS BUILDING
523 EAST CAPITOL AVENUE
PIERRE SD 57501-3182

NAME/TYPE OF PRODUCT SPILLED: Diesel, Motor Oil

TOTAL AMOUNT OF PRODUCT SPILLED: 50 gallons of diesel, 10 gallons of oil

POUNDS OF ACTIVE INGREDIENT SPILLED (fertilizer/pesticide spills): N/A

AMOUNT OF PRODUCT RECOVERED: N/A

WAS SURFACE WATER OR GROUND WATER IMPACTED BY THE SPILL?: No

SPILL DATE: 1-29-25 DATE CLEANUP OCCURRED: TBD

SPILL LOCATION (physical address, directions, distance to nearest intersection or landmark, etc.):
Hwy 18 EB, Hot Springs, SD, 1.1 miles from Conoco

LATITUDE/LONGITUDE: 43.4131390 N, 103.4470792 W

LAND USE (Residential, Commercial, Agricultural, Industrial, Other – describe): State Highway Easement

RESPONSIBLE PARTY: Prime, Inc.

MAILING ADDRESS: 2740 N Mayfair Ave

CITY/STATE: Springfield, MO 65803 TELEPHONE NUMBER: 417-866-0001

PROPERTY OWNER: South Dakota Department of Transportation

MAILING ADDRESS: 700 E Broadway Ave

CITY/STATE: Pierre, SD 57501 TELEPHONE NUMBER: 605-773-3265

CONSULTANT / CLEANUP CONTRACTOR (if applicable): Environmental Works, Inc

MAILING ADDRESS 2770 Industrial Ln

CITY/STATE: Broomfield, CO 80020 TELEPHONE NUMBER: 630-542-2234

INSURANCE PROVIDER (if applicable): N/A

NAME OF INSURED:

POLICY NUMBER: CLAIM NUMBER:

MAILING ADDRESS:

CITY/STATE: TELEPHONE NUMBER:

INCIDENT FOLLOW-UP REPORT (Page 2 of 2)

DANR CASE FILE #: 2025.007

WAS SOIL EXCAVATED?: TBD DIMENSIONS OF EXCAVATION: 20x10 ft need to be excavated

CUBIC YARDS EXCAVATED: _____

DISPOSAL SITE (Name of Facility): _____

DISPOSAL DATE: _____ ***If soil was disposed, attach copies of disposal receipts***

FERTILIZER/PESTICIDE SPILLS ONLY

WAS CONTAMINATED SOIL/MATERIAL LAND APPLIED?: N/A

APPLICATION DATE _____ ***Requires DANR Pre-Approval***

WAS SPILL CONTAINED TO IMMEDIATE AREA?: Yes

DISTANCE TO AND NAME OF NEAREST SURFACE WATER (include currently dry perennial streams): 50 feet to Fall River

DISTANCE TO NEAREST WATER WELL (if applicable): N/A

OWNER OF NEAREST WATER WELL (if applicable): N/A

DESCRIBE RESPONSE ACTION AND ADDITIONAL WORK PLANNED:

Crew measured the perimeter of the area that needs to be excavated, used a hand shovel and determined that both releases exceeded a depth of at least 8 inches, polyethylene sheeting was placed over the impacted soil and was secured to the ground with stakes, petroleum absorbent boom was placed on the down slope edge of the impacted soil and it too was secured with stakes

Additional Work Planned: Excavate the impacted soil with either a skid steer or Guzzler and use hand shovels to remove the impacted material that's alongside the asphalt shoulder, transport the impacted soil in a roll-off box or the Guzzler to an approved disposal facilty, backfill the excavated area with soil and scatter native grass seed over the soil

FORM COMPLETED BY: Ian Weigel DATE: 2-26-25

E-MAIL ADDRESS: iweigel@environmentalworks.com

Original – DANR
Copy – Keep for your records.

08/14/2025

Subject: **Closure Report for Incident** 2025-007

Please find enclosed the "Project Summary" for the incident in Hot Springs, SD on January 27, 2025. Upon review, please provide a "No Further Action" or equivalent letter for the above incident. If you have any questions or need further information, please contact our office.

Sincerely,

Crystal Willis
Premium Environmental Services
812-853-2400

Environmental Works, Inc.

Premium Environmental Services,
5366 Vann Rd,
Newburgh, IN 47630
Attn: Chris Calvin

RE: 25-016-010370 Diesel Release

On February 18th, 2025, at approximately 0730 MST, Environmental Works, Inc. received an email from Chris Calvin. Mr. Calvin stated that a site assessment was needed in Hot Springs, SD. The following information was provided at the time of the request:

- Released Product: Diesel
- Amount Released: 50 Gallons
- Cause of Release: Ruptured Saddle Tank

Upon receipt of the request, the site assessment was scheduled for the following week in which Environmental Works, Inc. (EWI) coordinated the appropriate personnel and equipment to the project site. The following is the timeline of events that occurred during the response.

Wednesday, February 26th

0730hrs
EWI received an email from Mr. Calvin regarding a diesel release in Hot springs, SD. Mr. Calvin informed the project manager that approximately 50 gallons of diesel had impacted a soil shoulder and that a site assessment was required by the state before remediation could be completed. Personnel gathered the necessary supplies to access and secure the release and mobilized to the site.

1330hrs
EWI arrived on site, located the release and held a site-specific safety meeting. The crew observed a patch of dead grass on the shoulder of the highway impacting an area of twenty by eight feet. After completing the state 'Incident Follow-Up Report' the crew began to secure the release by first placing poly sheeting over the entirety of the impacted area and staked it into the ground. Absorbent boom was then placed on the downslope edge and that too was secured to the ground with stakes. PES was notified that EWI was ready to head off site in which they mobilized to a nearby hotel and then to a shop the following day.

Thursday, June 26th

0500hrs
EWI mobilized back to the site with a skid steer and mini excavator to complete the remediation.

1100hrs
The crew arrived on site, held a site-specific safety meeting and notified PES of their arrival. After confirming with 811 that the area to be excavated was clear of all utilities EWI had a side dump of back fill off loaded and began stockpiling the diesel impacted soil with the excavator. The skid steer was then used to load the impacted soil into the side dump. Once cleared by the on-site consultant that all of the impacted soil had been excavated, the crew began to back fill using the skid steer and proceeded to scatter a native seed mixture across the top of the excavated area. The equipment used on the remediation were loaded and PES was notified that the crew was ready to head off site in which they mobilized to a nearby hotel and then back to the Denver shop the following day.

Waste
All waste was taken off site and disposed of at the Waste Management DADS facility consisting of 20 tons of diesel impacted soil.

There is no further work required by Environmental Works, Inc. at this time. Environmental Works appreciates the opportunity to be of service. Should there be any additional questions, please contact Mr. Ian Weigel at (630)-542-223.

Best Regards,
Ian Weigel
Emergency Response Project Manager
Environmental Works, Inc.

Denver Arapahoe Disposal
3500 S Gun Club , PO Box 460397
Aurora, CO, 80018
Ph: (720) 876-2620

Reprint
Ticket# 4781886

Customer Name	ENVIRONMENTALWORKSINC ENVIRON	Carrier	Gonzalez Trucking		
Ticket Date	06/27/2025	Vehicle#	GON 3	Volume	
Payment Type	Credit Account	Container			
Manual Ticket#		Driver			
Hauling Ticket#		Check#			
Route		Billing #	0016722		
State Waste Code		Gen EPA ID	N/A		
Manifest	14123683	Grid			
Destination					
PO					
Profile	138848CO (PCS - DIESEL FUEL IMPACTED SOIL AND/OR DEBRIS CLEANUP)				
Generator	VARIOUS VARIOUS-VARIOUS VARIOUS VARIOUS VARIOUS				

	Time	Scale	Operator	Inbound		
In	06/27/2025 09:49:34	Scale 2	lfeusier		Gross	65900 lb
Out	06/27/2025 09:49:34		lfeusier		Tare	36100 lb
					Net	29800 lb
					Tons	14.90

Comments

PLEASE MAKE SURE YOUR TICKET IS CORRECT BEFORE SIGNING.

	Product	LD%	Qty	UOM	Rate	Fee	Amount	Origin
1	Cont Soil Pet-Tons	100	14.90	Tons				
2	ENERGY-Energy Surc	100		%				
3	WWM-P-Waste Water	100		%				

Total Fees
Total Ticket

Driver`s Signature

NON-HAZARDOUS MANIFEST

WASTE MANAGEMENT

NON-HAZARDOUS MANIFEST	1. Generator's US EPA ID No. NA	Manifest Doc No. NA	2. Page 1 of 1	
3. Generator's Mailing Address: Prime Inc. 2740 N Mayfair St Springfield, MO 65803	Generator's Site Address (If different than mailing): EB Fall River Rd, Hot Springs, SD 57747		A. Manifest Number WMNA	14123683
4. Generator's Phone			B. State Generator's ID	
5. Transporter 1 Company Name: Gonzalez Trucking #Gon3	6. US EPA ID Number		C. State Transporter's ID	
			D. Transporter's Phone	
7. Transporter 2 Company Name	8. US EPA ID Number		E. State Transporter's ID	
			F. Transporter's Phone	
9. Designated Facility Name and Site Address: WM - Denver Arapahoe Disposal Site 3500 S Gun Club Rd, Aurora, CO 80018	10. US EPA ID Number		G. State Facility ID	
			H. State Facility Phone	

GENERATOR

11. Description of Waste Materials	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.	I. Misc. Comments
a. Non RCRA Hazardous Solids (Diesel Impacted Soil) WM Profile # 1388480	1	SD	20	T	
b. WM Profile #			18	Yd.	
c. WM Profile #					
d. WM Profile #					

J. Additional Descriptions for Materials Listed Above
ACCT # CUST #
Environmental Works

K. Disposal Location
Cell 32 Level
Grid

15. Special Handling Instructions and Additional Information

Purchase Order # 250703 EMERGENCY CONTACT / PHONE NO : 1-800-424-9300 24HR TOLL FREE

16. GENERATOR'S CERTIFICATE:
I hereby certify that the above-described materials are not hazardous wastes as defined by CFR Part 261 or any applicable state law, have been fully and accurately described, classified and packaged and are in proper condition for transportation according to applicable regulations.

Printed Name	Signature "On behalf of" Prime Inc.	Month	Day	Year
Ian Weigel	Ian	6	26	25

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed Name	Signature	Month	Day	Year
Arturo Gonzalez	Arturo Gonzalez	6	26	25

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed Name	Signature	Month	Day	Year

FACILITY

19. Certificate of Final Treatment/Disposal
I certify, on behalf of the above listed treatment facility, that to the best of my knowledge, the above-described waste was managed in compliance with all applicable laws, regulations, permits and licenses on the dates listed above.

20. Facility Owner or Operator: Certification of receipt of non-hazardous materials covered by this manifest.

Printed Name	Signature	Month	Day	Year
L. Fewsiff	L. Fewsiff	6	27	25

White- TREATMENT, STORAGE, DISPOSAL FACILITY COPY
Pink- FACILITY USE ONLY
Blue- GENERATOR #2 COPY
Gold- TRANSPORTER #1 COPY
Yellow- GENERATOR #1 COPY

Environmental Works, Inc.

Diesel Release
25-016-010370
Hot Springs, South Dakota

Photo: 1 **Description:** Initial site conditions.	

Photo: 2 **Description:** Poly sheeting was secured over the impacted area.	

Environmental Works, Inc.

Photo: 3 **Description:** Absorbent boom was secured on the downslope edge.	

Photo: 4 **Description:** Post site conditions upon initial site visit.	

Photo: 5 **Description:** Initial site conditions upon returning to the site for excavation.	

Photo: 6 **Description:** Impacted soil was stockpiled using the mini-excavator.	

Environmental Works, Inc.

Photo: 7 **Description:** Impacted soil was disposed of into the side dump.	

Photo: 8 **Description:** Backfill soil was placed over the excavated area.	

Environmental Works, Inc.

Photo: 9 **Description:** Post site conditions.	

Photo: 10 **Description:** Post site conditions.	


FREIGHTLINER
RIME
633895


3000R
223060


PRIME inc.
633395


C23060
PRIME inc.