PHOTOGRAPH

The following photos were provided to DANR by AET



Photo 1:	**View of hospital pavement upgradient toward dumpster.**
Photo 2:	**View of hospital pavement downgradient from dumpster.**



PHOTOGRAPHS



Photo 3:	**Creek Outfall at Burnham Avenue.**
Photo 4:	**View of creek at Burnham Avenue.**

PHOTOGRAPHS



Photo 5:	**View of creek at Rodeo Grounds.**
Photo 6:	**View of creek at sample location.**



PHOTOGRAPHS



Photo 7:	**Big D dumpster.**
Photo 8:	**View of pavement downgradient from Big D dumpster.**





PHOTOGRAPHS

Photo 9:	**Pavement surface water at hospital.**
Photo 10:	**Creek surface water at rodeo grounds.**



The following Photos were provided to DANR by the City of Deadwood

Photo taken 6/6/25
Blue discoloration and floor dry used to soak up spilled blue liquid.
This is in front of the Big D Dumpster.



Photo taken 6/6/25
Blue discoloration at the Post Office



Photo taken 6/6/25
Blue discoloration at McKinnley Apartments



Photo taken 6/6/25
Blue discoloration in front of the Big D dumpster



Photo taken 6/6/25
Blue discoloration at Comfort Inn



Photo taken 6/6/25
Blue discoloration on street in town



Photo taken 6/6/25
Blue liquid remaining in Big D dumpster



Photo taken 6/6/25

Blue discoloration on street in front of Tin Lizzie



Photo taken 6/6/25
Blue discoloration on street in front of Big D



Photo taken 6/6/25

Blue discoloration in front of the Vape Shop



Photo taken 6/6/25

Blue discoloration in hospital parking lot and puddle in the lot



Photo taken 6/6/25
Blue discoloration in hospital parking lot



Photo taken 6/6/25
Blue discoloration in the Creek following a rainfall event
When AET arrived, the blue coloration was no longer visible.

