South Dakota Spill Report Form
ATP Site

Spill Case Number	2026.125		
Reported: (mm/dd/yy) 08/12/26	Time: 4:30 pm	Recorded By: Justin Allen	

A. REPORTER

Reported By: Robert Prann			
Organization Name: American Engineering Testing, Inc			
Organization: ☐ discharger ☐ public ☐ state ☐ local ☐ federal			
Address: 1745 Samco Road			
City: Rapid City	County: Pennington	State: SD	
Zip: 57702	Phone: 605-388-0029		

B. DISCHARGER (Responsible Party)

Name: Michela Olson			
Address: 1810 12th Ave			
City: Belle Fourche	County: Butte	State: SD	
Zip: 57717	Phone: 605-645-9480		

C. INCIDENT LOCATION

Street or Approx. Location: As above in B ☐			LAT. 44.645347	
Olson Property, 10969 Hwy 34			LONG. -103.857289	
Survey Description:			Sec.	T / R
City: Belle Fourche	Zip: 57717	County: Butte	State: SD	

D. DATE

Spill Date: (mm/dd/yy)	Spill Time:

E. MATERIAL

Material Type (Code/Name): ☐ hazardous substance ☐ oil ☐ material unknown ☐ other	Quantity Spilled	Spilled in Water	Units (Check 1)
Gasoline & Diesel			○ lb. ○ bbl. ○ gal. ○ oth.
			○ lb. ○ bbl. ○ gal. ○ oth.
			○ lb. ○ bbl. ○ gal. ○ oth.

F. SOURCE

Source of Spill: ☐ AST ☑ UST ☐ railway ☐ fixed facility ☐ pipeline ☐ highway ☐ other

Description: Regulated Tank: ☑ One - 560 gal gasoline UST, one - 250 gal diesel UST. Fac. ID 15-00073

G. MED.

Medium Affected: ☐ air ☑ land ☐ water ☐ groundwater ☐ within facilities only

Waterway Affected:

H. CAUSE

Reported Cause: ○ transportation accident ○ operational error ○ dumping ○ equipment failure ○ natural phenomenon ○ unknown ○ Other:

Description: Leaky UST

I. DAM.

Damages: No. of injuries: No. of deaths: Property Damage > $50,000 ☐

J. ACTIONS

Date of Tank Removal: 07/21/26

ATP # 3860 PRCF # 8817

Removed One - 560 gal gasoline UST & one - 250 gal diesel UST

K. NOTIFIED

Responding Agency: ☑ DANR ☐ Local ☐ discharger ☐ federal ☐ EPA ☐ Other

Agencies Notified:

L. COMMENTS

Comments: Facility ID # 15-00073. No contaminated soils removed.

Sample Results: One tank basin soil sample @ 12 ft below grade had a TPH-G of 16.3 ppm.

Department of Agriculture and Natural Resources
Insepction, Compliance, and Remediation Program
523 East Capitol Avenue
Pierre, South Dakota 57501

Business Hours M thru F 8:00 - 5:00 pm
Normal business hours - (605) 773-3296
After business hours - (605) 773-3231

DEPARTMENT of AGRICULTURE and NATURAL RESOURCES
JOE FOSS BUILDING
523 E CAPITOL AVE
PIERRE SD 57501-3182
danr.sd.gov

August 24, 2026

Michela Olson
1810 12th Ave
Belle Fourche, SD 57717

Re: Closure of Department of Agriculture and Natural Resources File # 2026.125 pertaining to the removal of one 560-gallon gasoline tank and one 250-gallon diesel tank at the Olson Property (ATP FID #3860), 10969 SD Hwy 34, Belle Fourche, Butte County, South Dakota, UST Facility ID #15-00073

Dear Ms. Olson,

The Department of Agriculture and Natural Resources (DANR) has reviewed the case file for your site. As a result of this review, the DANR has determined work at this site can end, and the file can be closed. Petroleum hydrocarbon concentrations were detected while removing the tank system, but concentrations did not exceed DANR Tier I Action/Trigger Levels; therefore, DANR will not perform any further testing or remediation associated with the tank system removed on July 21, 2026.

As you know, the tanks were removed from this site as part of South Dakota's Abandoned Tank Program. If problems arise from contamination associated with the tanks that may not have been detected, please contact us so that further action may be taken. Should you have any questions or concerns, please contact Justin Allen of my staff. Thank you for your cooperation in protecting the groundwater resources of South Dakota.

Sincerely,

Terry Florentz, P.E.
Inspection, Compliance, & Remediation Program
Phone: (605) 773-3296

cc: Fred Lamphere, Butte County Emergency Manager, Belle Fourche, SD
John McVey, Petroleum Release Compensation Fund – PRCF #8804
Robert Prann, American Engineering Testing, Rapid City, SD