South Dakota Spill Report Form

PRCF #: **Case #:** 2026.146

Reported (MM/DD/YY): 9/17/26	Time:	Recorded By: HK	
A. REPORTER	Reported By: Zach Burggraff		
	Organization Name: SD DANR	☐ Discharger ☐ Public ☑ State ☐ Local ☐ Federal	
	Phone:	Email:	
	Address:		
	City:	State:	Zip:
B. DISCHARGER (Responsible Party) ☐ As Above in A	Name: Circle K (Veronica Rivera)		
	Address: 1120 W Warner Rd		
	City: Tempe	State: AZ	Zip: 85284
	Phone:	Email:	
C. INCIDENT DATE & LOCATION ☐ As Above In B	Spill Date: (MM/DD/YY) 09/17/26	Spill Time: 8:30 AM	
	Street or Approx. Location: 2460 W Chicago St		
	Survey Description: 44.085076, -103.259333		
	City: Rapid City	County: Pennington	State: SD Zip: 57702

D. MATERIAL

Material type (Code/Name): ☐ Hazardous Substance ☐ Oil ☐ Material Unknown ☐ Other	Quantity Spilled	Spilled in Water	Units (Check one)	
Gasoline	32	unk	☐ lb. ☐ bbl.	☑ gal. ☐ oth.
			☐ lb. ☐ bbl.	☐ gal. ☐ oth.
			☐ lb. ☐ bbl.	☐ gal. ☐ oth.

E. SOURCE

Source of Spill: ☐ AST ☐ UST ☐ Railway ☑ Transport ☑ Fixed Facility ☐ Pipeline ☐ Highway ☐ Other

Description: Vehicle being refueled on a trailer

Regulated Tank Facility: ☐ Tank Facility ID #:

F. MEDIUM

Medium Affected: ☐ Air ☑ Land ☐ Water ☐ Groundwater ☐ Within Facilities Only

Waterway Affected: Storm drain

G. CAUSE

Reported Cause: ☐ Transportation Accident ☑ Operational Error ☐ Dumping ☐ Equipment Failure ☐ Natural Phenomenon ☐ Unknown ☐ Other

Description: leaked out of the bottom of a vehicle on a trailer

H. DAMAGES

# of Injuries: # of Fatalities:

I. ACTIONS

Response Action Taken:
RC Hazmat responded and placed floor dry, AET responded and placed a boom around the storm drain inlet and outlet

K. NOTIFIED

Responding Agency: ☐ DANR ☑ Local ☑ Discharger ☐ Federal ☐ EPA ☐ Other

Agencies Notified: DANR

K. COMMENTS

Comments:

Department of Agriculture and Natural Resources
Inspection, Compliance, and Remediation Program
523 East Capitol Avenue
Pierre, South Dakota 57501

Business Hours M – F 8:00-5:00 pm
Normal Business Hours- (605)773-3296
After Business Hours- (605) 773-3231

DEPARTMENT of AGRICULTURE
and NATURAL RESOURCES
JOE FOSS BUILDING
523 E CAPITOL AVE
PIERRE SD 57501-3182
danr.sd.gov

Veronica Rivera
Circle K
1120 W Warner Rd
Tempe, AZ 85284

September 18, 2026

Subject: Department of Agriculture and Natural Resources File Number 2026.146: pertaining to a gasoline release at Circle K gas station at 2460 W Chicago St, Rapid City, SD 57702.

Dear Ms. Rivera:

The Department of Agriculture and Natural Resources (DANR) is contacting you regarding the event noted above. A copy of the initial spill report form is enclosed for your review. Based upon the information provided, approximately 32 gallons of gasoline were released due to a fuel pump operator error. Some of the released gasoline entered a nearby storm drain. The Rapid City Fire Department responded and applied floor dry to the impacted pavement and storm drain. American Engineering & Testing mobilized to place absorbent booms around the storm drain inlet and outfall to prevent further migration of petroleum contamination. In this instance, DANR requires the following (some of these steps may have already occurred):

- Hire an environmental consultant certified in petroleum remediation to assess the impacted storm drain inlet(s). DANR will determine if additional remedial efforts are required;
- Properly dispose of contaminated absorbents at a permitted municipal solid waste landfill;
- Provide this office with a copy of your consultant's report including disposal receipts and cleanup pictures;
- By October 18, 2026, please complete and return the enclosed Written Contamination Incident Follow Up Report form (this is a standard form so you can skip the questions that do not apply to your situation).

Hanna Kollbaum has been assigned as the project manager for this case. She will review the information provided and will contact you if further remedial action is necessary. If you have questions or need additional information, please do not hesitate to contact her at (605) 773-3296. Thank you for your cooperation and assistance.

Sincerely,

Marshall Braun. FOR.

Jaclyn McGuire
Inspection, Compliance, & Remediation Program
(605) 773-3296

cc Dustin Willett, Pennington County EM

INCIDENT FOLLOW-UP REPORT

DANR CASE FILE #: 2026.146

RETURN COMPLETED FORM TO:

SOUTH DAKOTA DEPARTMENT OF AGRICULTURE AND NATURAL RESOURCES (DANR)
INSPECTION, COMPLIANCE, AND REMEDIATION PROGRAM
JOE FOSS BUILDING
523 EAST CAPITOL AVENUE
PIERRE SD 57501-3182

NAME/TYPE OF PRODUCT SPILLED: Unleaded gasoline

TOTAL AMOUNT OF PRODUCT SPILLED: 32.671 gallons

POUNDS OF ACTIVE INGREDIENT SPILLED (fertilizer/pesticide spills): _____

AMOUNT OF PRODUCT RECOVERED: _____

WAS SURFACE WATER OR GROUND WATER IMPACTED BY THE SPILL?: No

SPILL DATE: 9/17/2026 DATE CLEANUP OCCURRED: 9/17/2026 & 9/18/2026

SPILL LOCATION (physical address, directions, distance to nearest intersection or landmark, etc.): _____
2460 W. Chicago St. Rapid City, SD 57702

LATITUDE/LONGITUDE: _____

LAND USE (Residential, Commercial, Agricultural, Industrial, Other – describe): Commercial

RESPONSIBLE PARTY: Circle K Stores Inc.

MAILING ADDRESS: 1130 W. Warner Rd

CITY/STATE: Tempe, AZ TELEPHONE NUMBER: 602-728-6507

PROPERTY OWNER: _____

MAILING ADDRESS: _____

CITY/STATE: _____ TELEPHONE NUMBER: _____

CONSULTANT / CLEANUP CONTRACTOR (if applicable): ERTS

MAILING ADDRESS 11231 Phillips Industrial Blvd. E, Bldg. 1, Suite 300

CITY/STATE: Jacksonville, FL TELEPHONE NUMBER: 800-924-6804

INSURANCE PROVIDER (if applicable): State Guarantee

NAME OF INSURED: _____

POLICY NUMBER: _____ CLAIM NUMBER: _____

MAILING ADDRESS: _____

CITY/STATE: _____ TELEPHONE NUMBER: _____

INCIDENT FOLLOW-UP REPORT (Page 2 of 2)

DANR CASE FILE #: _____

WAS SOIL EXCAVATED?: No DIMENSIONS OF EXCAVATION: _____

CUBIC YARDS EXCAVATED: _____

DISPOSAL SITE (Name of Facility): _____

DISPOSAL DATE: _____ ***If soil was disposed, attach copies of disposal receipts***

FERTILIZER/PESTICIDE SPILLS ONLY

WAS CONTAMINATED SOIL/MATERIAL LAND APPLIED?: _____

APPLICATION DATE _____ ***Requires DANR Pre-Approval***

WAS SPILL CONTAINED TO IMMEDIATE AREA?: Yes

DISTANCE TO AND NAME OF NEAREST SURFACE WATER (include currently dry perennial streams): _____

DISTANCE TO NEAREST WATER WELL (if applicable): _____

OWNER OF NEAREST WATER WELL (if applicable): _____

DESCRIBE RESPONSE ACTION AND ADDITIONAL WORK PLANNED: _____

9/17/2026 The fire department was called, and they cleaned up the spill including the drain. Floor dry was left on the affected areas. ERTS (Spill Hotline) Authorized Baranko Bros. to respond 9/18/2026 09:18 ET, at 13:00 ET.
9/18/2026 1330 ET ERTS contractor, Steve Landman, site supervisor-Baranko (ph. 425-359-3600) called with site update: - all site activities completed. - contractor applied degreaser and granular absorbents on stained-impacted asphalt area, brushed in, collected and containerized absorbents in a 55-gallon steel drum, and will transport offsite for disposal. - will containerize the 7 bags of granular absorbents (not sand) in a 55-gallon steel drum and will transport offsite for disposal. - inspected the storm drain catch basin and reported no visual or olfactory indication of gasoline. - Store manager approved of the contractor's work. - photos to follow

FORM COMPLETED BY: Veronica Rivera DATE: 9/22/2026

E-MAIL ADDRESS: vrivera1@circlek.com, NT-ESS@circlek.com

Original – DANR
Copy – Keep for your records.

Outlook

Re: [EXT] SD DANR Case #2026.146 - gasoline release

From 2746512 Store Mailbox <2746512@circlek.com>
Date Fri 10/2/2026 6:53 AM
To Rivera, Veronica <vrivera1@circlek.com>; Kollbaum, Hanna <Hanna.Kollbaum@state.sd.us>
Cc dustin.willett@penncosd.gov <dustin.willett@penncosd.gov>; Wetmore, Ezrie <ezrie.wetmore@circlek.com>; Northern Tier Environmental <NT-ESS@circlek.com>

Yes, it was.

Christian Mooney
Circle K 2746512
2460 W. Chicago St.
Rapid City, SD, 57702

From: Rivera, Veronica <vrivera1@circlek.com>
Sent: Thursday, October 1, 2026 4:36 PM
To: Kollbaum, Hanna <Hanna.Kollbaum@state.sd.us>; 2746512 Store Mailbox <2746512@circlek.com>
Cc: dustin.willett@penncosd.gov <dustin.willett@penncosd.gov>; Wetmore, Ezrie <ezrie.wetmore@circlek.com>; Northern Tier Environmental <NT-ESS@circlek.com>
Subject: RE: SD DANR Case #2026.146 - gasoline release

Store manager,
Can you please confirm that all the booms have been removed from your site. Please check the storm sewer outlet.

Thank you,
Veronica Rivera
Environmental Compliance Supervisor, Northern Tier & Midwest Division
North American Environmental

O: (602) 728-6507
C: (602) 403-3554
e: vrivera1@circlek.com & NT-ESS@circlek.com & MW-ESS@circlek.com

Circle K Stores Inc.
1120 W. Warner Rd
Tempe, AZ 85284

Part of Alimentation Couche-Tard

CONFIDENTIALITY NOTE: This e-mail message, including any attachment(s), contains information that may be confidential, protected by the attorney-client or other legal privileges, and/or proprietary non-public information. If you are not an intended recipient of this message or an authorized assistant to an intended recipient, please notify the sender by replying to this message so that we can correct our records to avoid the mistake in the future and then delete it from your system. Use, dissemination, distribution, or reproduction of this message and/or any of its attachments (if any) by unintended recipients is not authorized and may be unlawful. Your cooperation with this request is appreciated.

From: Kollbaum, Hanna <Hanna.Kollbaum@state.sd.us>
Sent: Thursday, October 1, 2026 2:59 PM
To: Rivera, Veronica <vrivera1@circlek.com>
Cc: dustin.willett@penncosd.gov; Wetmore, Ezrie <ezrie.wetmore@circlek.com>; Northern Tier Environmental <NT-ESS@circlek.com>
Subject: Re: SD DANR Case #2026.146 - gasoline release

CAUTION: This email originated from outside Circle K. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hi Veronica,

I was told a boom was placed at the storm sewer outlet. Was that boom also recovered?

Best,


Hanna Kollbaum, Environmental Scientist I
SD Department of Agriculture and Natural Resources
Inspection, Compliance, and Remediation Program
Office: 605-773-3296 | 24-Hour Spill Reporting: 605.773.3231
Spills Reporting Info Statewide Spills Database


Photos provided by cleanup contractor on 9/22/26.











Material ID ERT
Generator: Circle K - Rapid
Address:
Collection Date: 7-18-24
Job#: 02-26-0547
Material: Gasoline Impacted
Note: Floor Dry


Material ID ERT
Generator: Circle K - Rapid
Address:
Collection Date: 9-18-24
Job#: 02-26-0547
Material: Absorbants, gas impacted
Note: floor dry


DIESEL
DIESEL
DIESEL


CIRCLE K
DIESEL
DIESEL





Photos taken by DANR staff on 9/17/26. These photos show the release after Rapid City HAZMAT response.








TRUCK DIESEL
4.29
6.29
COLD BEER
CAR WASH
HAUL

Photos provided by AET on 9/17/2026. Photos show a boom placed around the storm drain inlet.






DUMP NO WASTE
DRAINS TO RIVER

Photo shows the contaminated floor dry in bags.



Photo shows the boom placed at the storm drain outlet.



