# South Dakota Spill Report Form

**PRCF #:** **Case #:** 2026.148

| | | |
|---|---|---|
| Reported (MM/DD/YY): 9/21/26 | Time: 11:40 PM | Recorded By: J. McGuire |

**A. REPORTER**

| | | | |
|---|---|---|---|
| Reported By: Mike Kulish | | | |
| Organization Name: M.G. Oil Co. | | ☑ Discharger ☐ Public ☐ State ☐ Local ☐ Federal | |
| Phone: 605-431-5063 | | Email: mkulish@mgoil.com | |
| Address: PO Box 1006 | | | |
| City: Rapid City | State: SD | Zip: 57703 | |

**B. DISCHARGER** (Responsible Party) ☒ As Above in A

| | | | |
|---|---|---|---|
| Name: C/o Dave Kulish | | | |
| Address: | | | |
| City: | State: | Zip: | |
| Phone: | Email: | | |

**C. INCIDENT DATE & LOCATION** ☐ As Above In B

| | | | |
|---|---|---|---|
| Spill Date: (MM/DD/YY) 9/18/26 | Spill Time: | | |
| Street or Approx. Location: 12998 SD Highway 34 | | | |
| Survey Description: 44.416907, -103.449166 | | | |
| City: Sturgis | County: Meade | State: SD | Zip: 57785 |

**D. MATERIAL**

Material type (Code/Name): ☑ Hazardous Substance ☐ Oil ☐ Material Unknown ☐ Other

| | Quantity Spilled | Spilled in Water | Units (Check one) |
|---|---|---|---|
| Diesel #2 - total released | 1400 | | ☐ lb. ☐ bbl. ☑ gal. ☐ oth. |
| Diesel #2 - outside containment | 126 | | ☐ lb. ☐ bbl. ☑ gal. ☐ oth. |
| | | | ☐ lb. ☐ bbl. ☐ gal. ☐ oth. |

**E. SOURCE**

Source of Spill: ☑ AST ☐ UST ☐ Railway ☐ Transport ☐ Fixed Facility ☐ Pipeline ☐ Highway ☐ Other

Description: bulk AST

Regulated Tank Facility: ☑ Tank Facility ID #: 4900052

**F. MEDIUM**

Medium Affected: ☐ Air ☑ Land ☐ Water ☐ Groundwater ☐ Within Facilities Only

Waterway Affected: n/a

**G. CAUSE**

Reported Cause: ☐ Transportation Accident ☑ Operational Error ☐ Dumping ☐ Equipment Failure ☐ Natural Phenomenon ☐ Unknown ☐ Other

Description: Overfill - wrong AST filled

**H. DAMAGES**

| | |
|---|---|
| # of Injuries: n/a | # of Fatalities: n/a |

**I. ACTIONS**

Response Action Taken:

Hired AET. Pumped out product from within the secondary containment.

**K. NOTIFIED**

Responding Agency: ☐ DANR ☐ Local ☑ Discharger ☐ Federal ☐ EPA ☐ Other

Agencies Notified: DANR

**K. COMMENTS**

Comments:

Plan to scrape up any contaminated soil.

**Department of Agriculture and Natural Resources**
**Inspection, Compliance, and Remediation Program**
**523 East Capitol Avenue**
**Pierre, South Dakota 57501**

**Business Hours M – F 8:00-5:00 pm**
**Normal Business Hours- (605)773-3296**
**After Business Hours- (605) 773-3231**

**DEPARTMENT of AGRICULTURE and NATURAL RESOURCES**
JOE FOSS BUILDING
523 E CAPITOL AVE
PIERRE SD 57501-3182
danr.sd.gov

Dave Kulish
M.G. Oil Co.
P.O. Box 1006
Rapid City, SD 57703

September 21, 2026

Subject: Department of Agriculture and Natural Resources File Number 2026.148: pertaining to a diesel release at the Kickstart Travel Center AST facility, DANR Tank ID 4900052, 12998 SD Highway 34, Sturgis, South Dakota.

Dear Mr. Kulish:

The Department of Agriculture and Natural Resources (DANR) is contacting you regarding the event noted above. A copy of the initial spill report form is enclosed for your review. Based upon the information provided, approximately 1,400 gallons of diesel were released due to an aboveground storage tank (AST) overfill. It is estimated that 126 gallons of diesel escaped the secondary containment system. In this situation, DANR requires the following (DANR is aware some of the following actions have already occurred):

- Retain an environmental consultant to pump up and properly manage spilled diesel. Your consultant must be certified to perform petroleum release remediation in South Dakota.
- Apply absorbents and remove any contaminated soil. Properly dispose at a permitted municipal solid waste landfill;
- Collect soil samples post excavation to confirm cleanup;
- Provide this office with a copy of your consultant's report including analytical results and disposal receipts; and
- By October 21, 2026, please complete and return the enclosed Written Contamination Incident Follow Up Report form (this is a standard form so you can skip the questions that do not apply to your situation).

Please properly manage future stormwater contamination within containment. Any water with an oil sheen cannot be discharged. Lance Clark has been assigned as the project manager for this case. He will review all information provided and will contact you if additional remedial action is required. If you have any questions or need additional information, please do not hesitate to contact him at 605.773.3749. Thank you for your cooperation and assistance.

Sincerely,

Jaclyn McGuire
Inspection, Compliance, & Remediation Program
(605) 773-3296

cc Sean Henderson, Meade County Emergency Manager
Brad Bishop, AET Inc.
William Lippold, Kickstart Travel Center, P.O. Box 309 Sturgis, SD 57785