


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location SE 1/4 SE 1/4 Sec 23 Twp 96N Rg 56W

Well Owner:

County
YANKTONName MUNKVOLD LAND & CATTLEAddress 43723 294th ST.Please mark well
location with
an "X"MENNO, SDPlugging completion Date 4/14/10

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐Well depth 34 1/2 FT.Casing material CONCRETECasing size(s) 15"Casing condition OLD

Hole depth _____

Hole size _____

RECEIVED
MAY 05 2010
WATER RIGHTS
PROGRAM

Describe plugging procedure: FILLED WITH SAND FROM 34 1/2 FT.
TO 10 FT. BELOW GRADE. PUT IN BENTONITE LAYER
TO 6 FT., THEN NATIVE MATERIAL TO TOP.
REMOVED TOP CURBING.

Describe grout or plugging material: BENTONITE POWDER

Type of non-slip plug: _____

This well or test hole was plugged under license # 21 And this report is true and accurate.

Drilling firm KORANDA WELL COMPANY LLC

Signature of Licensed Representative James P. Koranda

Signature of Well Owner John R. Munkvold Pres.

Date 4-29-10

5-10-10