


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02

Location SW 1/4 SE 1/4 Sec 29 Twp 6S Rg 7E

Well Owner:

County CusterPlease mark well
location with an "X"*Buffalo Gap SD*
57722Name: CP RailAddress: 501 Marquette Avenue South #1525City, State, Zip: Minneapolis MN 55402

Comments:

CP Rail - Richard JohnstonPlugging Completion Date July 20, 2010

CHECK APPROPRIATE BOX

EXISTING WELL ☐TEST HOLE ☒

Well depth _____

Casing material _____

Casing size(s) _____

Casing condition _____

Hole depth 8 boring 11 to 27 feetHole size 2"MacroCoresampler

Describe plugging procedure:

tremi Pumped High Solids bentonite Grout to bottom of drilled boring/temp monitoring well.

B-1 19.25' WL 13.5, B-2 24' WL 5', B-3 27' WL 23', B-4 23' WL 14.5', B-5 WL 20.5', B-6 WL 15', B-7 WL 7', B-8 11' WL 8'.

Soils brown silty sand, silty clay & sand & gravel, variable.

Describe grout or plugging material:

Wyo-Ben High Solids Bentonite Grout

RECEIVED

JAN 13 2011

WATER RIGHTS
PROGRAMType of non-slip plug: noneThis well or test hole was plugged under license # 615 and this report is true and accurate.Drilling firm: AECOMSignature of Licensed Representative: *[Signature]*

Signature of Well Owner: _____

Date: 1-10-2011

1-18-11




Fig. 3-10 Canadian Pacific\Buffalo Gap\Titer 1 report\Fig 3 - boring locations.dwg Layout: AWSL-BI-CP User: campbell Plotted: Dec 29, 2010 - 1:08pm kref's

AECOM

RECEIVED

JAN 13 2011

WATER RIGHTS