


SOUTH DAKOTA WATER WELL COMPLETION REPORT

07-92

Location NE 1/4 SW 1/4 Sec 5 Twp 42N Rg 24WCounty Mellott

Please mark well location with an "X"

Well Completion Date 7-14-95

LOCATION:

Distance from nearest potential pollution source (septic tank, abandoned well, feed lot, etc.)? _____ ft. from _____ (identify source).

PROPOSED USE:

☒ Domestic/Stock ☒ Municipal ☐ Business ☐ Test Holes
☐ Irrigation ☐ Industrial ☐ Institutional ☐ Monitoring well

METHOD OF DRILLING:

Bored

CASING DATA:

☐ Steel ☐ Plastic ☐ OtherIf other describe 24 in Cement tile

PIPEWEIGHT	DIAMETER	FROM	TO	HOLE DIAMETER
_____ LB/FT	_____ IN	_____ FT	_____ FT	_____ IN
_____ LB/FT	_____ IN	_____ FT	_____ FT	_____ IN
_____ LB/FT	_____ IN	_____ FT	_____ FT	_____ IN

GROUTING DATA

Grout Type	No. of Sacks	Grout Weight	From	To
_____	_____	_____ lb./gal	_____ ft	_____ ft
_____	_____	_____ lb./gal	_____ ft	_____ ft

Describe grouting procedure CementSCREEN: ☐ Perforated pipe ☐ Manufactured

Diameter _____ IN Length _____ FEET

Material _____

Slot Size _____ Set From _____ Feet to _____ Feet

Other information _____

WAS A PACKER OR SEAL USED? ☐ YES ☐ NO

If so, what material? _____

Describe packer(s) and location? _____

DISINFECTION:

Was well disinfected upon completion? _____ YES, How: _____

_____ NO, Why Not? _____

Laboratory sent to for water quality analysis _____

Well Owner: Harold P. Thompson

Business Name: _____

Address: PO # 253
White River, SD 57579

WELL LOG:


DEPTH

FORMATION

FROM

TO

27# top soil
22" sand + gravel
26" blue shale
50 ft. well

STATIC WATER LEVEL _____ 30 Feet

If flowing: closed in pressure _____ PSI

GPM flow _____ through _____ inch pipe

Controlled by ☐ Valve ☐ Reducers ☐ Other _____

Reduced Flowrate _____ GPM

Can well be completely shut in? _____

WELL TEST DATA:

☐ Pumped Describe: _____☐ Bailed _____☐ Other _____

Pumping Level Below Land Surface

_____ ft. After _____ Hrs. pumped _____ GPM

_____ ft. After _____ Hrs. pumped _____ GPM

If pump installed, pump rate _____ GPM

REMARKS

This well was drilled under license # 318

And this report is true and accurate.

Drilling firm Summers Drilling

Signature of License Representative: _____

Signature of Well Owner or Equitable Property Holder:

Harold P. ThompsonDate: 7-14-95