

SOUTH DAKOTA WELL REHABILITATION REPORT


10-85

Location 1/4 Sec 3 Twp 64 Rg 123

County

Brown

Please mark well location with an "X"



Rehabilitation Completion Date July 20th 92

PROPOSED USE:

- ☐ Domestic ☐ Municipal ☐ Stock
☐ Irrigation ☐ Industrial

Well Owner:

Name

E. Valerie Rochow

Address

724 - E. 12th Ave. Aberdeen, S.D.

Describe original construction if possible?

(Attach original log if known)

- 1- bored well plug - 32' Dia. steel
1- bored well plug Cement casing
1- bored well plug Cement casing

Description of condition of well before rehabilitation:

- 1- 28' - 32" - steel casing good condition water head 15'
1- 24' - 18" Cement Casing good - water head 15'
1- 24' - 24" Cement Casing good - water head 15.6"

used 70 yds sand wash - 17 bags Benorites

Description of rehabilitation work completed:

6-yds Clay & Black dirty test 3' at site

Ken - Please send me plugging reports


Thanks for information - phone & letter

Recasing information: Material _____ Diameter _____ Inches Depth _____ Feet

Describe screen or perforations _____ Screen Location From _____ To _____

From _____ To _____

Grout: ☐ YES ☐ NO Describe grouting procedure and grout _____



Well Test Data:

Specific capacity _____ Static water level _____

If a flowing well GPM _____ Shut in _____ PSI

This well rehabilitation was completed under license # 92 And this report is true and accurate.

Drilling firm Academy Well Drilling

Signature of Licensed Representative _____

Signature of Well Owner

E. Valerie Rochow

Date

July 21 1992