


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location SW 1/4 SW 1/4 Sec 4 Twp 116N Rg 57WCounty Clark

Please mark well location with an "X"



Well Owner:

Name Greg OverbyAddress Box 258Clark, S.D. 57225Plugging completion Date 8-8-95

CHECK APPROPRIATE BOX

EXISTING WELL

☒ MW 1, MW 2 + MW 5

TEST HOLE


Well depth 28', 25' + 23'Casing material PVC, Sch. 40, 2Casing size(s) 2"Casing condition Good

Hole depth _____

Hole size _____

Describe plugging procedure: Place Tremix pipe at bottom of wells and pump grout into wells.Describe grout or plugging material: 94 lb. bag Portland Cement to 6 gals. Water.

Type of non-slip plug: _____

This well or test hole was plugged under license # 78 And this report is true and accurate.Drilling firm Gem Star AssociatesSignature of Licensed Representative Mark Jensen License # 647Signature of Well Owner Gregory Overby managerDate 8-30-95