



SOUTH DAKOTA WELL REHABILITATION REPORT



Location $\frac{1}{4}$ $\frac{1}{4}$ Sec 18 Twp 122 Rg 55 W

County Day

Please mark well location with an "X"



Rehabilitation Completion Date _____

PROPOSED USE:

- ☒ Domestic ☐ Municipal ☐ Stock
☐ Irrigation ☐ Industrial

Well Owner:

Name Alan Siebmiller

Address Webster, S.D.

Describe original construction if possible?
(Attach original log if known)

2 ft black dirt 2 ft
rock and gravel and
16 sand clay 7 water
gravel back to sand
clay 24 ft

Description of condition of well before rehabilitation:

it pumped 6 GPM
ready mix concrete and sand pack

Description of rehabilitation work completed:

Recasing information: Material pvc Diameter 12 Inches Depth 24 Feet

Describe screen or perforations none Screen Location From 0 To 6
From _____ To _____

Grout: ☒ YES ☐ NO Describe grouting procedure and grout water

Well Test Data:

Specific capacity 5 GPM Static water level 6 ft

If a flowing well GPM _____ Shut in _____ PSI

This well rehabilitation was completed under license # _____ And this report is true and accurate.

Drilling firm _____

Signature of Licensed Representative O'Farrell well Drilling

Signature of Well Owner James O'Farrell

Date 1-24-89