


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location W 1/4 NW 1/4 Sec 9 Twp 48N Rg 98W

Well Owner:

County

HutchinsonPlease mark well
location with
an "X"

Name

Merlin Baltzer

Address

Rt. 1 Parkston, S.D. 57366

Plugging completion

Date

June 9, 1992

CHECK APPROPRIATE BOX

EXISTING WELL

☐

TEST HOLE

☒

Well depth

Casing material

Casing size(s)

Casing condition

Hole depth

Hole size

95 ft4 1/2 inches

Describe plugging procedure: Test hole was filled to about 30 ft. from the top with cuttings and cement for about the next 25 ft.

Describe grout or plugging material: Grout was pumped down the test hole, the top few feet were filled with native soil.

Type of non-slip plug:

Cement

This well or test hole was plugged under license #

302

And this report is true and accurate.

Drilling firm

Lehr Well Drilling

Signature of Licensed Representative

Victor Lehr

Signature of Well Owner

Merlin O Baltzer

Date

7-3-92