


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-35

Location S 24 E 1/4 Sec 25 Twp 99 N Rg 56

County Hutchinson

Please mark well location with an "X"



Well Owner Name Norman Walters
Address At 2 Truman St
57029

Plugging completion Date 8-24-81

CHECK APPROPRIATE BOX

EXISTING WELL ☒

TEST HOLE ☐

Well depth 249
Casing material Steel
Casing size(s) 3
Casing condition plugged at bottom

Hole depth _____
Hole size _____

Describe plugging procedure: tronic pipe

Describe grout or plugging material: portland cement

Type of non-slip plug: Homelite steel & rubber


This well or test hole was plugged under license # 123 And this report is true and accurate.

Drilling firm Prime Drilling
Signature of Licensed Representative Philip R...
Signature of Well Owner Norman Walters
Date 9-1-81



SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location 1/4 Sec 25 Twp 99 Rg 56County HutchinsonPlease mark well
location with
an "X"

Well Owner:

Name Norman W. WhitmanAddress At 2 Stinson S.D.
57029Plugging completion Date 8-24-88

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐Well depth 249Casing material steelCasing size(s) 3Casing condition plugged at bottom

Hole depth _____

Hole size _____

Describe plugging procedure: drum pipeDescribe grout or plugging material: portland cementType of non-slip plug: Homemade steel & rubberThis well or test hole was plugged under license # 123 And this report is true and accurate.Drilling firm Bois D'ArcySignature of Licensed Representative Bois D'ArcySignature of Well Owner Norman W. WhitmanDate 9-1-88