

me

Static water level 7' below land surface
If flowing: closed in pressure PSI

If flowing: closed in pressure PSI

☐ Negative ☐ Realized ☐ Other
If other; specify _____

/// Pumped

☒ Bailed

Describe:

☐ Other

Pumping Level Below Land Surface

ft. After	Hrs. pumped	GPM
10	1	100
10	2	100
10	3	100
10	4	100
10	5	100
10	6	100
10	7	100
10	8	100
10	9	100
10	10	100
10	11	100
10	12	100
10	13	100
10	14	100
10	15	100
10	16	100
10	17	100
10	18	100
10	19	100
10	20	100
10	21	100
10	22	100
10	23	100
10	24	100
10	25	100
10	26	100
10	27	100
10	28	100
10	29	100
10	30	100
10	31	100
10	32	100
10	33	100
10	34	100
10	35	100
10	36	100
10	37	100
10	38	100
10	39	100
10	40	100
10	41	100
10	42	100
10	43	100
10	44	100
10	45	100
10	46	100
10	47	100
10	48	100
10	49	100
10	50	100
10	51	100
10	52	100
10	53	100
10	54	100
10	55	100
10	56	100
10	57	100
10	58	100
10	59	100
10	60	100
10	61	100
10	62	100
10	63	100
10	64	100
10	65	100
10	66	100
10	67	100
10	68	100
10	69	100
10	70	100
10	71	100
10	72	100
10	73	100
10	74	100
10	75	100
10	76	100
10	77	100
10	78	100
10	79	100
10	80	100
10	81	100
10	82	100
10	83	100
10	84	100
10	85	100
10	86	100
10	87	100
10	88	100
10	89	100
10	90	100
10	91	100
10	92	100
10	93	100
10	94	100
10	95	100
10	96	100
10	97	100
10	98	100
10	99	100
10	100	100

Depth

Formation

From

To

Amber	0	1
-------	---	---

Left Beam	1'	3'
-----------	----	----

Spikes with black		
-------------------	--	--

Protein Abundance	5'	125'
-------------------	----	------

--	--	--

[illegible][illegible][illegible]

--	--	--

--	--	--

[illegible]

(Use Back if Necessary)

(Use Back if Necessary)

Date Completed:

Driller:

Driller's or Firm's Name

License NO

2. 25th - 10th

Address Box 154, Hill City, Dak

Address

David R. Boyd

Signed By _____

Date _____

Remarks:

Bottom 20' perforated
with 1/2 in.