

SOUTH DAKOTA WATER WELL COMPLETION REPORT


2497-3

07-92

Location 1/4 Sec 12 Twp 117N Rg 53W

County Codington

Please mark well location with an "X"



Well Completion Date

1-28-2000

LOCATION:

Distance from nearest potential pollution source (septic tank, abandoned well, feed lot, etc.)? None ft. from (identify source).

PROPOSED USE:

- ☐ Domestic/Stock ☐ Municipal ☐ Business ☐ Test Holes
☒ Irrigation ☐ Industrial ☐ Institutional ☐ Monitoring well

METHOD OF DRILLING:

CASING DATA: ☐ Steel ☐ Plastic ☒ Other

If other describe Fiber GLASS

PIPEWEIGHT DONT KNOW LB/FT DIAMETER 12 IN FROM 0 FT TO 28 FT HOLE DIAMETER 19 IN
 _____ LB/FT _____ IN _____ FT _____ FT _____ IN
 _____ LB/FT _____ IN _____ FT _____ FT _____ IN

GROUTING DATA

Grout Type CEMENT No. of Sacks DONT KNOW Grout Weight 0 lb./gal From 0 ft To 6 ft
 _____ lb./gal _____ ft _____ ft

Describe grouting procedure Ready Mix Truck
DUMP IN FROM TRUCK MOTOR
PUMP PIPES

SCREEN: ☐ Perforated pipe ☒ Manufactured

Diameter 12 IN Length 20 FEET

Material Fiber Glas

Slot Size 60 Set From 28 Feet to 48 Feet

Other information SPUN SCREEN-LIKE

JOHNSON STAINLESS

WAS A PACKER OR SEAL USED? ☐ YES ☒ NO

If so, what material?

Describe packer(s) and location?

DISINFECTION: Was well disinfected upon completion?

YES, How:

X NO, Why Not?

Laboratory sent to for water quality analysis

WASNT NECESSARY

Well Owner: HARLAN STADHEIM

Business Name: Irrigation & Well Drilling

Address: 2525 Stadheim Dr.
Watertown, SD 57201-7517

WELL LOG:

FORMATION	DEPTH	
	FROM	TO
<u>HARD CLAY</u>	<u>0</u>	<u>31</u>
<u>GRAVEL + ROCK</u>	<u>31</u>	<u>37</u>
<u>CLAY</u>	<u>37</u>	<u>43</u>
<u>GRAVEL</u>	<u>43</u>	<u>48</u>

STATIC WATER LEVEL 7 Feet

If flowing: closed in pressure _____ PSI

GPM flow _____ through _____ inch pipe

Controlled by ☐ Valve ☐ Reducers ☐ Other _____

Reduced Flowrate _____ GPM

Can well be completely shut in? _____

WELL TEST DATA:

☒ Pumped Describe: Air

☐ Bailed _____

☐ Other _____

Pumping Level Below Land Surface

_____ ft. After 50 Hrs. pumped Air GPM

_____ ft. After _____ Hrs. pumped _____ GPM

If pump installed, pump rate 600 GPM

REMARKS

This is Replacing
well put in 1976
Steel Screen, Got Hole in

This well was drilled under license # H14

And this report is true and accurate.

Drilling firm Stadheim

Irrigation & Well Drilling

Signature of Licensed Representative _____

Harlan Stadheim

Signature of Well Owner or Equitable Property Holder:

Date: 1-28-01

