


SOUTH DAKOTA WELL REHABILITATION REPORT

10-85

Location AAA 1/4 Sec. 7 Twp 12 S Rg 6 E

County

BrownPlease mark well
location with
an "X"Rehabilitation Completion Date May 24-92

PROPOSED USE:

- ☐ Domestic ☐ Municipal ☐ Stock
☐ Irrigation ☐ Industrial

Well Owner:

Name Lurel SmithAddress 1502 - N Dakota St.

Describe original construction if possible?

(Attach original log if known)

The log. info. 1" copperDown 10" with cement between casing & pipe. 2" casingPlaced 3" of pipe aboveWell estimate depth 1100'

Description of condition of well before rehabilitation: Top 3' Well with cement support
Replaced broken 1" ridge copper joint with compression
coupler. Well flows good for irrigating lawn only.

Description of rehabilitation work completed: _____

Recasing information: Material _____ Diameter _____ Inches Depth _____ Feet

Describe screen or perforations _____ Screen Location From _____ To _____


From _____ To _____

Grout: ☐ YES ☐ NO Describe grouting procedure and grout _____

Well Test Data:

Specific capacity _____ Static water level _____

If a flowing well GPM _____ Shut in _____ PSI

This well rehabilitation was completed under license # 724 And this report is true and accurate.Drilling firm Loftis DrillingSignature of Licensed Representative Alan H. DierckSignature of Well Owner Lurel SmithDate 6-11-92