


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location SE 1/4 SE 1/4 Sec 23 Twp 127N Rg 58WCounty MarshallPlease mark well
location with
an "X"

Well Owner:

Name Britton Public SchoolAddress 759 5th Str.Britton, S.D. 57430Plugging completion Date 5-11-06

CHECK APPROPRIATE BOX

EXISTING WELL ☒ Monitor WellsTEST HOLE ☐Well depth 20'-25'Casing material Schedule 40 PVCCasing size(s) 2"Casing condition Good

Hole depth _____

Hole size _____

Describe plugging procedure: Remove protective covers, cut casings below ground level 2' and grout wells.Describe grout or plugging material: Cement

Type of non-slip plug: _____

This well or test hole was plugged under license # 647 And this report is true and accurate.Drilling firm Geon Star Inc.Signature of Licensed Representative [Signature]Signature of Well Owner [Signature]Date 5-15-06

RECEIVED
MAY 23 2006
WATER RIGHTS
PROGRAM

1-25-06