


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec Twp RgCounty
MinnehahaPlease mark well
location with
an "X"

Well Owner:

Magellan Midstream Partners

Name

5301 West 12th Street

Address

Sioux Falls, SD 57106

Plugging completion

Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL



ASV94-7

TEST HOLE



Well depth

8.5

Casing material

PVC

Casing size(s)

4"

Casing condition

Good

Hole depth

Hole size

RECEIVED

JUL 21 2006

WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe Method

Describe grout or plugging material:

3/8" Pure Gold Bentonite Chips

Type of non-slip plug:

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear Company

Signature of Licensed Representative

Signature of Well Owner

Date

5/23/2006

7-22-06


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec 14 Twp 101N Rg 50W

County Minnehaha

Please mark well location with an "X"



Well Owner: Magellan Midstream Partners
 Name 5301 West 12th Street
 Address Sioux Falls, SD 57106

Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL



ASV94-6

TEST HOLE



Well depth 12.5
 Casing material PVC
 Casing size(s) 4"
 Casing condition Good

Hole depth _____
 Hole size _____

Describe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.

Drilling firm Boart Longyear Company

Signature of Licensed Representative [Signature]


Signature of Well Owner [Signature]

Date 5/23/2006

7-24-06

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec 14 Twp 101N Rg 50WCounty MinnehahaPlease mark well
location with
an "X"

Well Owner:

Magellan Midstream Partners

Name

5301 West 12th Street

Address

Sioux Falls, SD 57106

5/23/2006

Plugging completion

Date

CHECK APPROPRIATE BOX

EXISTING WELL



ASV94-5

TEST HOLE



Well depth

15

Casing material

PVC

Casing size(s)

4"

Casing condition

Good

Hole depth

Hole size

Describe plugging procedure:

Tremie Pipe Method

Describe grout or plugging material:

3/8" Pure Gold Bentonite Chips

Type of non-slip plug:

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear Company

Signature of Licensed Representative


Signature of Well Owner

Date

5/23/2006

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
Twp RgCounty MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL



ASV94-7C

TEST HOLE

Well depth 15.5Casing material PVCCasing size(s) 2"Casing condition Good

Hole depth _____

Hole size _____

RECEIVED

JUL 21 2006

WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: _____


3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear CompanySignature of Licensed Representative [Signature]Signature of Well Owner [Signature]Date 5/23/2006

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec 14 Twp 101N Rg 50WCounty MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006


CHECK APPROPRIATE BOX

EXISTING WELL ☒ ASV94-7BTEST HOLE ☐Well depth 15.5Casing material PVCCasing size(s) 2"Casing condition GoodHole depth Hole size Describe plugging procedure: Tremie Pipe MethodDescribe grout or plugging material: 3/8" Pure Gold Bentonite ChipsType of non-slip plug: This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear CompanySignature of Licensed Representative [Signature]Signature of Well Owner [Signature]Date 5/23/2006

7-24-06

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec Twp RgCounty MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL



ASV94-7A

TEST HOLE



Well depth 13.5

Casing material PVC

Casing size(s) 2"

Casing condition Good

Hole depth _____

Hole size _____

RECEIVED**JUL 21 2006****WATER RIGHTS
PROGRAM**Describe plugging procedure: Tremie Pipe MethodDescribe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear CompanySignature of Licensed Representative [Signature]Signature of Well Owner [Signature]Date 5/23/2006


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec 14 Twp 101N Rg 50W

County Minnehaha

Please mark well location with an "X"



Well Owner: Magellan Midstream Partners
 Name 5301 West 12th Street
 Address Sioux Falls, SD 57106
 Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ ASV94-6C Well depth <u>16.5</u> Casing material <u>PVC</u> Casing size(s) <u>2"</u> Casing condition <u>Good</u>	TEST HOLE ☐ Hole depth _____ Hole size _____
--	---

Describe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.

Drilling firm Boart Longyear Company

Signature of Licensed Representative [Signature]


Signature of Well Owner [Signature]

Date 5/23/2006

7-24-06

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 Sec 101N Twp 50W RgCounty
MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ ASV94-6BTEST HOLE ☐Well depth 16.5Casing material PVCCasing size(s) 2"Casing condition Good

Hole depth _____

Hole size _____

RECEIVED
JUL 21 2006
WATER RIGHTS
PROGRAM


Describe plugging procedure: Tremie Pipe MethodDescribe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear CompanySignature of Licensed Representative [Signature]Signature of Well Owner [Signature]Date 5/23/2006

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec Twp RgCounty MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL



ASV94-6A

TEST HOLE

Well depth 16.5
Casing material PVC
Casing size(s) 2"
Casing condition GoodHole depth _____
Hole size _____**RECEIVED**
JUL 21 2006
WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe MethodDescribe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear CompanySignature of Licensed Representative [Signature]Signature of Well Owner Alan [Signature]Date 5/23/2006


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
 Twp Rg

County
Minnehaha

Please mark well
 location with
 an "X"



Well Owner: Magellan Midstream Partners
 Name 5301 West 12th Street
 Address Sioux Falls, SD 57106

Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ ASV94-5C

TEST HOLE ☐

Well depth 21
 Casing material PVC
 Casing size(s) 2"
 Casing condition Good

Hole depth _____
 Hole size _____

RECEIVED
JUL 21 2006
 WATER RIGHTS
 PROGRAM

Describe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.

Drilling firm Boart Longyear Company

Signature of Licensed Representative [Signature]

Signature of Well Owner [Signature]

Date 5/23/2006


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec Twp Rg

County Minnehaha

Please mark well location with an "X"



Well Owner: Magellan Midstream Partners
 Name 5301 West 12th Street
 Address Sioux Falls, SD 57106
 Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ ASV94-5B

TEST HOLE ☐

Well depth 21
 Casing material PVC
 Casing size(s) 2"
 Casing condition Good

Hole depth _____
 Hole size _____

RECEIVED
JUN 21 2006
 WATER RIGHTS
 PROGRAM

Describe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.

Drilling firm Boart Longyear Company

Signature of Licensed Representative [Signature]

Signature of Well Owner [Signature]

Date 5/23/2006


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec 14 Twp 101N Rg 50W

County Minnehaha

Please mark well location with an "X"



Well Owner: Magellan Midstream Partners
 Name 5301 West 12th Street
 Address Sioux Falls, SD 57106
 Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ ASV94-5A Well depth <u>21</u> Casing material <u>PVC</u> Casing size(s) <u>2"</u> Casing condition <u>Good</u>	TEST HOLE ☐ Hole depth _____ Hole size _____
--	---

RECEIVED
JUL 21 2006
 WATER RIGHTS PROGRAM

Describe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.

Drilling firm Boart Longyear Company

Signature of Licensed Representative [Signature]


Signature of Well Owner [Signature]

Date 5/23/2006

7-2001-06

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
Location 1/4 1/4 Sec 14 Twp 101N Rg 50WCounty MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ AS94-2TEST HOLE ☐Well depth 14Casing material PVCCasing size(s) 2"Casing condition Good

Hole depth _____

Hole size _____

RECEIVED

JUL 21 2006

WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: _____

3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear CompanySignature of Licensed Representative [Signature]Signature of Well Owner [Signature]Date 5/23/2006


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec Twp Rg

County Minnehaha

Please mark well location with an "X"



Well Owner: Magellan Midstream Partners
 Name 5301 West 12th Street
 Address Sioux Falls, SD 57106
 Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ AS94-1 Well depth <u>12.5</u> Casing material <u>PVC</u> Casing size(s) <u>2"</u> Casing condition <u>Good</u>	TEST HOLE ☐ Hole depth _____ Hole size _____ RECEIVED JUL 21 2006 WATER RIGHTS PROGRAM
--	--

Describe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.

Drilling firm Boart Longyear Company

Signature of Licensed Representative [Signature]


Signature of Well Owner [Signature]

Date 5/23/2006

7-3-06

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec Twp Rg County MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006


CHECK APPROPRIATE BOX

EXISTING WELL



SVE95-20

TEST HOLE

Well depth 15
Casing material PVC
Casing size(s) 4"
Casing condition GoodHole depth
Hole size **RECEIVED**
JUL 21 2006
WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe MethodDescribe grout or plugging material: 3/8" Pure Gold Bentonite ChipsType of non-slip plug: This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear CompanySignature of Licensed Representative Signature of Well Owner Date 5/23/2006Date

10-85

Well Owner: **Magellan Midstream Partners**

Name _____ 5301 West 12th Street

Address Sioux Falls, SD 57106

Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL

☒

SVE95-19

TEST HOLE

7

15

Well depth

PVC

Casing material

4"

Casing size(s)

Good

Casing condition

Hole depth _____

Hole size _____

RECEIVED

21 2006

WATER RIGHTS PROGRAM

Describe plugging procedure: _____ Tremie Pipe Method

Describe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug:

This well or test hole was plugged under license # 424. And this report is true and accurate.

Drilling firm

Signature of Licensed Representative


Signature of Well Owner

5/23/2006

Date _____

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
Sec Twp RgCounty MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL



SVE95-18

TEST HOLE



Well depth

15

Casing material

PVC

Casing size(s)

4"

Casing condition

Good

Hole depth

Hole size

RECEIVED

JUN 21 2006

WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe Method

Describe grout or plugging material:

3/8" Pure Gold Bentonite Chips

Type of non-slip plug:

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear Company

Signature of Licensed Representative

Signature of Well Owner


Date

5/23/2006

7021146

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec Twp RgCounty
MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ SVE95-17TEST HOLE ☐Well depth 15Casing material PVCCasing size(s) 4"Casing condition Good

Hole depth _____

Hole size _____

RECEIVED
JUL 21 2006
WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe MethodDescribe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear CompanySignature of Licensed Representative [Signature]Signature of Well Owner [Signature]Date 5/23/2006


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec 14 Twp 101N Rg 50W

County Minnehaha

Please mark well location with an "X"



Well Owner: Magellan Midstream Partners

Name 5301 West 12th Street

Address Sioux Falls, SD 57106

Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ SVE95-16

TEST HOLE ☐

Well depth 16
 Casing material PVC
 Casing size(s) 4"
 Casing condition Good

Hole depth _____
 Hole size _____

RECEIVED
JUL 21 2006
 WATER RIGHTS
 PROGRAM

Describe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.

Drilling firm Boart Longyear Company


Signature of Licensed Representative [Signature]

Signature of Well Owner [Signature]

Date 5/23/2006

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
Twp RgCounty
MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ SVE95-15TEST HOLE ☐Well depth 17Casing material PVCCasing size(s) 4"Casing condition Good

Hole depth _____

Hole size _____

RECEIVED

JUL 21 2006

WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: _____


3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear CompanySignature of Licensed Representative [Signature]Signature of Well Owner Alan [Signature]Date 5/23/2006

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
County MinnehahaPlease mark well
location with
an "X"

Well Owner:

Magellan Midstream Partners

Name

5301 West 12th Street

Address

Sioux Falls, SD 57106

Plugging completion

Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL



SVE95-14

TEST HOLE



Well depth

17

Casing material

PVC

Casing size(s)

4"

Casing condition

Good

Hole depth

Hole size

RECEIVED
JUN 21 2006
WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe Method

Describe grout or plugging material:

3/8" Pure Gold Bentonite Chips

Type of non-slip plug:

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear Company

Signature of Licensed Representative


Signature of Well Owner

Date

5/23/2006

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50WCounty
MinnehahaPlease mark well
location with
an "X"

Well Owner:

Magellan Midstream Partners

Name

5301 West 12th Street

Address

Sioux Falls, SD 57106

Plugging completion Date

5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL



SVE95-12

TEST HOLE

Well depth 18Casing material PVCCasing size(s) 4"Casing condition Good

Hole depth _____

Hole size _____

RECEIVED

JUL 21 2006

WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: _____

3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear Company

Signature of Licensed Representative

Signature of Well Owner

Date

5/23/2006


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
 Location 1/4 1/4 Sec 14 Twp 101N Rg 50W

County Minnehaha

Please mark well location with an "X"



Well Owner: Magellan Midstream Partners
 Name 5301 West 12th Street
 Address Sioux Falls, SD 57106
 Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ SVE95-10

TEST HOLE ☐

Well depth 18
 Casing material PVC
 Casing size(s) 4"
 Casing condition Good

Hole depth _____
 Hole size _____

RECEIVED
JUN 21 2006
 WATER RIGHTS
 PROGRAM

Describe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.

Drilling firm Boart Longyear Company

Signature of Licensed Representative [Signature]


Signature of Well Owner [Signature]

Date 5/23/2006

5/23/06

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 Sec 101N Twp 50W RgCounty MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ SVE95-8TEST HOLE ☐Well depth 19Casing material PVCCasing size(s) 4"Casing condition Good

Hole depth _____

Hole size _____

RECEIVED
JUL 21 2006
WATER RIGHTS
PROGRAM


Describe plugging procedure: Tremie Pipe MethodDescribe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear CompanySignature of Licensed Representative [Signature]Signature of Well Owner Alan JhDate 5/23/2006

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
Twp RgCounty
MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ SVE94-7TEST HOLE ☐Well depth 22.3Casing material PVCCasing size(s) 4"Casing condition Good

Hole depth _____

Hole size _____

RECEIVED

MAY 21 2006


WELL RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe MethodDescribe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear CompanySignature of Licensed Representative [Signature]Signature of Well Owner [Signature]Date 5/23/2006

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
Twp RgCounty
MinnehahaPlease mark well
location with
an "X"

Well Owner:

Magellan Midstream Partners

Name

5301 West 12th Street

Address

Sioux Falls, SD 57106

Plugging completion

Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL



SVE94-6

TEST HOLE



Well depth

22

Casing material

PVC

Casing size(s)

4"

Casing condition

Good

Hole depth

Hole size

RECEIVED

MAY 23 2006

SOUTH DAKOTA
PLUGGING PROGRAMDescribe plugging procedure: Tremie Pipe Method

Describe grout or plugging material:

3/8" Pure Gold Bentonite Chips

Type of non-slip plug:

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear Company

Signature of Licensed Representative


Signature of Well Owner

Date

5/23/2006

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
Twp RgCounty
MinnehahaPlease mark well
location with
an "X"

Well Owner:

Magellan Midstream Partners

Name

5301 West 12th Street

Address

Sioux Falls, SD 57106

Plugging completion

Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL



SVE94-4

TEST HOLE



Well depth

12

Casing material

PVC

Casing size(s)

4"

Casing condition

Good

Hole depth

Hole size

RECEIVED

JUL 2 2006

WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe Method

Describe grout or plugging material:

3/8" Pure Gold Bentonite Chips

Type of non-slip plug:

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear Company

Signature of Licensed Representative


Signature of Well Owner

Date

5/23/2006

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
Location 1/4 1/4 Sec 14 Twp 101N Rg 50WCounty MinnehahaPlease mark well
location with
an "X"

Well Owner:

Magellan Midstream Partners

Name

5301 West 12th Street

Address

Sioux Falls, SD 57106

Plugging completion

Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL



SVE94-3

TEST HOLE



Well depth

14

Casing material

PVC

Casing size(s)

4"

Casing condition

Good

Hole depth

Hole size

RECEIVED

JUN 21 2006

WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe Method

Describe grout or plugging material:

3/8" Pure Gold Bentonite Chips

Type of non-slip plug:

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear Company

Signature of Licensed Representative


Signature of Well Owner

Date

5/23/2006

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
Twp RgCounty
MinnehahaPlease mark well
location with
an "X"Well Owner: Magellan Midstream PartnersName 5301 West 12th StreetAddress Sioux Falls, SD 57106Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ SVE94-2TEST HOLE ☐Well depth 14Casing material PVCCasing size(s) 4"Casing condition Good

Hole depth _____

Hole size _____

RECEIVED

JUN 21 2006

WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: _____

3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear CompanySignature of Licensed Representative [Signature]Signature of Well Owner Alan [Signature]Date 5/23/2006


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 101N 50W
1/4 1/4 Sec Twp Rg

County Minnehaha

Please mark well location with an "X"



Well Owner: Magellan Midstream Partners
 Name 5301 West 12th Street
 Address Sioux Falls, SD 57106
 Plugging completion Date 5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL ☒ SVE94-1 Well depth <u>16</u> Casing material <u>PVC</u> Casing size(s) <u>4"</u> Casing condition <u>Good</u>	TEST HOLE ☐ Hole depth _____ Hole size _____
---	---

RECEIVED
 JUN 21 2006
 WATER RIGHTS PROGRAM

Describe plugging procedure: Tremie Pipe Method

Describe grout or plugging material: 3/8" Pure Gold Bentonite Chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 424 And this report is true and accurate.

Drilling firm Boart Longyear Company

Signature of Licensed Representative [Signature]


Signature of Well Owner Alan [Signature]

Date 5/23/2006

70 100 200 300 400 500 600 700 800 900 1000

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location S SE 14 Sec 101N Twp 50W RgCounty
MinnehahaPlease mark well
location with
an "X"

Well Owner:

Magellan Midstream Partners

Name

5301 West 12th Street

Address

Sioux Falls, SD 57106

Plugging completion Date

5/23/2006

CHECK APPROPRIATE BOX

EXISTING WELL



RW-5

TEST HOLE



Well depth

33

Casing material

Steel

Casing size(s)

10"

Casing condition

Good

Hole depth

Hole size

RECEIVED

JUN 21 2006

WATER RIGHTS
PROGRAMDescribe plugging procedure: Tremie Pipe Method

Describe grout or plugging material:

3/8" Pure Gold Bentonite Chips

Type of non-slip plug:

This well or test hole was plugged under license # 424 And this report is true and accurate.Drilling firm Boart Longyear Company

Signature of Licensed Representative

Signature of Well Owner

Date

5/23/2006



Alan P. Johns
Project Manager – Remediation

One Williams Center
Mail Drop 30-7
Tulsa, OK 74172

Voice: (918) 574-7383
Fax: (918) 574-7540
Email: alan.johns@magellanlp.com

July 17, 2006

Water Rights Program
South Dakota Department of Environment and Natural Resources (DENR)
523 East Capitol
Pierre, South Dakota 57501-3181

Water Rights Program:

Enclosed please find completed South Dakota Well and Test Hole Plugging Reports associated with the DENR-approved dismantling of the remediation system at Magellan Pipeline Company, L.P. (Magellan)'s Terminal located at 5301 West 12th Street, Sioux Falls, SD.

Please don't hesitate to call with any questions or comments.

Sincerely,

A handwritten signature in black ink, appearing to read "Alan Johns", with a long horizontal line extending to the right.

Alan Johns
Project Manager – Remediation

Attachment

RECEIVED
JUL 21 2006
WATER RIGHTS
PROGRAM