


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location SE 1/4 SE 1/4 Sec 6 Twp 1 Rg 8County PenningtonPlease mark well
location with
an "X"1220 E St. Patrick St

Well Owner:

Name Atlantic Richfield (AR) c/o Delta ConsultantsAddress 5910 Rice Creek Parkway
Suite 100
Shoreview, MN 55126Plugging completion Date 9/27/07

CHECK APPROPRIATE BOX

EXISTING WELL

☒ EW1, EW2

TEST HOLE



Well depth

25, 25

Casing material

PVC

Casing size(s)

2"

Casing condition

Good

Hole depth

Hole size

RECEIVED

OCT 25 2007

WATER RIGHTS
PROGRAM

Describe plugging procedure:

Tremie from bottom → up

Describe grout or plugging material:

Bentonite Grout Slurry

Type of non-slip plug:

This well or test hole was plugged under license #

597

And this report is true and accurate.

Drilling firm

Bergerson - Coswell, Inc

Signature of Licensed Representative

John W. Hennrich

Signature of Well Owner

(Agent for AR)

Date

10.16.07

10-25-07