SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location SE ¼ SE ¼ Sec 16 Twp 1 Rg 8

County Pennington

Please mark well location with an "X"

ROW Riley Ave
N of St. Patrick St.



Well Owner:

Name Atlantic Richfield (BP) c/o Delta Consultants

Address 5910 Rice Creek Parkway
Suite 100
Shoreview, MN 55126

Plugging completion Date 9/27/07

CHECK APPROPRIATE BOX

EXISTING WELL ☒ MW44

Well depth 20

Casing material PVC

Casing size(s) 2"

Casing condition Good

TEST HOLE ☐

Hole depth

Hole size

RECEIVED
OCT 25 2007
WATER RIGHTS PROGRAM

Describe plugging procedure: Tremie from bottom → up

Describe grout or plugging material: Bentonite Grout Slurry

Type of non-slip plug:

This well or test hole was plugged under license # 597 And this report is true and accurate.

Drilling firm Bergerson-Caswell, Inc.

Signature of Licensed Representative John W. Hamm

Signature of Well Owner (Agent for BP)

Date 10-16-07

10-24-07