


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location SW 1/4 SW 1/4 Sec 10 Twp 110N Rg 50WCounty Brookings

Please mark well location with an "X"

See ATTACHED
Logs

Well Owner:

Name Le Roy VossAddress 141 S. MainBrookings, S.D. 57006Plugging completion Date 8-30-07

CHECK APPROPRIATE BOX

EXISTING WELL ☐TEST HOLE ☒

Well depth _____

Casing material _____

Casing size(s) _____

Casing condition _____

Hole depth _____

Hole size _____

See ATTACHED
LogsDescribe plugging procedure: Backfilled w/ Clay, Cuttings
& Sand

Describe grout or plugging material: _____

RECEIVED

FEB 4 2008

WATER RIGHTS
PROGRAM

Type of non-slip plug: _____

This well or test hole was plugged under license # 4 And this report is true and accurate.Drilling firm Bullis BrosSignature of Licensed Representative Le Roy BullisSignature of Well Owner Le Roy VossDate 8-30-07

2-12-08

BULLIS BROTHERS

LeRoy Bullis
1201 Karen Street
886-4044

Well Boring
Trenching
Water and Sewer System
1201 Karen Street
Watertown, South Dakota 57201

Duane Bullis
1120 North Broadway
886-6746

Drilling Log

Date 8-30 19 07

Name LeRoy Voss
Address 141 S Main
City & State Brookings, S.D. 57006
County Brookings

SW 1/4 SW 1/4 Sec 10 Twp 110N Rg 50W

Test Hole # 1

Formation	From	To
Top Soil	0	1
yellow Grzuel	1	4
yellow Clay Firm	4	15
yellow + Blue Clay	15	31
Blue Clay (Hard)	31	51
Dirty Grzuelly Clay	51	61
yellow, Red + Black		
Course Sand +		
Grzuel w/ Clay	61	69
Blue Clay (Firm)	69	90
yellow Clay (Firm)	90	115
Blue Clay (Firm)	115	170
Set casing + screen		
Through 61' to 69'		
2 rez. Grzuel no		
water. Pulled casing		
License # 4 LeRoy Bullis		

Casing		
Length	Diam.	Type
Screen		
Length	Diam.	Slot & Type
Completed depth _____		
Comments <u>Pulled</u>		
<u>Casing. Back</u>		
<u>filled w/ clay,</u>		
<u>Cuttings +</u>		
<u>sand</u>		

2-12-08

BULLIS BROTHERS

LeRoy Bullis
1201 Karen Street
886-4044

**Well Boring
Trenching
Water and Sewer System**
1201 Karen Street
Watertown, South Dakota 57201

Duane Bullis
1120 North Broadway
886-6746

Drilling Log

Date 8.30 1907

Name LeRoy Voss

Address 141 S. Main

City & State Brookings S.D. 57006

County Brookings

SW $\frac{1}{4}$ SW $\frac{1}{4}$ Sec 10 Twp 110N Rg 50W

Test Hole # 2

Formation	From	To
Top Soil	0	2 1/2
Course yellow Gravel	2 1/2	4 1/2
Firm yellow Clay	4 1/2	14
Dark Clay Firm	14	23
yellow Clay Hard	23	34
Blue Clay Hard	34	60
Dry Hole		
Backfilled w/ Clay, cuttings + sand		
License # 4		
Se Dog Bull		

x	

Casing		
Length	Diam.	Type

Screen		
Length	Diam.	Slot & Type

Completed depth _____

Comments _____

80-21-6