


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02

Location SE 1/4 SW 1/4 Sec 9 Twp 2N Rg 9E

County Meade

Please mark well location with an "X"



Plugging Completion Date 11-15-11

Well Owner:

Name: U.S Air Force

Address: 25
2103 Scott St

City, State, Zip: Ellsworth S.D. 57706

Comments:

Abandoned 1 2" well MW972404

CHECK APPROPRIATE BOX

EXISTING WELL ☒

TEST HOLE ☐

Well depth 21'

Casing material PVC

Casing size(s) 2"

Casing condition Good

Hole depth _____

Hole size _____

Describe plugging procedure:

Tremied from bottom of well with grout to @ 3' b.g. Filled 3' to grade with soil or concrete

Describe grout or plugging material:

B H 20 high solid grout

Type of non-slip plug: _____

This well or test hole was plugged under license # 797 and this report is true and accurate.

Drilling firm: O'Malley Drilling Inc.

Signature of Licensed Representative: Michael O'Malley

Signature of Well Owner: Jerald C. Styles

Date: 20 Jan 12

FILE: T:\ellsworth\16169962\12033\Abandoned Wells\Figure 02-10.dgn
DATE: 11/28/2011 TIME: 9:20:16 AM BY: daniel_galde
MODEL: 2-10

