


OFF BASE - 4

SD EForm - 1622LD V1

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02Location SE 1/4 SE 1/4 Sec 9 Twp 2N Rg 9E

Well Owner:

County MeadePlease mark well
location with an "X"Plugging Completion Date 11-14-11Name: U.S Air ForceAddress: 25
2103 Scott StCity, State, Zip: Ellsworth S.D. 57706

Comments:

Abandoned 1 2" well MW972407**CHECK APPROPRIATE BOX**EXISTING WELL ☒TEST HOLE ☐Well depth 21'Casing material PVCCasing size(s) 2"Casing condition Good

Hole depth _____

Hole size _____

Describe plugging procedure:

Tremied from bottom of well with grout to @ 3' b.g. Filled 3' to grade with soil or concrete

Describe grout or plugging material:

B H 20 high solid grout

Type of non-slip plug: _____

This well or test hole was plugged under license # 797 and this report is true and accurate.Drilling firm: O'Malley Drilling Inc.Signature of Licensed Representative: Michael O'MalleySignature of Well Owner: Donald EdgleyDate: 20 Jan 12

FILE: T:\ellsworth\16169962\12033\Abandoned Wells\Figure 02-10.dgn
DATE: 11/28/2011 TIME: 9:20:16 AM BY: daniel_galde
MODEL: 2-10

