


OFF BASE
#7

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02

Location SE ¼ SE ¼ Sec 15 Twp 2N Rg 9E

County Pennington

Please mark well
location with an "X"



Plugging Completion Date 11-14-11

Well Owner:

Name: U.S Air Force

Address: 25
2103 Scott St

City, State, Zip: Ellsworth S.D. 57706

Comments:

Abandoned 6-2" wells MW002418 MW002424
MW002419 MW002420 MW002421 MW002425

CHECK APPROPRIATE BOX

EXISTING WELL ☒	TEST HOLE ☐
Well depth <u>9'-25'</u>	Hole depth _____
Casing material <u>PVC</u>	Hole size _____
Casing size(s) <u>2"</u>	
Casing condition <u>Good</u>	

Describe plugging procedure:

Tremied from bottom of well with grout to @ 3' b.g. Filled 3' to grade with soil or concrete

Describe grout or plugging material:

B H 20 high solid grout

Type of non-slip plug: _____

This well or test hole was plugged under license # 797 and this report is true and accurate.

Drilling firm: O'Malley Drilling Inc.

Signature of Licensed Representative: Michael O'Malley

Signature of Well Owner: Jerald E. Hylton

Date: 20 Jan 12

FILE: T:\ellsworth\16169962\Abandoned Wells\Figure 02-10.dgn
DATE: 11/28/2011 TIME: 9:20:16 AM BY: daniel_galde
MODEL: 2-10

