


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location Lot 8-9 1/4 Sec 10 Twp 5-N Rg 5-E
County McPherson S. Add
Meade

Please mark well
location with
an "X"



Well Owner:

Name Caldwell Banker Realtors
Address 2131 Baldwin St.

Sturgis S.D. 57785

Plugging completion Date 5-15-14

CHECK APPROPRIATE BOX

EXISTING WELL



TEST HOLE



Well depth

30'

Casing material

Cement Tile

Casing size(s)

20"

Casing condition

Good

Hole depth

Hole size

RECEIVED

DEC 16 2014

WATER RIGHTS
PROGRAM

Describe plugging procedure:

Filled with clean rock to static level @ 16'. Placed 26 bags 3/8" Bentonite chips approx. 2 1/2'. Removed top 3' of casing & tamped in clay soil to surface

Describe grout or plugging material:

16' of one inch clean rock
2 1/2' of 3/8 Bentonite chips
13 1/2' of clay soil

Type of non-slip plug:

This well or test hole was plugged under license #

568

And this report is true and accurate.

Drilling firm

Camarillo Drilling Inc.

Signature of Licensed Representative

Michael J. Deitch

Signature of Well Owner

Steve Ehlert

Date

5-15-14