


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location SW 1/4 SE 1/4 Sec 29 Twp 002S Rg 09E

County

CusterPlease mark well
location with
an "X"13.840037
-103.198299
KB per email

Well Owner:

Name CP RailroadAddress C/O Acon 800 LaSalle Ave
Suite 500 Minneapolis MN 55402E Well location hermosaPlugging completion Date 11-3-2015

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐Well depth 13' feetCasing material brick, mortarCasing size(s) 3 feetCasing condition poor, delapidated

Hole depth _____

Hole size _____

RECEIVED

JAN 27 2016

WATER RIGHTS
PROGRAMDescribe plugging procedure: excavate well, fill with sand to water level. Then add
bentonite, Then add concrete. finish leveling with local materialDescribe grout or plugging material: bags of sand, bag of bentonite chips, Trucked
in 3yds concreteType of non-slip plug: concreteThis well or test hole was plugged under license # 694 And this report is true and accurate.Drilling firm Antler enterprisesSignature of Licensed Representative [Signature]

Signature of Well Owner _____

Date _____