


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location NW 1/4 NE 1/4 Sec 26 Twp 7N R. 3E
KB per LAT/LON

County

LawrencePlease mark well
location with
an "X"

Well Owner:

Name C.P. RailroadAddress c/o Alcom 800 LaSalle Ave. Suite 500
Minneapolis, Minn 55402Well location Stouge, SDPlugging completion Date 11-3-2015LAT 44.546502
LON -103.721592

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐Well depth 12 FeetCasing material BrickCasing size(s) 3 FeetCasing condition delapitatedHole depth 12 FeetHole size 3 Feet diameter

RECEIVED

JAN 27 2016

WATER RIGHTS
PROGRAMDescribe plugging procedure: excavated well, placed approx 1-2 feet bentonite
chips, 3 yds cement, 2 feet fill, excavated and destroyed top 6' of well
(well was filled with sand, before bentonite was added)
to top of waterDescribe grout or plugging material: 9 bentonite chips, Trucked in cementType of non-slip plug: CementThis well or test hole was plugged under license # 694 And this report is true and accurate.Drilling firm Autler EnterprisesSignature of Licensed Representative [Signature]

Signature of Well Owner _____

Date 12-3-2015