


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location SE 1/4 SW 1/4 Sec 11 Twp 100N Rg 62W

County

DouglasPlease mark well
location with
an "X"

Well Owner:

Name Mr. Danilo GeidelAddress 4042 26th StDemock 5057331Plugging completion Date Aug 16

CHECK APPROPRIATE BOX

EXISTING WELL



TEST HOLE



Well depth

270

Casing material

Steel

Casing size(s)

2"

Casing condition

Good

Hole depth

Hole size

Describe plugging procedure:

Trim my pipe

Describe grout or plugging material:

Bentons Grout with cement on top

Type of non-slip plug:

Bentons

This well or test hole was plugged under license #

42

And this report is true and accurate.

Drilling firm

Goetz Drilling Co

Signature of Licensed Representative

[Signature]

Signature of Well Owner

[Signature]

Date

Oct 15 2018

RECEIVED

JAN 11 2019

WATER RIGHTS
PROGRAM