


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02Location nw ¼ nw ¼ Sec 23 Twp 106 Rg 48

Well Owner:

County MoodyPlease mark well
location with an "X"Name: Jesse AndersonAddress: 23526 482nd Ave.City, State, Zip: Flandreau SD 57028

Comments:

43.9750 Lat
96.5638 LongPlugging Completion Date 7-25-18**CHECK APPROPRIATE BOX**EXISTING WELL ☒TEST HOLE ☐Well depth 37'6"Casing material concrete culvertCasing size(s) 26"Casing condition good

Hole depth _____

Hole size _____

Describe plugging procedure:

Filled the well with pea rock to the static water level then 2' of Bentonite chips then fill dirt.

Describe grout or plugging material:

Medium Bentonite chips

Type of non-slip plug: _____

This well or test hole was plugged under license # 796 and this report is true and accurate.Drilling firm: T & J Redder Well and Electric, Inc.Signature of Licensed Representative: *Thomas J. Redder*Signature of Well Owner: *Jesse Anderson*

Date: _____

RECEIVED
JAN 31 2019
 WATER RIGHTS
 PROGRAM