


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location SW 1/4 SW 1/4 Sec 6 Twp 109 Rg 76County StanleyPlease mark well
location with
an "X"

Well Owner:

Name Lower Brule Range UnitAddress + NRCS

Plugging completion

Date 10-12-18

CHECK APPROPRIATE BOX

EXISTING WELL



TEST HOLE



Well depth

56

Casing material

Steel

Casing size(s)

8"

Casing condition

Poor

Hole depth

Hole size

Describe plugging procedure:

Pressure thru tremie

Describe grout or plugging material:

Portland Cement Grout

Type of non-slip plug:

This well or test hole was plugged under license #

213

And this report is true and accurate.

Drilling firm

Hertmacher Drilling Inc

Signature of Licensed Representative

[Signature]

Signature of Well Owner

Date

10-14-18

RECEIVED

AUG 01 2019

WATER RIGHTS
PROGRAM