


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location NE 1/4 NE 1/4 Sec 13 Twp 99N Rg 56WCounty
HUTCHINSONPlease mark well
location with
an "X"

Well Owner:

Name DERRICK WALTER
Address 43979 HWY 44
MARION S.D. 57043Plugging completion Date 10-9-20

CHECK APPROPRIATE BOX

EXISTING WELL



TEST HOLE



Well depth

213'

Casing material

2 IN PIPE

Casing size(s)

3"

Casing condition

FAIR

Hole depth

Hole size

Describe plugging procedure:

PULLED Pump RAN TREMIE LINE
TO BOTTOM WELL PRESSURE Pumped D.F
GROUT TO FILL Well PULLED LINE
& FILLED TOP 10' WITH PORTLAND CEMENT

Describe grout or plugging material:

D.F. GROUT

RECEIVED

NOV 02 2020

WATER RIGHTS
PROGRAM

Type of non-slip plug:

NONE

This well or test hole was plugged under license #

515

And this report is true and accurate.

Drilling firm

MARION

Signature of Licensed Representative

Signature of Well Owner

Date

10-28-20