


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02

Location SE 1/4 SE 1/4 Sec 32 Twp 107N Rg 67W Well OwnerCounty Sheridan

Please mark well location with an "X"



Name

Spring Valley Colony

Address

25064 365th AveCity, State, Zip Westington Springs SD 57382

Comments

Filled MW 3 at hog barn sitePlugging Completion Date 7/29/2022

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐

Well depth

35'

Hole depth

Casing material

PVC

Hole size

Casing size(s)

2"

Casing condition

Good

Describe plugging procedure

Protective cover and casing was removed. Hole was then filled with bentonite and the top was concreted.

Describe grout or plugging material

Bentonite & Concrete

Type of non-slip plug

This well or test hole was plugged under license # 599 and this report is true and accurateDrilling firm: Dakota Environmental

Signature of Licensed Representative

Signature of Well Owner

Date

7/29/2022

RECEIVED

AUG 11 2022

OFFICE OF
WATER