


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location NE SE 1/4 Sec 35 Twp 99N Rg 56WCounty HOTCHINSONPlease mark well
location with
an "X"

Well Owner:

Name FREEMAN REGIONAL HEALTHAddress 510 E. 8TH STREETFREEMAN S.D. 57029

Plugging completion

Date Aug 11-22

CHECK APPROPRIATE BOX

EXISTING WELL



TEST HOLE



Well depth

260

Casing material

STEEL

Casing size(s)

5"

Casing condition

Good

Hole depth

Hole size

Describe plugging procedure:

RAN TREMIE LINE TO 260'
PUMPED GROUT TILL CASING WAS
FULL REMOVED PITLESS UNIT

Describe grout or plugging material:

DF

Type of non-slip plug:

This well or test hole was plugged under license #

515

And this report is true and accurate.

Drilling firm

MARION

Signature of Licensed Representative

[Signature]

Signature of Well Owner

Cheryl Walker

Date

08-15-2022

RECEIVED

AUG 18 2022

OFFICE OF
WATER