


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location NE 1/4 SE 1/4 Sec 35 Twp 99N Rg 56WCounty HUTCHINSONPlease mark well
location with
an "X"

Well Owner:

Name FREEMAN REGIONAL HEALTHAddress 510 E. 8TH ST.FREEMAN S.D 57029

Plugging completion

Date AUG. 11 - 22

CHECK APPROPRIATE BOX

EXISTING WELL



TEST HOLE



Well depth

263

Casing material

STEEL

Casing size(s)

4"

Casing condition

POOR

Hole depth

Hole size

Describe plugging procedure:

PULLED PUMP RAN TREMIE
LINE DOWN PUMPED D.F. GROUT
DOWN HOWE TAIL WERE WAS FULL
REMOVED PRESS ADAPTOR

Describe grout or plugging material:

D.F.

Type of non-slip plug:

NONE

This well or test hole was plugged under license #

515

And this report is true and accurate.

Drilling firm

MARTONWELL DRILLING

Signature of Licensed Representative

[Signature]

Signature of Well Owner

Chad Waters

Date

8-15-2022

RECEIVED

AUG 18 2022

OFFICE OF
WATER