


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02

Location 1/4 SW 1/4 Sec 34 Twp 110N Rg 51W

Well Owner:

County BrookingsPlease mark well
location with an "X"

Name:

Frido & Sonja VerPaalen

Address:

46318 214th St

City, State, Zip:

Volga SD 57071

Comments:

4 monitoring wells pluggedPlugging Completion Date 5/18/23

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐

Well depth

30'

Casing material

PVC

Casing size(s)

2"

Casing condition

Good

Hole depth

Hole size

Describe plugging procedure:

Protective cover & as much casing as possible was removed. Holes were then filled with bentonite and the top was concreted.

Describe grout or plugging material:

Bentonite & concrete

Type of non-slip plug:

This well or test hole was plugged under license # 599 and this report is true and accurate.

Drilling firm:

Dakota Environmental

Signature of Licensed Representative:

Signature of Well Owner:

Date:

5/19/23

RECEIVED

MAY 22 2023

OFFICE OF
WATER